# Investigation of condominium building collapse in Surfside, Florida: a video feature tracking approach

Xiangxiong Kong

Department of Physics and Engineering Science, Coastal Carolina University P.O. Box 261954, Conway, SC, USA 29528-6054

#### Abstract

On June 24, 2021, a 12-story condominium building (Champlain Towers South) in Surfside, Florida partially collapsed, resulting in one of the deadliest building collapses in United States history with 98 people are confirmed dead. We analyze this collapse event using a video clip that is publicly available from social media. We apply computer vision algorithms to corroborate new information from the video clip that may not be readily interpreted by human eyes. By comparing the differential features against different video frames, our method can quantify the falling structural components by intuitively showing the directions and magnitudes of their movements. We demonstrate the potential of this video processing methodology in investigations of catastrophic structural failures and hope our results would serve as the basis for further investigations of this and other structure collapse events.

## 1. Introduction

Structural engineering is critical to our society for enabling safe, efficient, and economical designs to resist the gravity load and loads caused by natural disasters. Despite significant efforts made in improving the structural design, catastrophic structural failures still occur. The most recent event in the United States is the partial collapse of the 12-story condominium building (Champlain Towers South) in Surfside, Florida on June 24, 2021 [1]. This is one of the deadliest building collapses in American history with 98 people are confirmed dead as of July 22, 2021.

To date, extensive efforts have been made in investigating the mechanisms of building collapses including the use of numerical simulations [2], experimental tests [3], and post-disaster field inspections [4]. On the other hand, inspecting *in-situ* structure collapse video clips is a more straightforward engineering approach as the video clips contain valuable information for representing the procedures of structural failures. Extracting useful information from video clips of structure collapses can provide direct knowledge of the structural failure behaviors, quantify characteristics of the structural failures, assist in identifying the failure causes, and help first responders to prioritize their efforts in rescue searches.

In this paper, we propose a novel vision-based method to evaluate the structural collapse of the condominium building in Surfside, Florida. We utilize a video clip of the building collapse that is publicly available from social media, and further apply computer vision algorithms to identify and quantify the falling structural components. The rest of the paper is structured as follows: Section 2 introduces the video acquisition and explains the principles of vision-based algorithms; Section 3 illustrates and discusses the analysis results; Section 4 concludes the study and elaborates the future work.

# 2. Materials and Methods

# 2.1 Video Acquisition

Figure 1 illustrates the procedure of video acquisition. Per ABC Chicago [5], the video was originally captured by a surveillance camera installed in an adjacent condominium building. Then the surveillance video appeared to be displayed on a playback monitor and re-filmed by a hand-held camera. This can be confirmed by observing the small movements (in both translation and scaling) in the video scene caused by the camera movement [6]. Next, the re-filmed video clip was distributed through the internet. Ultimately a copy of this re-filmed video clip was uploaded to YouTube [6] and was downloaded by the author through a third-party website YouTube Downloader (YT1s.com). This video clip was adopted as the data source for our study. After saving the MP4 format to the local drive, the video clip was found to have a resolution of 1920 pixels by 810 pixels with a frame rate of 29.97 frames/sec.



Figure 1. Video acquisition procedure where (a) *in-situ* video collection; (b) video re-filming; (c) video distribution; and (d) video adopted in this study.

#### 2.2 Video Feature Tracking

Figure 2 illustrates the procedure for video feature tracking that includes three components: 1) video frame preparation (Figure 2a to c), 2) feature detection (Figure 2d to g), and 3) feature tracking (Figure 2h to j).

Video frame preparation starts with extracting a total of 723 video frames (i.e., still images) from the video clip. Next, two adjacent video frames are selected. For illustration, the 4<sup>th</sup> and 5<sup>th</sup> frames at the beginning of the video clip are adopted. The 4<sup>th</sup> video frame is first shown in Figure 2 and is then cropped using a region of interest (ROI) (see the red box in Figure 2a). The ROI has a dimension of 581 pixels by 311 pixels and covers the Champlain Towers South (Figure 2b). The same ROI is applied to the 5<sup>th</sup> video frame and the cropped image is shown in Figure 2c.



Figure 2. Video feature tracking: (a) the original 4<sup>th</sup> video frame; (b) the cropped 4<sup>th</sup> video frame under the region of interest (ROI); (c) the 5<sup>th</sup> video frame under ROI; (d) Shi-Tomasi features of the 4<sup>th</sup> video frame under ROI; (e) blow-up view with all Shi-Tomasi features; (f) blow-up view of the 50 strongest Shi-Tomasi features; (g) image patches of the 50 strongest Shi-Tomasi features; (h) matched feature pairs between 4<sup>th</sup> and 5<sup>th</sup> video frames under ROI; (i) blow-up view 1 of matched feature pairs; and (j) blow-up view 2 of matched feature pairs. The label at the lower-left corner with yellow background indicates the number of frames from the video.

In terms of feature detection, the ROI of the 4<sup>th</sup> video frame (Figure 2b) is first converted from RGB channels into a grayscale image. Then, Shi-Tomasi features [7] (red circles in Figure 2d) are extracted in the ROI. The feature point describes a location where its adjacent area has unique intensity changes that are invariant against image translation, rotation, and scaling; hence the same feature point can be consistently found in different video frames. To better demonstrate the concept of feature point, Figure 2e shows all the Shi-Tomasi features within an area of 100 pixels by pixels under a blow-up view. Figure 2f further lists the 50 strongest Shi-Tomasi features, and their adjacent areas are plotted as small image patches (5 pixels by 5 pixels) in Figure 2g.

For feature tracking, we applied the Kanade-Lucas-Tomasi (KLT) tracker [8, 9] to the ROI of the 4<sup>th</sup> and 5<sup>th</sup> video frames. The KLT tracker obtains the information of feature points in the 4<sup>th</sup> video frame (Figure 2d) and actively scans the same ROI of the 5<sup>th</sup> video frame to match feature points with similar intensity changes. Figure 2h shows all matched feature pairs as a result of KLT tracking. Two areas are highlighted in the figure including 1) the top-left area (red box A) of the building complex where no structural movement occurs in between these two frames (Figure 2i), and 2) the mid-height of the middle section of the building complex (red box B) where movements of matched feature pairs can be found due to motions of falling structural components (Figure 2j).

## 2.3 Video Stabilization

The large movements observed in Figure 2j may contain movements of both falling structural components and the hand-held camera. Here we apply a video stabilization method to eliminate the camera movement. To this end, a geometric transformation matrix is estimated [10] using the matched feature pairs between the 4<sup>th</sup> and 5<sup>th</sup> video frames (see Figure 2h). Then, such a matrix is applied to all features in the 5<sup>th</sup> video frame to slightly adjust their image coordinates. As a result, the locations of all features in the 5<sup>th</sup> video frame can be aligned to the same coordinate system of the 4<sup>th</sup> video frame. As can be seen in Figure 3, the camera movement at the top-left corner (Figure 3d and e) is eliminated after video stabilization. For the area where structural components are falling (Figure 3f and g), the camera movement is also eliminated, leading to slightly adjusted image coordinates of features in the 5<sup>th</sup> frame (i.e., green crosses).



Figure 3. Video stabilization: (a) the building complex in the  $4^{th}$  frame; (b) the blow-up view of the topleft corner of the building; (c) the blow-up view of a window in the middle section; (d) and (f) are matched feature pairs before video frame stabilization; and (e) and (g) are matched feature pairs after video frame stabilization.

#### 2.4 Identification of the Falling Components

We treat the movements of matched feature pairs as robust indicators for identifying falling structural components. Figure 4a is the schematic diagram showing such a methodology. The feature points located in the falling components usually have large movements (see Figure 2j). In contrast, the feature points around intact areas of the building complex are subjected to much lower movements (see Figure 3d after video frame stabilization). By applying a cutoff threshold (*ts*), the feature points at intact areas can be eliminated such that the falling components can be identified. Figure 4b to f show the matched feature pairs after applying different cutoff thresholds. Applying a lower cutoff threshold could lead to more false-positive identification results (see Figure 4b); while higher cutoff thresholds can produce more reliable results (Figure 4d, e, f) but may also filter out falling components with small pixel movements. To balance the trade-off, a cutoff threshold is selected as 3.5 pixels for the rest of the video processing in Section 2.



Figure 4. (a) Methodology for identifying the falling structural components; (b) matched feature pairs (ts = 0 pixels); (c) matched feature pairs (ts = 0.5 pixels); (d) matched feature pairs (ts = 2.5 pixels); (e) matched feature pairs (ts = 3.5 pixels); and (f) matched feature pairs (ts = 4.5 pixels). The background images in b to f are taken from the 4<sup>th</sup> video frame with its image brightness adjusted for the illustration purpose.

#### 2.5 Quantifications of the Falling Components

Figure 5a to c demonstrate the method for quantifying the falling components. Briefly, matched feature pairs between the 4<sup>th</sup> and 5<sup>th</sup> video frames are replaced by arrows that start from the matched feature point in the 4<sup>th</sup> video frame and point to the matched feature point in the 5<sup>th</sup> video frame. The magnitudes of the arrows are the lengths of feature movements (Figure 5b). Because feature movements are usually very small (e.g., a few pixels), here we amplify the arrow lengths by multiplying a unified scaling factor as shown in Figure 5c, enabling a more intuitive way of viewing the result graphically. This method is applied to matched feature pairs between the 4<sup>th</sup> and 5<sup>th</sup> video frames and the results are shown in Figure 5d and e. The benefit of using arrows is two-fold: 1) they indicate the directions structural components moved; and 2) the magnitudes of arrows qualitatively represent the distances of matched feature pairs moved within a one video frame interval (i.e., the arrow magnitude indicates the velocities of the falling component).



Figure 5. (a) Two matched feature pairs between the 4<sup>th</sup> and 5<sup>th</sup> video frames; (b) the matched feature pairs are replaced by two arrows; (c) two arrows after applying a scaling factor; (d) arrows created in 4<sup>th</sup> video frame; (e) the blow-up view of the arrows. The background images in d and e are taken from the 4<sup>th</sup> video frame with its image brightness adjusted for the illustration purpose.

#### 3. Results and Discussions

We identify five building collapse instants across the video clip that depict critical moments of building collapse. For each instant, two adjacent video frames are selected for video processing using MATLAB [11]. As shown in Table 1, the corresponding timelines of selected video frames are calculated using a frame rate of 29.97 frames/sec. The selected video frames and analysis results are summarized in Figure 6.

	Video frame	Timeline	Result
Instant 1	$4^{th}$ and $5^{th}$	0.13 and 0.17 seconds	Figure 6c
Instant 2	$17^{\text{th}}$ and $18^{\text{th}}$	0.57 and 0.6 seconds	Figure 6g
Instant 3	$30^{\text{th}}$ and $31^{\text{st}}$	1 and 1.03 seconds	Figure 6k
Instant 4	$52^{nd}$ and $53^{rd}$	1.73 and 1.77 seconds	Figure 60
Instant 5	$309^{\text{th}}$ and $310^{\text{th}}$	10.3 and 10.33 seconds	Figure 6s

Table 1: Matrix for video processing

As can be found in Figure 6, the middle section of the building complex starts falling at the beginning of this video clip (see the first, second, and third columns in Figure 6). Consistently, the red arrows can pick up the falling structural components and further quantify their moving directions and magnitudes. Next, more components in the middle section fall (see the fourth column), and the camera view is partially obstructed by particulate matter made by the prior collapsing building debris. Thereafter, the right section of the building complex falls as can be seen in the last column of the figure.



Figure 6. Video processing results where Columns 1 to 5 are results for Instants 1 to 5 from the video clip. The first and second rows are the selected video frames; the third row shows the video analysis results with arrows indicting the moving directions and magnitudes of the falling structural components; the last row shows the blow-up views. The labels at the lower-left corners of the images at the first and second rows are the frame numbers from the video clip. The brightnesses of images in the third and last rows are adjusted for the purpose of illustration.

Several areas of the images in the last row in Figure 6 are highlighted by blue dotted circles. In dotted circle 1, the horizontal arrow may be caused by an incorrect KLT matching and hence shall be considered as the outlier. In dotted circles 2, 3, and 6, arrows can be found in the upward directions due to movements of particulate matter (dust and/or smoke). This can be further confirmed by inspecting the particulates in video frames (e.g., Figure 6i and q). In dotted circle 4, arrows depict the horizontal movements of the structural components. This shall be considered as the correct detection. These structural components may be initially attached to the left building section through reinforcing steel bars in the slabs, which prevents the components from moving down. In the dotted circle 5, horizontal and upward arrows can be found. This may be caused by both the horizontal movements of the structural components and the upward movement of the particulates.

Our approach has serval limitations. The major limitation is that the matched feature pairs cannot be evenly distributed across the entire falling structural components, leading to a scattered pattern of arrow distributions. This is due to the difficulty of the KLT tracker in matching the feature points from different video frames. Factors that can negatively affect the KLT matching capability include the low quality of the surveillance camera, potential video quality losses during the procedures of re-filming, distributing, and downloading, and the dark lighting condition at night. The second limitation is that our method fails if the camera view is obstructed by other objects (e.g., particulates). The use of advanced regularization methods, especially sparse ( $L_1$  or Total Variation) approaches may improve video information via the eliminations of image artifacts and will be investigated in further investigation.

The video clip adopted in this study also results in limited information. Firstly, because true timestamps are not available for this video clip, the video playback speed (i.e. video timeline) may be different than the actual event time. Secondly, the pixel resolutions and video frame rates of original *in-situ* surveillance video footage remain unknown. Lastly, the video clip likely does not capture the initiation of the collapse event (i.e., the building may start collapsing before the 1<sup>st</sup> video frame). Notice that our approach solely relies on extracting information from two adjacent frames from the existing video clip. Hence, potential losses of initial video frames would not affect the results of this study.

## 4. Conclusions and Future Work

The investigation of a structure collapse requires joint efforts from structural engineers, government agencies, law enforcement, and other stakeholders. The investigation team needs to examine every piece of evidence related to the event, among which the *in-situ* collapse video clip, if available, is one of the most essential pieces of evidence. Traditionally, the structure collapse video clip is visually inspected by human eyes (e.g., engineers or researchers [12]). In this paper, we present a novel video processing methodology to extract new information from the collapse video clip by showing the directions and magnitudes of the movements of the falling components. Our method will help the investigators to obtain direct knowledge on the behaviors and mechanisms of building collapses, which will help them in their decision-making.

In addition to MATLAB, the proposed method can be easily implemented through other computer vision platforms such as Open CV [13]. The computational time for generating results from two adjacent frames in this study is about seven seconds using a workstation with a 2.9 GHz CPU and a 32GB RAM. These flexibilities allow the proposed method to be implemented in rescue searching shortly after the building collapse. As shown in the last row of Figure 6, the proposed method can provide a factual interpretation of the sequence of the collapsing components (e.g., which building section collapses first hence shall be at the bottom of the building debris). This could help first responders to prioritize their efforts in the rescue mission after the disaster.

Recently, with the rapid commercialization and technological development of consumer-grade digital cameras, structure collapses could be filmed by a variety of means. In addition to surveillance cameras, other video collection tools may include smartphone cameras, dash cameras on passing vehicles, body cameras from onsite construction workers, and drones operated by rescue teams. Further work will focus on investigating the viability of this video processing technology in broader applications.

#### Acknowledgment

The author conveys condolences to the families affected by the building collapse and wants to thank those who collected the surveillance video footage of the building collapse, and those who shared and distributed the building collapse video clip over social media. The author also wants to thank William Ambrose and Danny Smyl for their fruitful discussions and anonymous reviewers for improving the quality of this paper.

#### Funding

The author received no financial support for the research, authorship, and/or publication of this article.

#### **Conflicts of Interest**

The author declares no conflict of interest.

#### **Data Availability Statement**

The data that support the findings of this study are openly available in the internet sources referred to in the paper.

#### References

- [1] BBC News, Miami building collapse: What happened, and how quickly? https://www.bbc.com/news/world-us-canada-57609620
- [2] Lu, X., Lin, X., Ma, Y., Li, Y., & Ye, L. (2008). Numerical simulation for the progressive collapse of concrete building due to earthquake. a a, 2, 2.
- [3] Suita, K., Yamada, S., Tada, M., Kasai, K., Matsuoka, Y., & Shimada, Y. (2008, October). Collapse experiment on 4-story steel moment frame: Part 2 detail of collapse behavior. In Proceedings of the 14th world conference on earthquake engineering, Beijing, China (Vol. 11).
- [4] Miller, D. K. (1998). Lessons learned from the Northridge earthquake. Engineering structures, 20(4-6), 249-260.
- [5] ABC Chicago, Security camera video shows moment of condo building collapse in Surfside, Florida, https://abc7chicago.com/building-collapse-video-surfside-miami-of/10827847/
- [6] Video shows moment condo tower collapsed in Surfside, Florida, north of Miami Beach, <u>https://www.youtube.com/watch?v=jtQMH8S57fw</u>
- [7] Shi, J. (1994, June). Good features to track. In 1994 Proceedings of IEEE conference on computer vision and pattern recognition (pp. 593-600). IEEE.
- [8] Lucas, B. D., & Kanade, T. (1981, April). An iterative image registration technique with an application to stereo vision.
- [9] Tomasi, C., & Kanade, T. (1991). Detection and tracking of point. Int J Comput Vis, 9, 137-154.
- [10] Torr, P. H., & Zisserman, A. (2000). MLESAC: A new robust estimator with application to estimating image geometry. Computer vision and image understanding, 78(1), 138-156.

- [11] Higham, D. J., & Higham, N. J. (2016). MATLAB guide. Society for Industrial and Applied Mathematics.
- [12] Zhou, X., Di, J., & Tu, X. (2019). Investigation of collapse of Florida International University (FIU) pedestrian bridge. Engineering Structures, 200, 109733.
- [13] Bradski, G., & Kaehler, A. (2000). OpenCV. Dr. Dobb's journal of software tools, 3.