# One-sided Shewhart control charts for monitoring the ratio of two normal variables in Short Production Runs

K.D. Tran<sup>1</sup>, Q.U.A Khaliq<sup>2</sup>, A. A. Nadi<sup>4</sup>, H Tran<sup>3</sup>, and K.P. Tran<sup>\*4</sup>

<sup>1</sup>Institute of Research and Development, Duy Tan University, Danang, 550000 Vietnam
<sup>2</sup>Department of Statistics Allama Iqbal Open University Islamabad, Pakistan
<sup>3</sup>Institute of Artificial Intelligence and Data Science, Dong A University, Danang, Vietnam
<sup>4</sup>Ecole Nationale Supérieure des Arts et Industries Textiles, GEMTEX Laboratory, BP 30329 59056 Roubaix Cedex 1, France

October 6, 2020

#### Abstract

Monitoring the ratio of two normal random variables plays an important role in several manufacturing environments. For short production runs, however, the control charts assumed infinite processes cannot function effectively to detect anomalies. In this paper, we tackle this problem by proposing two one-sided Shewhart-type charts to monitor the ratio of two normal random variables for a finite horizon production. The statistical performance of the proposed charts is investigated using the truncated average run length as a performance measure in short production runs. In order to help the quality practitioner to implement these control charts, we have provided ready-to-use tables of the control limit parameters. An illustrative example from the food industry is given for illustration.

**Keywords**: Statistical process monitoring, Ratio distribution, Short production runs, Truncated run length, Shewhart control chart.

## 1 Introduction

Quality control (QC) enables the manufacturer to produce high-quality products according to the needs of the customer. Its tool kit helps to improve product

<sup>\*</sup>kim-phuc.tran@ensait.fr (corresponding author)

quality by minimizing product cost, increase the efficiency of the process by reducing product waste. Control charts are famous tools for monitoring the assignable causes, they also tell us when corrective action must be taken or timely notify us when corrective action must be taken to improve the process behavior (see Shewhart<sup>20</sup>). With growing competition in customer markets, manufacturers extremely depend on the quality of their products and services for their survival. The short-run manufacturing production process is become quite common for achieving the satisfaction of the customers like job-shops, which are categorized by a high amount of flexibility and manufacture diversity. Therefore, the life cycle of the products is decreasing rapidly. Nowadays, the production lines in several manufacturings and engineering processes have limited. In short runs production, some sources are fixed or the time span of the product is too short, maybe one hour or day. For example, any warehouse which may be on the lease. This warehouse is operating in the short run because it has a limited place. The owner cannot extend their business or shifted it to another place. When the agreement expires, he will have in position to enlarge business or shift to a large place. The same is the case, in manufacturing industries, like robotics manufacturing industry incorporates the limited production runs of automatic parts within the flexible production cells and semiconductor industry assembly of electronic boards and in beverages industries where the high volume of production and filling of soft drinks in every 24 to 48 hour required the 20 to 30 inspection between consecutive session.

There is a myth among some manufacturing organizations, as they mostly feel that control charts are less applicable for the short-run process as the duration of their production cycle is too short. Recent studies signify control charts for the production process draw the attention of quality practitioners. Quality professionals are more concerned about the quality of the product. They are doing continuous improvement in product quality by reducing variability. The repute of any industry depends on the quality of goods or services that they offer to the customer. Quality is a major strategy that increases the productivity of any industry.

There are various SPC (statistical process control) short run control charts presented in literature to serve the purpose. Short run control charts are more effective and useful for the small lot manufacturing runs with limited production data. Ladany<sup>11</sup> first introduced optimized-p chart for short production run. Later on, numerous authors introduced effective designs for such economic process, see for instance Ladany and Bedi<sup>12</sup>, Del Castillo and Montgomery<sup>7</sup>, Del Castillo and Montgomery<sup>8</sup>, Tagaras<sup>21</sup>, Nenes and Tagaras<sup>14</sup>, Nenes and Tagaras<sup>15</sup>, Celano et al.<sup>6</sup>, Castagliola et al.<sup>3</sup>, Castagliola et al.<sup>2</sup>, Amdouni et al.<sup>1</sup>, Khatun et al.<sup>9</sup>, Naseri et al.<sup>13</sup> and Khoo et al.<sup>10</sup>.

This study is planned to design the Shewhart control chart for monitoring the ratio of two variables for a short production run. There are several production or manufacturing processes, where the quality characteristics of interest formed the ratio of two normal variables. Production strategies, where numerous components need to be blended together to get a product composition can require monitoring the ratios of random variables when quality experts are frequently interested in the relative evaluation of the same property for two-components. In fact, guaranteeing the stable ratio between different components permits the product specifications to be encountered. Automotive, aerospace, electronics, pharmaceutical, materials production, food preparation, and packaging industries are typical applications of these manufacturing environments.

Celano and Castagliola<sup>4</sup> designed the ratio type Shewhart control chart by using the data from the food processing company. They took the ratio of two seeds (pumpkin and flex) to meet the nutrition facts. Tran et al.<sup>22</sup> investigated the performance of the ratio chart using the run-rules scheme. Tran et al.<sup>22</sup> designed EWMA type control charts for efficient monitoring of the ratio. Tran et al.<sup>23</sup> assessed RZ chart efficiency and performance in presence of measurement error. Tran and Knoth<sup>25</sup> did an analysis to evaluate the steady-state ARL performance of the RZ chart. Tran et al.<sup>24</sup> designed the CUSUM control chart which was more efficient than its RZ setup. Nguyen et al.<sup>16</sup> and Nguyen, Tran and Heuchenne<sup>17</sup> introduced EWMA and CUSUM design for ratio type control chart at several sampling intervals. Nguyen, Tran and Goh<sup>19</sup> applied the variable sampling interval idea to RZ chart to evaluate its efficacy and performance. Nguyen and Tran<sup>18</sup> presented the one-sided RZ chart which was more efficient in case of measurement error present in the process.

The articles cited above are planned to observe the ratio over a production horizon considered as infinite. However, there are numerous situations, where the production run no longer is infinite. As far as we know, no research has been done regarding the observing of the ratio (of two normal variables) infinite horizon framework. The aim of this study is to fill this gap by introducing two one-sided RZ charts aiming to observe the decrease or increase in the finite runs. In the remainder of the study, they are denoted by " $Sh_{RZ}^+$  Chart" for the upper sided chart and by " $Sh_{RZ}^-$  Chart" for the lower sided one.

The rest of the article organized as follows, Section 2 denotes the main properties of ratio distribution. Section 3 deals with the design structure of one-sided RZ ( $Sh_{RZ}^+$  and  $Sh_{RZ}^-$ ) Shewhart charts for a limited production run. The truncated run length (TRL), as the performance measure of the proposed short run charts, is briefly described in Section 4. To assess the behavior of the new charts, a numerical analysis is done in Section 5. Real-life illustration of the proposed technique presented in Section 6. Finally, conclusion and recommendation for future research are given in Section 7.

# 2 Derivation of properties of the ratio distribution

Suppose that X and Y be the two normal random variables such that  $\mathbf{W} = (X, Y)^T \sim N(\boldsymbol{\mu}_{\mathbf{W}}, \boldsymbol{\Sigma}_{\mathbf{W}})$ , i.e. **W** is a bivariate normal random vector with mean vector and variance-covariance matrix as follows:

$$\boldsymbol{\mu}_{\mathbf{W}} = \begin{pmatrix} \mu_X \\ \mu_Y \end{pmatrix} \quad \text{and} \quad \boldsymbol{\Sigma}_{\mathbf{W}} = \begin{pmatrix} \sigma_X^2 & \rho \sigma_X \sigma_Y \\ \rho \sigma_X \sigma_Y & \sigma_Y^2 \end{pmatrix} \tag{1}$$

where  $\mu_X$  and  $\mu_Y$  are the means of two variables and  $\rho$  is the correlation coefficient between them. Coefficients of variation  $(\gamma_X, \gamma_Y)$  and standard-deviation ratio  $(\omega)$  of X and Y are denoted by  $\gamma_X = \frac{\sigma_X}{\mu_Y}$ ,  $\gamma_Y = \frac{\sigma_Y}{\mu_Y}$  and  $\omega = \frac{\sigma_X}{\sigma_Y}$ , respectively. Let Z be the ratio of X to Y (Z = X/Y). Celano and Castagliola<sup>4</sup> derived an adequate approximation for the c.d.f (cumulative distribution function) of Z as a function of  $\gamma_X, \gamma_Y, \omega$ , and  $\rho$  as:

$$F_Z(z|\gamma_X, \gamma_Y, \omega, \rho) \simeq \Phi\left(\frac{A}{B}\right),$$
 (2)

where

$$A = \frac{z}{\gamma_Y} - \frac{\omega}{\gamma_X}$$
, and  $B = \sqrt{\omega^2 - 2\rho\omega z + z^2}$ ,

and  $\Phi$  is the *c.d.f* of standard normal distribution (Sdn). After some tedious derivations, approximated *p.d.f* (probability density function) of the ratio Z is

$$f_Z(z|\gamma_X, \gamma_Y, \omega, \rho) \simeq \left(\frac{1}{B\gamma_Y} - \frac{(z - \rho\omega)A}{B^3}\right) \times \phi\left(\frac{A}{B}\right),\tag{3}$$

where  $\phi(\cdot)$  is the p.d.f. of Sdn. Solving the equation  $F_Z(z | \gamma_X, \gamma_Y, \omega, \rho) = p$ allows obtaining an approximate expression for the *i.d.f* (inverse distribution function)  $F_Z^{-1}(p|\gamma_X, \gamma_Y, \omega, \rho)$ . We have

$$F_Z^{-1}(p|\gamma_X, \gamma_Y, \omega, \rho) \simeq \begin{cases} \frac{-C_2 - \sqrt{C_2^2 - 4C_1C_3}}{2C_1}, & \text{if } p \in (0, 0.5], \\ \frac{-C_2 + \sqrt{C_2^2 - 4C_1C_3}}{2C_1}, & \text{if } p \in [0.5, 1), \end{cases}$$
(4)

where  $C_1$ ,  $C_2$ , and  $C_3$  are functions of  $\omega, \rho, \gamma_X, \gamma_Y, p$  and they are:

$$C_{1} = \frac{1}{\gamma_{Y}^{2}} - \left(\Phi^{-1}(p)\right)^{2},$$

$$C_{2} = 2\omega \left(\rho \left(\Phi^{-1}(p)\right)^{2} - \frac{1}{\gamma_{X}\gamma_{Y}}\right)$$

$$C_{3} = \omega^{2} \left(\frac{1}{\gamma_{X}^{2}} - \left(\Phi^{-1}(p)\right)^{2}\right),$$

and where  $\Phi^{-1}(\cdot)$  is the *i.d.f.* of Sdn.

# 3 Design of two one sided Shewhart RZ charts for short production Runs

The production run is planned to produce small size lot having N parts after a fixed rolling length H. Let I be the number of planned inspections of rolling horizon H and assume that no inspection takes place at the end of the run. By these settings, the sampling frequency (the time interval between two consecutive inspections) will be  $S_h = \frac{H}{(I+1)}$  hours. The observed values of random variables X and Y are used to calculate the ratio for two one sided Shewhart charts for short run. In order to monitor the ratio Z, samples of size n will be taken at every sampling interval from the process and the quality characteristic **W** will be measured for each item. Let  $[\mathbf{W}_{i,1}, \mathbf{W}_{i,2}, \ldots, \mathbf{W}_{i,n}]$  be the collected sample in which the couples  $\mathbf{W}_{i,j} = (X_{i,j}, Y_{i,j})^T$  for j = 1, 2, ...n follow the bivariate normal model  $N(\boldsymbol{\mu}_{\mathbf{W},i}, \boldsymbol{\Sigma}_{\mathbf{W},i})$  where:

$$\boldsymbol{\mu}_{\mathbf{W},i} = \begin{pmatrix} \mu_{X,i} \\ \mu_{Y,i} \end{pmatrix} \quad \text{and} \quad \boldsymbol{\Sigma}_{\mathbf{W},i} = \begin{pmatrix} \sigma_{X,i}^2 & \rho \sigma_{X,i} \sigma_{Y,i} \\ \rho \sigma_{X,i} \sigma_{Y,i} & \sigma_{Y,i}^2 \end{pmatrix}, \quad i = 1, 2, 3, \dots \quad (5)$$

To design the charts, let  $\gamma_X$  and  $\gamma_Y$  be the known and constant coefficients of variation and let  $z_0 = \frac{\mu_{X,i}}{\mu_{Y,i}}$  and  $\rho_0$  be the known in-control values of the ratio and the coefficient of correlation that will ensure the stability of process. We further assume that linear relationships are held between the sample standard deviation and the sample mean for both variables X and Y, i.e.,  $\sigma_{X,i} = \gamma_X \mu_{X,i}$ and  $\sigma_{Y,i} = \gamma_Y \mu_{Y,i}$  for every  $i \geq 1$ . This implies that the standard deviation of each sample can change proportionally to its mean such that their ratio remains constant. There are several quality characteristics in practice (such as weights, tensile strengths and linear dimensions) that can have a dispersion proportional to the population mean. Finally, the sample units are considered free to vary from sample to sample and thus it is possible to have  $\mu_{\mathbf{W},i} \neq \mu_{\mathbf{W},k}$  and  $\Sigma_{\mathbf{W},i} \neq$  $\Sigma_{\mathbf{W},k}$ , for  $i \neq k$ . The monitoring statistic of the proposed chart is the ratio of sample means that should be calculated at the inspections i = 1, 2, , 3, ... as:

$$\hat{Z}_{i} = \frac{\hat{\mu}_{X,i}}{\hat{\mu}_{Y,i}} = \frac{\bar{X}_{i}}{\bar{Y}_{i}} = \frac{\sum_{j=1}^{n} X_{i,j}}{\sum_{j=1}^{n} Y_{i,j}}$$
(6)

To obtain the *c.d.f* and *i.d.f* of the statistic  $\hat{Z}_i$ , one needs to some distributional proportions of the sample means  $\bar{X}_i$  and  $\bar{Y}_i$ . It is easy to see that  $\bar{X}_i \sim N(\mu_{X,i}, \frac{\sigma_{X,i}}{\sqrt{n}})$  and  $\bar{Y}_i \sim N(\mu_{Y,i}, \frac{\sigma_{Y,i}}{\sqrt{n}})$  having the constant coefficients of variation  $\gamma_{\bar{X}} = \frac{\gamma_X}{\sqrt{n}}$  and  $\gamma_{\bar{Y}} = \frac{\gamma_Y}{\sqrt{n}}$ . By the definition and the mentioned assumptions, the standard deviation ratio  $\omega_i$  in each inspection can be calculated as:

$$\omega_i = \frac{\sigma_{X,i}}{\sigma_{Y,i}} = \frac{\mu_{X,i}}{\mu_{Y,i}} \frac{\gamma_X}{\gamma_Y} = z_0 \times \frac{\gamma_X}{\gamma_Y} = \omega_0, \tag{7}$$

where  $\omega_0$  is the in-control standard deviations ratio. We are now in a position to obtain the *c.d.f* and *i.d.f* of  $\hat{Z}_i$  based on the *c.d.f* and *i.d.f* of Z in (2) and (4) as (Nguyen, Tran and  $Goh^{19}$ ):

$$F_{\hat{Z}_i}(z|n,\gamma_X,\gamma_Y,z_0,\rho_0) = F_Z\left(z|\frac{\gamma_X}{\sqrt{n}},\frac{\gamma_Y}{\sqrt{n}},\frac{z_0\gamma_X}{\gamma_Y},\rho_0\right),\tag{8}$$

$$F_{\hat{Z}_i}^{-1}(p|n,\gamma_X,\gamma_Y,z_0,\rho_0) = F_Z^{-1}\left(p|\frac{\gamma_X}{\sqrt{n}},\frac{\gamma_Y}{\sqrt{n}},\frac{z_0\gamma_X}{\gamma_Y},\rho_0\right).$$
(9)

The control limits of two separate one sided ratio charts are as follows

1. One sided Shewhart- $RZ^-$  chart ( $Sh_{RZ}^-$  Chart) The downward ratio uses to monitor the decrease in ratio of two variables. The lower and the upper control limits  $LCL^-$  and  $UCL^-$  of said chart are:

$$LCL^{-} = F_{\hat{z}}^{-1}(\alpha_0 | n, \gamma_X, \gamma_Y, z_0, \rho_0)$$
(10)

$$UCL^{-} = +\infty. \tag{11}$$

where  $\alpha_0$  is the probability of type I error.

2. One sided Shewhart- $RZ^+$  chart ( $Sh_{RZ}^+$  Chart) The upward ratio uses to monitor the increase in ratio of two variables. The lower and the upper control limits  $LCL^+$  and  $UCL^+$  of said chart are:

$$LCL^+ = 0 \tag{12}$$

$$UCL^{+} = F_{\hat{Z}_{i}}^{-1}(1 - \alpha_{0}|n, \gamma_{X}, \gamma_{Y}, z_{0}, \rho_{0}).$$
(13)

The ratio of two normal variables  $\hat{Z}_i$  will be plotted against the limits. We will count all points which fall outside of the limits of both charts. The process is consider to be out-of-control (occ) if  $\hat{Z}_i$  fulfills either of these conditions,  $\hat{Z}_i < LCL^-$  or  $\hat{Z}_i > UCL^+$  and assignable causes will be removed. As the production run is too small, the traditional run length will not be applicable to determine the run length properties of the control charts. To serve the purpose truncated run-length *TRL* and its average (*TARL*) will be used to determine the performance of the charts. The details and computations of *TRL* and *TARL* are provided in what follows.

### 4 Properties of Truncated Run Length TRL

In certain manufacturing processes, it could not be practical to gather a sufficient amount of data at the beginning of the manufacturing process for trial limits in phase-I. For example, in the aerospace industry, the production rate of huge components can be finite. It takes too much time to gather enough samples for the applying control charts. On the other hand, it is often needed that the quality control procedure starts as early as possible since the rate of each product is high. In such circumstances, traditional quality charts are not as effective. It may need more samples to create control limits until they are precise adequate to screen the whole process. Traditional run-length does not give the reliable monitoring of assignable cause for such a process in which a finite (or limited) number I of samples is available in the production horizon having finite length H. Therefore, TRL as a modified version of traditional run length is used to determine the behavior of the process short production runs. It is define as "the number of samples until a shift is identified or until completion of process either happen first". TRL is a discreet random variable with support  $TRL \in \{1, 2, ..., I, I+1\}$ . The event TRL = l for  $l \in \{1, 2, ..., I\}$  means that an ooc signal is declared by the chart before the termination of the production run and TRL = I + 1 expresses that the run is completed without detecting any shift in I inspections. The p.m.f (probability mass function)  $f_{TRL}(l)$  and the  $c.d.f \ F_{TRL}(l)$  of TRL can be derived as follows:

$$f_{TRL}(l) = \begin{cases} p(1-p)^{l-1}, & \text{if } l = 1, 2, ..., I, \\ (1-p)^{I}, & \text{if } l = I+1, \end{cases}$$
(14)

and

$$F_{TRL}(l) = \begin{cases} 1 - (1-p)^l, & \text{if } l = 1, 2, ..., I, \\ 1, & \text{if } l = I+1, \end{cases}$$
(15)

where p is the probability of an occ signal. Let TARL be the expected value of TRL that can be used in place of the traditional ARL to evaluate the performance of the control charts in finite horizon production. Moreover, let  $TARL_0$  and  $TARL_1$  be the in-control and out-of-control values of TARL, respectively. Substituting p by  $\alpha$  ( $\alpha$  is the probability of type I error) or  $1 - \beta$  ( $\beta$  is the probability of type II error) in (14) and taking expectation over the TRL support,  $TARL_0$  and  $TARL_1$  will be derived as (Nenes and Tagaras <sup>15</sup>):

$$TARL_0 = \sum_{l=1}^{I} l(1-\alpha)^{l-1} \alpha + (I+1)(1-\alpha)^I = \frac{1-(1-\alpha)^{I+1}}{\alpha}, \qquad (16)$$

$$TARL_{1} = \sum_{l=1}^{I} l\beta^{l-1}(1-\beta) + (I+1)\beta^{I} = \frac{1-\beta^{I+1}}{1-\beta}.$$
(17)

The error probabilities  $\alpha$  and  $\beta$  can be calculated for the proposed charts by:

$$\alpha = \begin{cases} F_{\hat{Z}_i}(LCL^-|n,\gamma_X,\gamma_Y,z_0,\rho_0), & \text{for } \mathcal{S}h_{RZ}^- \text{ Chart} \\ 1 - F_{\hat{Z}_i}(UCL^+|n,\gamma_X,\gamma_Y,z_0,\rho_0), & \text{for } \mathcal{S}h_{RZ}^+ \text{ Chart} \end{cases}$$
(18)

and

$$\beta = \begin{cases} 1 - F_{\hat{Z}_i}(LCL^-|n,\gamma_X,\gamma_Y,z_1,\rho_1), & \text{for } \mathcal{S}h_{RZ}^- \text{ Chart} \\ F_{\hat{Z}_i}(UCL^+|n,\gamma_X,\gamma_Y,z_1,\rho_1), & \text{for } \mathcal{S}h_{RZ}^+ \text{ Chart} \end{cases}$$
(19)

where  $z_1 = \tau z_0 \ (\tau > 0)$  and  $\rho_1$  are the out-of-control values of the ratio and the coefficient of correlation, respectively. While the values of shift size  $\tau \in (0, 1)$  correspond to decrease of nominal ratio  $z_0$ , the values of  $\tau > 1$  correspond to an increase of nominal ratio  $z_0$ .

### 5 Numerical Performance Analysis

In this section, we evaluate the statistical performance of the two one-sided  $Sh_{RZ}^-$  and  $Sh_{RZ}^+$  charts for the short production run. The performance of the chart is evaluated by the startup of the short run when a particular shift  $(\tau)$  happens. To serve the purpose, the *TARL* metric is used as the performance measure instead of using traditional *ARL*. Initially, let *TARL*<sub>0</sub> = *I* when the process expected to be in control. Statistical performance has been calculated by considering the following parameters values.

- $z_0=1$  (in-control ratio of two variables)
- $\gamma_X \in \{0.01, 0.2\}$  and  $\gamma_Y \in \{0.01, 0.2\}$
- $\rho_0 \in \{0.0, \pm 0.4, \pm 0.8\}$
- $n = \{1, 5, 7, 10, 15\}$
- $I = \{10, 30, 50\}$

• 
$$\tau = \begin{cases} 0.9, 0.95, 0.98, 0.99; & for Sh_{RZ}^- chart \\ 1.01, 1.02, 1.05, 1.1 & for Sh_{RZ}^+ chart \end{cases}$$

Tables 1-3 illustrate the probability-type control limits  $LCL^-$  and  $UCL^+$  values designing such that  $TARL_0 = I$  (Nenes and Tagaras<sup>14</sup>) by varying  $\gamma_X, \gamma_Y, \rho_0$ and n at  $\tau = \tau_0$  (when process is in control) and  $z_0 = 1$ . Tables 4-9 exhibit the  $TARL_1$  values for two charts  $(Sh_{RZ}^-$  and  $Sh_{RZ}^+)$  for I = 10, 30 and 50, when  $\rho_1 = \rho_0$  using  $n \in \{1, 5, 7, 15, 30\}, \gamma_X = \gamma_Y, \gamma_X \neq \gamma_Y$  and  $\tau = \{0.9, 0.95, 0.98, 0.99, 1.01, 1.02, 1.05, 1.1\}$ . Tables 10-15 demonstrate the  $TARL_1$ values for two charts  $(Sh_{RZ}^-$  and  $Sh_{RZ}^+)$  for I = 10, 30 and 50, when  $\rho_1 \neq \rho_0$  using  $n \in \{1, 5, 7, 15, 30\}, \tau = \{0.9, 0.95, 0.98, 0.99, 1.01, 1.02, 1.05, 1.1\}, \gamma_X = \gamma_Y,$ and  $\gamma_X \neq \gamma_Y$ . The findings of proposed design in Tables 1-3 are as follows:

1. Influence of sample size (n) to chart performance The width of control limits decreases as sample size (n) increases for particular values of  $\gamma_X, \gamma_Y, \rho_0$  and I. For example, when  $(\gamma_X, \gamma_Y) = (0.01, 0.01)$ , n = 1, I = 10, and  $\rho_0 = \rho_1 = -0.8$  we have  $(LCL^-, UCL^+) = (0.9615, 1.0401)$  while for, n = 15, we have  $(LCL^-, UCL^+) = (0.9899, 1.0102)$  (cf. Table 1). Similar pattern can be observed for other values.

$\gamma_X$	$\gamma_Y$	$ ho_0$	n = 1	n = 5	n = 7	n = 10	n = 15
0.01	0.01	-0.8	0.9615	0.9826	0.9853	0.9877	0.9899
			1.0401	1.0177	1.0150	1.0125	1.0102
		-0.4	0.9660	0.9846	0.9870	0.9891	0.9911
			1.0352	1.0156	1.0132	1.0110	1.0090
		0.0	0.9712	0.9870	0.9890	0.9908	0.9925
			1.0297	1.0132	1.0111	1.0093	1.0076
		0.4	0.9776	0.9899	0.9915	0.9929	0.9942
			1.0229	1.0102	1.0086	1.0072	1.0059
		0.8	0.9870	0.9942	0.9951	0.9959	0.9966
			1.0132	1.0059	1.0050	1.0041	1.0034
0.20	0.20	-0.8	0.4326	0.7008	0.7413	0.7789	0.8158
			2.3116	1.4269	1.3490	1.2838	1.2258
		-0.4	0.4754	0.7306	0.7678	0.8021	0.8356
			2.1034	1.3687	1.3025	1.2467	1.1967
		0.0	0.5313	0.7668	0.7997	0.8299	0.8591
			1.8821	1.3042	1.2505	1.2049	1.1640
		0.4	0.6108	0.8139	0.8409	0.8655	0.8890
			1.6373	1.2287	1.1892	1.1555	1.1249
		0.8	0.7508	0.8878	0.9047	0.9199	0.9343
			1.3319	1.1264	1.1053	1.0871	1.0703
0.01	0.20	-0.8	0.6954	0.8375	0.8592	0.8796	0.8995
			1.7346	1.2363	1.1929	1.1567	1.1245
		-0.4	0.7010	0.8405	0.8619	0.8818	0.9014
			1.7207	1.2319	1.1893	1.1537	1.1222
		0.0	0.7068	0.8436	0.8645	0.8841	0.9033
			1.7067	1.2274	1.1856	1.1508	1.1198
		0.4	0.7127	0.8467	0.8673	0.8864	0.9053
			1.6925	1.2228	1.1819	1.1477	1.1174
		0.8	0.7188	0.8500	0.8701	0.8888	0.9073
			1.6781	1.2181	1.1781	1.1446	1.1149
0.20	0.01	-0.8	0.5765	0.8089	0.8383	0.8645	0.8893
			1.4381	1.1941	1.1638	1.1369	1.1117
		-0.4	0.5812	0.8118	0.8408	0.8667	0.8911
			1.4266	1.1898	1.1603	1.1340	1.1094
		0.0	0.5859	0.8147	0.8434	0.8690	0.8930
			1.4149	1.1854	1.1567	1.1311	1.1070
		0.4	0.5908	0.8178	0.8461	0.8713	0.8950
			1.4032	1.1810	1.1531	1.1281	1.1046
		0.8	0.5959	0.8209	0.8488	0.8736	0.8969
			1.3912	1.1765	1.1493	1.1251	1.1022

Table 1: Values of  $(LCL^-, UCL^+)$  for  $z_0 = 1$ ,  $\gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}$ ,  $\rho_0 \in \{0.0, \pm 0.4, \pm 0.8\}$ ,  $n = \{1, 5, 7, 10, 15\}$  and  $TARL_0 = 10$ .

$\gamma_X$	$\gamma_Y$	$ ho_0$	n = 1	n = 5	n = 7	n = 10	n = 15
0.01	0.01	-0.8	0.9474	0.9761	0.9798	0.9831	0.9861
			1.0555	1.0245	1.0206	1.0172	1.0141
		-0.4	0.9534	0.9789	0.9821	0.9850	0.9878
			1.0488	1.0215	1.0182	1.0152	1.0124
		0.0	0.9605	0.9821	0.9849	0.9873	0.9897
			1.0411	1.0182	1.0153	1.0128	1.0105
		0.4	0.9693	0.9861	0.9883	0.9902	0.9920
			1.0317	1.0141	1.0119	1.0099	1.0081
		0.8	0.9821	0.9920	0.9932	0.9943	0.9954
			1.0182	1.0081	1.0068	1.0057	1.0047
0.20	0.20	-0.8	0.2908	0.6097	0.6601	0.7077	0.7549
			3.4390	1.6402	1.5149	1.4131	1.3248
		-0.4	0.3318	0.6457	0.6929	0.7369	0.7802
			3.0136	1.5486	1.4433	1.3570	1.2817
		0.0	0.3888	0.6904	0.7330	0.7724	0.8106
			2.5722	1.4484	1.3642	1.2947	1.2336
		0.4	0.4761	0.7500	0.7859	0.8185	0.8498
			2.1005	1.3333	1.2725	1.2218	1.1767
		0.8	0.6473	0.8467	0.8699	0.8907	0.9103
			1.5449	1.1811	1.1495	1.1227	1.0986
0.01	0.20	-0.8	0.6223	0.7887	0.8156	0.8412	0.8666
			2.3771	1.3557	1.2855	1.2286	1.1794
		-0.4	0.6292	0.7926	0.8191	0.8441	0.8691
			2.3510	1.3490	1.2801	1.2243	1.1761
		0.0	0.6364	0.7966	0.8226	0.8471	0.8716
			2.3246	1.3422	1.2747	1.2200	1.1726
		0.4	0.6437	0.8007	0.8261	0.8502	0.8742
			2.2981	1.3353	1.2692	1.2155	1.1692
		0.8	0.6513	0.8050	0.8298	0.8534	0.8768
			2.2712	1.3283	1.2635	1.2110	1.1656
0.20	0.01	-0.8	0.4207	0.7376	0.7779	0.8139	0.8479
			1.6069	1.2679	1.2260	1.1888	1.1540
		-0.4	0.4254	0.7413	0.7812	0.8168	0.8503
			1.5893	1.2616	1.2209	1.1847	1.1507
		0.0	0.4302	0.7450	0.7845	0.8197	0.8528
			1.5715	1.2553	1.2157	1.1805	1.1473
		0.4	0.4351	0.7489	0.7879	0.8227	0.8553
			1.5535	1.2488	1.2105	1.1762	1.1439
		0.8	0.4403	0.7528	0.7914	0.8257	0.8579
			1.5354	1.2423	1.2051	1.1718	1.1405

Table 2: Values of  $(LCL^-, UCL^+)$  for  $z_0 = 1$ ,  $\gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}$ ,  $\rho_0 \in \{0.0, \pm 0.4, \pm 0.8\}$ ,  $n = \{1, 5, 7, 10, 15\}$  and  $TARL_0 = 30$ .

$\gamma_X$	$\gamma_Y$	$ ho_0$	n = 1	n = 5	n = 7	n = 10	n = 15
0.01	0.01	-0.8	0.9418	0.9736	0.9776	0.9812	0.9846
			1.0618	1.0272	1.0229	1.0191	1.0156
		-0.4	0.9485	0.9766	0.9802	0.9834	0.9864
			1.0543	1.0239	1.0202	1.0169	1.0137
		0.0	0.9563	0.9802	0.9833	0.9860	0.9885
			1.0457	1.0202	1.0170	1.0142	1.0116
		0.4	0.9660	0.9846	0.9870	0.9891	0.9911
			1.0352	1.0156	1.0132	1.0110	1.0090
		0.8	0.9802	0.9911	0.9925	0.9937	0.9949
			1.0202	1.0090	1.0076	1.0063	1.0052
0.20	0.20	-0.8	0.2411	0.5760	0.6298	0.6809	0.7317
			4.1479	1.7361	1.5877	1.4687	1.3666
		-0.4	0.2794	0.6139	0.6647	0.7122	0.7590
			3.5787	1.6288	1.5045	1.4042	1.3175
		0.0	0.3341	0.6614	0.7076	0.7503	0.7920
			2.9931	1.5120	1.4133	1.3328	1.2627
		0.4	0.4210	0.7253	0.7645	0.8003	0.8346
			2.3753	1.3787	1.3080	1.2496	1.1982
		0.8	0.6007	0.8303	0.8561	0.8791	0.9008
			1.6648	1.2044	1.1680	1.1375	1.1101
0.01	0.20	-0.8	0.5971	0.7708	0.7995	0.8268	0.8541
			2.7832	1.4095	1.3262	1.2596	1.2027
		-0.4	0.6045	0.7751	0.8032	0.8300	0.8568
			2.7492	1.4018	1.3201	1.2548	1.1989
		0.0	0.6121	0.7794	0.8070	0.8333	0.8596
			2.7151	1.3940	1.3139	1.2498	1.1951
		0.4	0.6200	0.7839	0.8109	0.8366	0.8624
			2.6807	1.3861	1.3076	1.2448	1.1911
		0.8	0.6281	0.7884	0.8149	0.8401	0.8653
			2.6460	1.3780	1.3011	1.2397	1.1871
0.20	0.01	-0.8	0.3593	0.7095	0.7540	0.7939	0.8315
			1.6746	1.2973	1.2508	1.2095	1.1708
		-0.4	0.3637	0.7134	0.7575	0.7970	0.8341
			1.6542	1.2902	1.2450	1.2048	1.1671
		0.0	0.3683	0.7174	0.7611	0.8001	0.8368
			1.6337	1.2830	1.2392	1.2001	1.1633
		0.4	0.3730	0.7215	0.7648	0.8033	0.8395
			1.6130	1.2757	1.2332	1.1953	1.1595
		0.8	0.3779	0.7257	0.7686	0.8067	0.8424
_			1.5921	1.2683	1.2272	1.1903	1.1556

Table 3: Values of  $(LCL^-, UCL^+)$  for  $z_0 = 1$ ,  $\gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}$ ,  $\rho_0 \in \{0.0, \pm 0.4, \pm 0.8\}$ ,  $n = \{1, 5, 7, 10, 15\}$  and  $TARL_0 = 50$ .

- 2. Effect of  $\gamma_X$  and  $\gamma_Y$  values to chart performance Mostly, the control limits  $LCL^-$  and  $UCL^+$  do not hold symmetry around 1. However, symmetry approximated attained by increasing sample size (n) for strong correlation and smaller values of  $(\gamma_X, \gamma_Y)$ . In general,  $UCL^+ \neq \frac{1}{LCL^-}$ ; when  $\gamma_X = \gamma_Y$  than  $UCL^+ = \frac{1}{LCL^-}$  hold. For example, when  $\gamma_X = \gamma_Y = 0.01$ ,  $\rho_0 = \rho_1 = -0.8, n = 1$ , and I = 10 the values of  $LCL^-$  and  $UCL^+$  are 0.9615 and 1.0401 that hold symmetry  $(\frac{1}{0.9615} = 1.0401)$  (cf. Table 1). Similar pattern may be observe for  $I = 30\&50(\gamma_X = \gamma_Y)$  and which is accordance to Celano and Castagliola<sup>4</sup>.
- 3. Impact of *I* to chart performance The number of inspections *I* affects the width of control limits. The values of  $LCL^-$  and  $UCL^+$ , when  $\gamma_X = \gamma_Y = 0.01$ ,  $\rho_0 = \rho_1 = -0.8$  are (0.9615, 1.0401) for I = 10 (cf. Table 1), (0.9474, 1.055) for I = 30 (cf. Table 2), and (0.9418, 1.0618) for I = 50 (cf. Table 3). The value of  $LCL^-$  and  $UCL^+$  using  $\gamma_X = 0.01$ ,  $\gamma_Y = 0.2$ , n = 1,  $\rho_0 = \rho_1 = -0.8$  are (0.6954, 1.7346) for I = 10, (0.6223, 2.3771) for I = 30, and (0.5971, 2.7832) for I = 50. Similar pattern of  $LCL^-$  and  $UCL^+$ can be observed for other values. Number of inspection widens the control limits.

The following results can be drawn from Tables 4-9.

- 1. When shift size  $\tau$  decrease or increase at fixed values of I, n and  $\rho_0$ , the TARL will decrease or increase accordingly. It can be observe that  $TARL_1 < TARL_0$  in all cases. For instance, at fixed values of I = $10, \gamma_X = \gamma_Y = 0.01, n = 1, \rho_1 = \rho_0 = -0.8, TARL_0 = 10$  and for a specific  $\tau, TARL_1$  values are 1, 1.4, 5.4, 8.2 and 8.2, 5.5, 1.4, 1. Similar pattern of  $TARL_1$  may be noted for other values of  $I = 30, 50, \gamma_X = \gamma_Y, \rho_1 = \rho_0$ . Since, the ratio distribution is skewed but one sided Shewhart charts attain symmetry.
- 2. As sample size increases, the value of TARL1 decreases. Sample size influences the chart performance for specific values of  $\tau$ , I,  $\gamma_X = \gamma_Y$ ,  $\rho_1 = \rho_0$ . For example,  $TARL_1$  values are 8.2, 4.8, 3.9, 2.9, 2.0 for  $Sh_{RZ}^-$  chart with  $\tau = 0.99$  and are 8.2, 4.8, 3.8, 2.9, 2.1 for  $Sh_{RZ}^+$  chart with  $\tau = 1.01$  at  $n \in \{1, 5, 7, 15, 30\}$ , I = 10, and  $\rho_1 = \rho_0 = -0.8$  (cf. Table-4).  $Sh_{RZ}^-$  chart is more sensitive to shifts than  $Sh_{RZ}^+$  chart in ratio z. Similar pattern may be observed for I = 30 and 50.

Table 4:  $TARL_1$  values of the one-sided Shewhart RZ chart  $(Sh_{RZ}^-)$  and  $Sh_{RZ}^+)$  for  $z_0 = 1, \gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}, \gamma_X = \gamma_Y, \ \rho_0 \in \{-0.8, -0.4, 0.0, 0.4, 0.8\}, \rho_1 = \rho_0, n = \{1, 5, 7, 10, 15\}, \tau = \{0.9, 0.95, 0.98, 0.99, 1, 1.01, 1.02, 1.05, 1.1\}$  and  $TARL_0 = 10$ 

	$(\gamma_X, \gamma_Y) = (0.01, 0.01)$						$(\gamma_X, \gamma_Y) = (0.2, 0.2)$				
au	$\overline{n=1}$	n = 5	n = 7	n = 10	n = 15	_	n = 1	n = 5	n = 7	n = 10	n = 15
					$\rho_0$ =	$= \rho_1 =$	-0.8				
0.90	1.0	1.0	1.0	1.0	1.0		9.3	7.8	7.2	6.4	5.4
0.95	1.4	1.0	1.0	1.0	1.0		9.7	9.1	8.9	8.6	8.2
0.98	5.4	1.6	1.3	1.1	1.0		9.9	9.7	9.6	9.6	9.4
0.99	8.2	4.8	3.8	2.9	2.0		9.9	9.9	9.8	9.8	9.7
1.01	8.2	4.8	3.9	2.9	2.1		9.9	9.9	9.8	9.8	9.7
1.02	5.5	1.7	1.3	1.1	1.0		9.9	9.7	9.7	9.6	9.5
1.05	1.4	1.0	1.0	1.0	1.0		9.7	9.2	9.0	8.7	8.3
1.10	1.0	1.0	1.0	1.0	1.0		9.4	8.1	7.6	6.9	5.9
					$\rho_0$ =	$= \rho_1 =$	-0.4				
0.90	1.0	1.0	1.0	1.0	1.0		9.3	7.4	6.7	5.8	4.7
0.95	1.2	1.0	1.0	1.0	1.0		9.7	9.0	8.7	8.4	7.9
0.98	4.7	1.4	1.1	1.0	1.0		9.9	9.7	9.6	9.5	9.4
0.99	7.8	4.0	3.1	2.3	1.7		9.9	9.8	9.8	9.8	9.7
1.01	7.9	4.1	3.2	2.3	1.7		9.9	9.8	9.8	9.8	9.7
1.02	4.8	1.4	1.2	1.0	1.0		9.9	9.7	9.6	9.5	9.4
1.05	1.2	1.0	1.0	1.0	1.0		9.7	9.1	8.8	8.5	8.0
1.10	1.0	1.0	1.0	1.0	1.0		9.3	7.7	7.1	6.3	5.2
					$ ho_0$	$= \rho_1 =$	= 0.0				
0.90	1.0	1.0	1.0	1.0	1.0		9.1	6.7	5.9	4.9	3.7
0.95	1.1	1.0	1.0	1.0	1.0		9.6	8.8	8.4	8.0	7.3
0.98	3.7	1.1	1.0	1.0	1.0		9.9	9.6	9.5	9.4	9.2
0.99	7.3	3.1	2.3	1.8	1.3		9.9	9.8	9.8	9.7	9.6
1.01	7.3	3.2	2.4	1.8	1.3		9.9	9.8	9.8	9.7	9.7
1.02	3.8	1.2	1.1	1.0	1.0		9.9	9.6	9.5	9.4	9.2
1.05	1.1	1.0	1.0	1.0	1.0		9.6	8.8	8.5	8.1	7.5
1.10	1.0	1.0	1.0	1.0	1.0		9.2	7.2	6.4	5.4	4.3
					$ ho_0$	$= \rho_1 =$	= 0.4				
0.90	1.0	1.0	1.0	1.0	1.0		8.8	5.5	4.5	3.4	2.4
0.95	1.0	1.0	1.0	1.0	1.0		9.5	8.3	7.8	7.2	6.3
0.98	2.4	1.0	1.0	1.0	1.0		9.8	9.5	9.3	9.2	8.9
0.99	6.2	2.0	1.6	1.3	1.1		9.9	9.8	9.7	9.6	9.5
1.01	6.2	2.1	1.6	1.3	1.1		9.9	9.8	9.7	9.6	9.5
1.02	2.5	1.0	1.0	1.0	1.0		9.8	9.5	9.3	9.2	8.9
1.05	1.0	1.0	1.0	1.0	1.0		9.5	8.4	7.9	7.4	6.5
1.10	1.0	1.0	1.0	1.0	1.0		8.9	6.0	5.1	4.0	2.9
		1.0	1.0		ρ <sub>0</sub>	$= \rho_1 =$	= 0.8				
0.90	1.0	1.0	1.0	1.0	1.0		7.4	2.5	1.8	1.4	1.1
0.95	1.0	1.0	1.0	1.0	1.0		9.0	6.4	5.5	4.4	3.2
0.98	1.1	1.0	1.0	1.0	1.0		9.7	9.0	8.7	8.3	7.8
0.99	3.1	1.1	1.0	1.0	1.0		9.9	9.5	9.4	9.3	9.1
1.01	3.2	1.1	1.0	1.0	1.0		9.9	9.6	9.4	9.3	9.1
1.02	1.2	1.0	1.0	1.0	1.0		9.7	9.0	8.7	8.4	7.8
1.05	1.0	1.0	1.0	1.0	1.0		9.1	6.6	5.7	4.7	3.5
1.10	1.0	1.0	1.0	1.0	1.0		7.7	2.9	2.2	1.6	1.3

Table 5:  $TARL_1$  values of the one-sided Shewhart RZ chart  $(Sh_{RZ}^-)$  and  $Sh_{RZ}^+$  for  $z_0 = 1, \gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}, \gamma_X \neq \gamma_Y, \rho_0 \in \{-0.8, -0.4, 0.0, 0.4, 0.8\}, \rho_1 = \rho_0, n = \{1, 5, 7, 10, 15\}, \tau = \{0.9, 0.95, 0.98, 0.99, 1, 1.01, 1.02, 1.05, 1.1\}$  and  $TARL_0 = 10$ .

$ \begin{array}{c c c c c c c c c c c c c c c c c c c $			$(\gamma_X$	$(\gamma_Y) = ($	(0.01, 0.2)			$(\gamma_X, \gamma_Y) = (0.2, 0.01)$				
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	au	n = 1	n = 5	n = 7	n = 10	n = 15	n = 1	n = 5	n = 7	n = 10	n = 15	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$						$\rho_0 =$	$\rho_1 = -0.8$					
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	0.90	7.5	4.4	3.5	2.7	2.0	9.0	5.8	4.7	3.5	2.4	
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	0.95	9.0	7.7	7.2	6.5	5.6	9.6	8.5	8.0	7.3	6.4	
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	0.98	9.7	9.3	9.1	9.0	8.7	9.9	9.5	9.4	9.2	9.0	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.99	9.8	9.7	9.6	9.5	9.4	9.9	9.8	9.7	9.7	9.6	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.01	9.9	9.8	9.7	9.7	9.6	9.8	9.7	9.6	9.5	9.4	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.02	9.9	9.5	9.4	9.2	9.0	9.7	9.3	9.2	9.0	8.7	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.05	9.6	8.6	8.1	7.5	6.6	9.0	7.8	7.3	6.7	5.8	
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	1.10	9.2	6.4	5.3	4.1	2.9	7.8	4.9	4.1	3.2	2.4	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$						$\rho_0 =$	$\rho_1 = -0.4$					
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	0.90	7.4	4.3	3.4	2.7	2.0	9.0	5.8	4.6	3.4	2.3	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.95	9.0	7.6	7.1	6.4	5.5	9.6	8.4	7.9	7.3	6.3	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.98	9.6	9.3	9.1	8.9	8.6	9.9	9.5	9.4	9.2	8.9	
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.99	9.8	9.7	9.6	9.5	9.4	9.9	9.8	9.7	9.6	9.5	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.01	9.9	9.8	9.7	9.7	9.5	9.8	9.7	9.6	9.5	9.4	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.02	9.9	9.5	9.4	9.2	9.0	9.7	9.3	9.1	9.0	8.7	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.05	9.6	8.5	8.1	7.5	6.5	9.0	7.7	7.3	6.6	5.7	
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	1.10	9.2	6.3	5.2	4.0	2.8	7.7	4.8	4.0	3.1	2.3	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$						$\rho_0$ :	$= \rho_1 = 0.0$					
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.90	7.3	4.1	3.3	2.6	1.9	9.0	5.7	4.5	3.3	2.3	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.95	8.9	7.5	7.0	6.3	5.4	9.6	8.4	7.9	7.2	6.2	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.98	9.6	9.2	9.1	8.9	8.6	9.9	9.5	9.4	9.2	8.9	
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.99	9.8	9.7	9.6	9.5	9.4	9.9	9.8	9.7	9.6	9.5	
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.01	9.9	9.8	9.7	9.6	9.5	9.8	9.7	9.6	9.5	9.4	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.02	9.9	9.5	9.4	9.2	8.9	9.6	9.3	9.1	8.9	8.6	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.05	9.6	8.5	8.0	7.4	6.5	9.0	7.7	7.2	6.5	5.6	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.10	9.1	6.2	5.1	3.9	2.7	7.0	4.7	3.9	3.0	2.2	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	- 0.00	7.0	1.0			1.0	$-p_1 = 0.4$	50		0.0		
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.90	7.2	4.0	3.2	2.5	1.8	9.0	5.0	4.4	3.2	2.2	
$\begin{array}{cccccccccccccccccccccccccccccccccccc$	0.95	0.9	1.4	0.9	0.2	0.2	9.0	0.4	1.0	(.1	0.1	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.90	9.0 0.8	9.2	9.1	0.9	0.0	9.9	9.0	9.4 0.7	9.2 0.6	0.9	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.01	9.0 0.0	9.0	9.0 0.7	9.J 0.6	9.4	9.9	9.0 0.7	9.1	9.0	9.0 Q /	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.01	9.9 Q Q	9.5	9.1 9.1	9.0 0.2	9.0 8 0	0.6 0.0	9.1	9.0	9.0 8 0	5.4 8.6	
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.02	9.5 9.6	8.5	8.0	7 2	6.4	5.0 8.0	7.6	71	6.4	5.5	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	1.10	9.1	6.1	5.0	3.8	2.6	7.5	4.6	3.7	2.9	2.1	
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$		0.1	011	0.0	0.0	$\rho_0$	$= \rho_1 = 0.8$	110	0.1	2.0		
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.90	7.1	3.9	3.1	2.4	1.8	9.0	5.5	4.3	3.1	2.1	
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	0.95	8.8	7.4	6.8	6.1	5.1	9.6	8.3	7.8	7.1	6.0	
	0.98	9.6	9.2	9.0	8.8	8.5	9.9	9.5	9.3	9.1	8.9	
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	0.99	9.8	9.6	9.6	9.5	9.4	9.9	9.8	9.7	9.6	9.5	
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	1.01	9.9	9.8	9.7	9.6	9.5	9.8	9.6	9.6	9.5	9.4	
	1.02	9.9	9.5	9.4	9.2	8.9	9.6	9.2	9.1	8.9	8.6	
$1.10 \qquad 9.1 \qquad 6.0 \qquad 4.9 \qquad 3.7 \qquad 2.5 \qquad 7.4 \qquad 4.4 \qquad 3.6 \qquad 2.8 \qquad 2.1$	1.05	9.6	8.4	7.9	7.3	6.3	8.9	7.5	7.0	6.3	5.4	
	1.10	9.1	6.0	4.9	3.7	2.5	7.4	4.4	3.6	2.8	2.1	

Table 6:  $TARL_1$  values of the one-sided Shewhart RZ chart  $(Sh_{RZ}^-)$  and  $Sh_{RZ}^+)$  for  $z_0 = 1$ ,  $\gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}, \gamma_X = \gamma_Y$ ,  $\rho_0 \in \{-0.8, -0.4, 0.0, 0.4, 0.8\}, \rho_1 = \rho_0$ ,  $n = \{1, 5, 7, 10, 15\}, \tau = \{0.9, 0.95, 0.98, 0.99, 1, 1.01, 1.02, 1.05, 1.1\}$  and  $TARL_0 = 30$ .

		$(\gamma_X$	$(\gamma_Y) = ($	0.01, 0.01)		$(\gamma_X, \gamma_Y) = (0.2, 0.2)$				
au	n = 1	n = 5	n = 7	n = 10	n = 15	$\overline{n=1}$	n = 5	n = 7	n = 10	n = 15
					$\rho_0 =$	$= \rho_1 = -0.8$				
0.90	24.1	13.4	10.0	6.9	4.2	29.0	21.6	17.6	12.5	7.1
0.95	28.1	25.1	23.7	21.7	18.6	29.6	27.7	26.7	25.2	22.6
0.98	29.4	28.8	28.6	28.2	27.7	29.9	29.4	29.2	28.9	28.4
0.99	29.7	29.5	29.4	29.3	29.1	29.9	29.7	29.6	29.5	29.4
1.01	29.9	29.7	29.6	29.5	29.4	29.8	29.5	29.4	29.3	29.1
1.02	29.9	29.4	29.2	28.9	28.5	29.5	28.8	28.6	28.3	27.7
1.05	29.6	27.9	27.0	25.6	23.2	28.3	25.5	24.2	22.4	19.5
1.10	29.1	23.1	19.7	15.0	9.3	25.0	15.6	12.3	8.8	5.5
					$\rho_0 =$	$= \rho_1 = -0.4$				
0.90	23.8	12.8	9.6	6.5	4.0	29.0	21.4	17.3	12.1	6.7
0.95	28.0	24.9	23.4	21.4	18.2	29.6	27.6	26.6	25.0	22.3
0.98	29.4	28.8	28.5	28.2	27.6	29.9	29.4	29.1	28.9	28.4
0.99	29.7	29.5	29.4	29.3	29.1	29.9	29.7	29.6	29.5	29.4
1.01	29.9	29.7	29.6	29.5	29.4	29.7	29.5	29.4	29.3	29.1
1.02	29.9	29.4	29.2	28.9	28.4	29.4	28.8	28.6	28.2	27.7
1.05	29.6	27.8	26.9	25.5	23.0	28.2	25.3	24.0	22.1	19.2
1.10	29.1	22.9	19.4	14.6	8.9	24.8	15.1	11.8	8.4	5.2
					$ ho_0$	$= \rho_1 = 0.0$				
0.90	23.5	12.3	9.1	6.1	3.8	29.0	21.1	16.9	11.6	6.4
0.95	28.0	24.6	23.2	21.0	17.7	29.6	27.6	26.5	24.9	22.1
0.98	29.4	28.7	28.5	28.1	27.5	29.9	29.3	29.1	28.8	28.4
0.99	29.7	29.5	29.4	29.3	29.1	29.9	29.7	29.6	29.5	29.4
1.01	29.9	29.7	29.6	29.5	29.4	29.7	29.5	29.4	29.3	29.1
1.02	29.9	29.4	29.2	28.9	28.4	29.4	28.8	28.5	28.2	27.6
1.05	29.6	27.8	26.8	25.3	22.8	28.1	25.1	23.7	21.8	18.7
1.10	29.1	22.7	19.1	14.2	8.5	24.5	14.6	11.3	7.9	4.9
					$ ho_0$	$= \rho_1 = 0.4$				
0.90	23.1	11.7	8.6	5.8	3.6	29.0	20.8	16.5	11.2	6.1
0.95	27.9	24.4	22.9	20.6	17.3	29.6	27.5	26.4	24.7	21.8
0.98	29.4	28.7	28.4	28.0	27.4	29.9	29.3	29.1	28.8	28.3
0.99	29.7	29.5	29.4	29.2	29.0	29.9	29.7	29.6	29.5	29.3
1.01	29.9	29.7	29.6	29.5	29.4	29.7	29.5	29.4	29.2	29.1
1.02	29.9	29.3	29.1	28.8	28.4	29.4	28.7	28.5	28.1	27.5
1.05	29.6	27.7	26.7	25.2	22.6	28.0	24.9	23.5	21.4	18.3
1.10	29.1	22.4	18.7	13.7	8.1	24.2	14.1	10.8	7.5	4.6
					$\rho_0$	$= \rho_1 = 0.8$				
0.90	22.7	11.2	8.1	5.4	3.4	29.0	20.5	16.1	10.7	5.8
0.95	27.8	24.2	22.5	20.2	16.8	29.6	27.4	26.3	24.6	21.5
0.98	29.4	28.6	28.4	28.0	27.3	29.9	29.3	29.1	28.8	28.3
0.99	29.7	29.4	29.3	29.2	29.0	29.9	29.7	29.6	29.5	29.3
1.01	29.9	29.7	29.6	29.5	29.3	29.7	29.5	29.4	29.2	29.0
1.02	29.9	29.3	29.1	28.8	28.3	29.4	28.7	28.4	28.0	27.4
1.05	29.6	27.6	26.6	25.0	22.3	27.9	24.6	23.2	21.0	17.8
1.10	29.1	22.2	18.4	13.3	7.7	23.9	13.5	10.2	7.0	4.4

Table 7:  $TARL_1$  values of the one-sided Shewhart RZ chart  $(Sh_{RZ}^-)$  and  $Sh_{RZ}^+$ ) for  $z_0 = 1, \gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}, \gamma_X \neq \gamma_Y, \rho_0 \in \{-0.8, -0.4, 0.0, 0.4, 0.8\}, \rho_1 = \rho_0, n = \{1, 5, 7, 10, 15\}, \tau = \{0.9, 0.95, 0.98, 0.99, 1, 1.01, 1.02, 1.05, 1.1\}$  and  $TARL_0 = 30$ .

		$(\gamma_X$	$(\gamma_Y) = 0$	(0.01, 0.2)		$(\gamma_X, \gamma_Y) = (0.2, 0.01)$				
au	n = 1	n = 5	n = 7	n = 10	n = 15	$\overline{n=1}$	n = 5	n = 7	n = 10	n = 15
					$\rho_0$ =	$= \rho_1 = -0.8$				
0.90	24.1	13.4	10.0	6.9	4.2	29.0	21.6	17.6	12.5	7.1
0.95	28.1	25.1	23.7	21.7	18.6	29.6	27.7	26.7	25.2	22.6
0.98	29.4	28.8	28.6	28.2	27.7	29.9	29.4	29.2	28.9	28.4
0.99	29.7	29.5	29.4	29.3	29.1	29.9	29.7	29.6	29.5	29.4
1.01	29.9	29.7	29.6	29.5	29.4	29.8	29.5	29.4	29.3	29.1
1.02	29.9	29.4	29.2	28.9	28.5	29.5	28.8	28.6	28.3	27.7
1.05	29.6	27.9	27.0	25.6	23.2	28.3	25.5	24.2	22.4	19.5
1.10	29.1	23.1	19.7	15.0	9.3	25.0	15.6	12.3	8.8	5.5
					$\rho_0$ =	$= \rho_1 = -0.4$				
0.90	23.8	12.8	9.6	6.5	4.0	29.0	21.4	17.3	12.1	6.7
0.95	28.0	24.9	23.4	21.4	18.2	29.6	27.6	26.6	25.0	22.3
0.98	29.4	28.8	28.5	28.2	27.6	29.9	29.4	29.1	28.9	28.4
0.99	29.7	29.5	29.4	29.3	29.1	29.9	29.7	29.6	29.5	29.4
1.01	29.9	29.7	29.6	29.5	29.4	29.7	29.5	29.4	29.3	29.1
1.02	29.9	29.4	29.2	28.9	28.4	29.4	28.8	28.6	28.2	27.7
1.05	29.6	27.8	26.9	25.5	23.0	28.2	25.3	24.0	22.1	19.2
1.10	29.1	22.9	19.4	14.6	8.9	24.8	15.1	11.8	8.4	5.2
					$\rho_0$	$= \rho_1 = 0.0$				
0.90	23.5	12.3	9.1	6.1	3.8	29.0	21.1	16.9	11.6	6.4
0.95	28.0	24.6	23.2	21.0	17.7	29.6	27.6	26.5	24.9	22.1
0.98	29.4	28.7	28.5	28.1	27.5	29.9	29.3	29.1	28.8	28.4
0.99	29.7	29.5	29.4	29.3	29.1	29.9	29.7	29.6	29.5	29.4
1.01	29.9	29.7	29.6	29.5	29.4	29.7	29.5	29.4	29.3	29.1
1.02	29.9	29.4	29.2	28.9	28.4	29.4	28.8	28.5	28.2	27.6
1.05	29.6	27.8	26.8	25.3	22.8	28.1	25.1	23.7	21.8	18.7
1.10	29.1	22.7	19.1	14.2	8.5	24.5	14.6	11.3	7.9	4.9
					$ ho_0$	$= \rho_1 = 0.4$				
0.90	23.1	11.7	8.6	5.8	3.6	29.0	20.8	16.5	11.2	6.1
0.95	27.9	24.4	22.9	20.6	17.3	29.6	27.5	26.4	24.7	21.8
0.98	29.4	28.7	28.4	28.0	27.4	29.9	29.3	29.1	28.8	28.3
0.99	29.7	29.5	29.4	29.2	29.0	29.9	29.7	29.6	29.5	29.3
1.01	29.9	29.7	29.6	29.5	29.4	29.7	29.5	29.4	29.2	29.1
1.02	29.9	29.3	29.1	28.8	28.4	29.4	28.7	28.5	28.1	27.5
1.05	29.6	27.7	26.7	25.2	22.6	28.0	24.9	23.5	21.4	18.3
1.10	29.1	22.4	18.7	13.7	8.1	24.2	14.1	10.8	7.5	4.6
					$ ho_0$	$= \rho_1 = 0.8$				
0.90	22.7	11.2	8.1	5.4	3.4	29.0	20.5	16.1	10.7	5.8
0.95	27.8	24.2	22.5	20.2	16.8	29.6	27.4	26.3	24.6	21.5
0.98	29.4	28.6	28.4	28.0	27.3	29.9	29.3	29.1	28.8	28.3
0.99	29.7	29.4	29.3	29.2	29.0	29.9	29.7	29.6	29.5	29.3
1.01	29.9	29.7	29.6	29.5	29.3	29.7	29.5	29.4	29.2	29.0
1.02	29.9	29.3	29.1	28.8	28.3	29.4	28.7	28.4	28.0	27.4
1.05	29.6	27.6	26.6	25.0	22.3	27.9	24.6	23.2	21.0	17.8
1.10	29.1	22.2	18.4	13.3	7.7	23.9	13.5	10.2	7.0	4.4

Table 8:  $TARL_1$  values of the one-sided Shewhart RZ chart  $(Sh_{RZ}^-)$  and  $Sh_{RZ}^+)$  for  $z_0 = 1, \gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}, \gamma_X = \gamma_Y, \rho_0 \in \{-0.8, -0.4, 0.0, 0.4, 0.8\}, \rho_1 = \rho_0, n = \{1, 5, 7, 10, 15\}, \tau = \{0.9, 0.95, 0.98, 0.99, 1, 1.01, 1.02, 1.05, 1.1\}$  and  $TARL_0 = 50$ .

		$(\gamma_X$	$, \gamma_Y) = ($	0.01, 0.01)		$(\gamma_X, \gamma_Y) = (0.2, 0.2)$				
au	n = 1	n = 5	n = 7	n = 10	n = 15	n = 1	n = 5	n = 7	n = 10	n = 15
					$\rho_0$ =	$= \rho_1 = -0.8$				
0.90	41.6	23.2	17.0	11.0	6.3	49.1	39.3	32.9	23.5	12.7
0.95	47.6	43.4	41.3	38.2	33.0	49.6	47.4	46.1	44.1	40.3
0.98	49.3	48.6	48.3	47.8	47.1	49.9	49.3	49.1	48.7	48.2
0.99	49.7	49.4	49.3	49.2	49.0	49.9	49.7	49.6	49.5	49.3
1.01	49.9	49.7	49.6	49.5	49.3	49.7	49.4	49.3	49.2	49.0
1.02	49.9	49.3	49.1	48.8	48.3	49.4	48.6	48.3	47.9	47.2
1.05	49.6	47.6	46.4	44.6	41.3	47.8	44.0	42.1	39.3	34.7
1.10	49.2	41.4	36.2	28.2	17.1	43.1	27.4	21.3	14.7	8.6
					$\rho_0$ =	$= \rho_1 = -0.4$				
0.90	41.1	22.2	16.0	10.3	5.9	49.1	38.9	32.3	22.8	12.0
0.95	47.5	43.1	40.9	37.6	32.3	49.6	47.3	46.0	43.9	40.0
0.98	49.3	48.5	48.2	47.8	47.0	49.9	49.3	49.1	48.7	48.2
0.99	49.7	49.4	49.3	49.2	49.0	49.9	49.7	49.6	49.5	49.3
1.01	49.9	49.7	49.6	49.5	49.3	49.7	49.4	49.3	49.2	49.0
1.02	49.9	49.3	49.1	48.8	48.2	49.3	48.6	48.3	47.8	47.1
1.05	49.6	47.5	46.4	44.5	41.0	47.7	43.7	41.8	38.8	34.0
1.10	49.2	41.1	35.8	27.5	16.3	42.7	26.5	20.4	13.9	8.1
					$ ho_0$	$= \rho_1 = 0.0$				
0.90	40.6	21.1	15.1	9.7	5.5	49.0	38.6	31.7	22.0	11.4
0.95	47.4	42.7	40.4	37.0	31.5	49.6	47.2	45.9	43.7	39.6
0.98	49.3	48.5	48.1	47.7	46.9	49.9	49.3	49.0	48.7	48.1
0.99	49.7	49.4	49.3	49.1	48.9	49.9	49.7	49.6	49.5	49.3
1.01	49.9	49.7	49.6	49.5	49.3	49.7	49.4	49.3	49.1	48.9
1.02	49.9	49.3	49.1	48.7	48.2	49.3	48.5	48.2	47.7	47.0
1.05	49.6	47.5	46.3	44.3	40.6	47.6	43.4	41.4	38.3	33.2
1.10	49.2	40.8	35.3	26.7	15.5	42.2	25.5	19.3	13.0	7.5
					$ ho_0$	$= \rho_1 = 0.4$				
0.90	40.0	20.0	14.2	9.0	5.1	49.0	38.2	31.0	21.1	10.7
0.95	47.3	42.3	40.0	36.4	30.6	49.6	47.2	45.8	43.5	39.2
0.98	49.3	48.4	48.1	47.6	46.8	49.9	49.3	49.0	48.7	48.1
0.99	49.7	49.4	49.3	49.1	48.9	49.9	49.7	49.6	49.5	49.3
1.01	49.9	49.7	49.6	49.5	49.3	49.7	49.4	49.3	49.1	48.9
1.02	49.9	49.3	49.0	48.7	48.1	49.3	48.5	48.1	47.7	46.9
1.05	49.6	47.4	46.1	44.1	40.3	47.5	43.1	40.9	37.7	32.5
1.10	49.2	40.5	34.7	25.9	14.7	41.7	24.4	18.3	12.2	7.0
					$ ho_0$	$= \rho_1 = 0.8$				
0.90	39.3	18.9	13.2	8.4	4.8	49.0	37.8	30.4	20.2	10.1
0.95	47.1	41.9	39.4	35.7	29.7	49.6	47.1	45.6	43.2	38.8
0.98	49.2	48.4	48.0	47.5	46.7	49.9	49.3	49.0	48.6	48.0
0.99	49.7	49.4	49.2	49.1	48.8	49.9	49.7	49.6	49.5	49.3
1.01	49.9	49.7	49.6	49.5	49.3	49.7	49.4	49.2	49.1	48.9
1.02	49.9	49.3	49.0	48.7	48.1	49.2	48.4	48.1	47.6	46.8
1.05	49.6	47.3	46.0	43.9	39.9	47.3	42.7	40.4	37.1	31.6
1.10	49.2	40.2	34.2	25.1	13.9	41.2	23.3	17.2	11.3	6.5

Table 9:  $TARL_1$  values of the one-sided Shewhart RZ chart  $(Sh_{RZ}^-)$  and  $Sh_{RZ}^+$ ) for  $z_0 = 1, \gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}, \gamma_X \neq \gamma_Y, \rho_0 \in \{-0.8, -0.4, 0.0, 0.4, 0.8\}, \rho_1 = \rho_0, n = \{1, 5, 7, 10, 15\}, \tau = \{0.9, 0.95, 0.98, 0.99, 1, 1.01, 1.02, 1.05, 1.1\}$  and  $TARL_0 = 50$ .

		$(\gamma_X$	$(\gamma_Y) = 0$	(0.01, 0.2)		$(\gamma_X, \gamma_Y) = (0.2, 0.01)$				
au	n = 1	n = 5	n = 7	n = 10	n = 15	$\overline{n=1}$	n = 5	n = 7	n = 10	n = 15
					$\rho_0 =$	$= \rho_1 = -0.8$				
0.90	41.6	23.2	17.0	11.0	6.3	49.1	39.3	32.9	23.5	12.7
0.95	47.6	43.4	41.3	38.2	33.0	49.6	47.4	46.1	44.1	40.3
0.98	49.3	48.6	48.3	47.8	47.1	49.9	49.3	49.1	48.7	48.2
0.99	49.7	49.4	49.3	49.2	49.0	49.9	49.7	49.6	49.5	49.3
1.01	49.9	49.7	49.6	49.5	49.3	49.7	49.4	49.3	49.2	49.0
1.02	49.9	49.3	49.1	48.8	48.3	49.4	48.6	48.3	47.9	47.2
1.05	49.6	47.6	46.4	44.6	41.3	47.8	44.0	42.1	39.3	34.7
1.10	49.2	41.4	36.2	28.2	17.1	43.1	27.4	21.3	14.7	8.6
					$\rho_0 =$	$= \rho_1 = -0.4$				
0.90	41.1	22.2	16.0	10.3	5.9	49.1	38.9	32.3	22.8	12.0
0.95	47.5	43.1	40.9	37.6	32.3	49.6	47.3	46.0	43.9	40.0
0.98	49.3	48.5	48.2	47.8	47.0	49.9	49.3	49.1	48.7	48.2
0.99	49.7	49.4	49.3	49.2	49.0	49.9	49.7	49.6	49.5	49.3
1.01	49.9	49.7	49.6	49.5	49.3	49.7	49.4	49.3	49.2	49.0
1.02	49.9	49.3	49.1	48.8	48.2	49.3	48.6	48.3	47.8	47.1
1.05	49.6	47.5	46.4	44.5	41.0	47.7	43.7	41.8	38.8	34.0
1.10	49.2	41.1	35.8	27.5	16.3	42.7	26.5	20.4	13.9	8.1
					$ ho_0$	$= \rho_1 = 0.0$				
0.90	40.6	21.1	15.1	9.7	5.5	49.0	38.6	31.7	22.0	11.4
0.95	47.4	42.7	40.4	37.0	31.5	49.6	47.2	45.9	43.7	39.6
0.98	49.3	48.5	48.1	47.7	46.9	49.9	49.3	49.0	48.7	48.1
0.99	49.7	49.4	49.3	49.1	48.9	49.9	49.7	49.6	49.5	49.3
1.01	49.9	49.7	49.6	49.5	49.3	49.7	49.4	49.3	49.1	48.9
1.02	49.9	49.3	49.1	48.7	48.2	49.3	48.5	48.2	47.7	47.0
1.05	49.6	47.5	46.3	44.3	40.6	47.6	43.4	41.4	38.3	33.2
1.10	49.2	40.8	35.3	26.7	15.5	42.2	25.5	19.3	13.0	7.5
					$ ho_0$	$= \rho_1 = 0.4$				
0.90	40.0	20.0	14.2	9.0	5.1	49.0	38.2	31.0	21.1	10.7
0.95	47.3	42.3	40.0	36.4	30.6	49.6	47.2	45.8	43.5	39.2
0.98	49.3	48.4	48.1	47.6	46.8	49.9	49.3	49.0	48.7	48.1
0.99	49.7	49.4	49.3	49.1	48.9	49.9	49.7	49.6	49.5	49.3
1.01	49.9	49.7	49.6	49.5	49.3	49.7	49.4	49.3	49.1	48.9
1.02	49.9	49.3	49.0	48.7	48.1	49.3	48.5	48.1	47.7	46.9
1.05	49.6	47.4	46.1	44.1	40.3	47.5	43.1	40.9	37.7	32.5
1.10	49.2	40.5	34.7	25.9	14.7	41.7	24.4	18.3	12.2	7.0
					$\rho_0$	$= \rho_1 = 0.8$				
0.90	39.3	18.9	13.2	8.4	4.8	49.0	37.8	30.4	20.2	10.1
0.95	47.1	41.9	39.4	35.7	29.7	49.6	47.1	45.6	43.2	38.8
0.98	49.2	48.4	48.0	47.5	46.7	49.9	49.3	49.0	48.6	48.0
0.99	49.7	49.4	49.2	49.1	48.8	49.9	49.7	49.6	49.5	49.3
1.01	49.9	49.7	49.6	49.5	49.3	49.7	49.4	49.2	49.1	48.9
1.02	49.9	49.3	49.0	48.7	48.1	49.2	48.4	48.1	47.6	46.8
1.05	49.6	47.3	46.0	43.9	39.9	47.3	42.7	40.4	37.1	31.6
1.10	49.2	40.2	34.2	25.1	13.9	41.2	23.3	17.2	11.3	6.5

3. The charts performance is strongly influenced by values of  $\gamma_X, \gamma_Y$  and I. Proposed design is more efficient, when  $\gamma_X = \gamma_Y$  at  $TARL_0 = 10$ . Both charts equally performed, when  $TARL_0 = 30, 50, \gamma_X = \gamma_Y$  and  $\gamma_X \neq \gamma_Y$ . For example, when  $TARL_0 = 10, n = 1, \rho_0 = \rho_1 = -0.8, \tau^+ = 1.01$  and  $\tau^- = 0.99$ , we have  $TARL_1$  is 8.2 for  $\gamma_X = \gamma_Y = 0.01$ . However for  $\gamma_X = .01 \& \gamma_Y = 0.2$ , we have 9.8&9.9 (cf. Table (4)). The performance of one sided Shewhart chart is identical  $TARL_0 = 30 \& 50$  for all values of  $\gamma_X$  and  $\gamma_Y$  (cf. Table (5)). We have  $TARL_1 = 29.7$  and 29.9 (for  $\gamma_X = \gamma_Y = .01 \& \gamma_X = .01, \gamma_Y = 0.2$ ) (cf. Table (4-9)).

Tables 10-15 indicate the  $TARL_1$  of two  $Sh_{RZ}^-$  and  $Sh_{RZ}^+$  charts for I = 10, 30and 50, when  $\rho_1 \neq \rho_0$  using  $n \in \{1, 5, 7, 15, 30\}, \gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}$  and  $\tau = \{0.9, 0.95, .98, 0.99, 1.01, 1.02, 1.05, 1.1\}$ . Result discussion can be summarized of Tables 10-15 as follows

- 1. Charts showed the asymmetrical performance due to biased feature of  $TARL_1$  for all values of  $n, I, \gamma_X$  and  $\gamma_Y$ . Since in control I = 10, 30, and 50 are not stable.
- 2. It is the worth of observing that when  $\gamma_X < \gamma_Y$  and  $\rho_1 = \rho_0$ , the one sided  $Sh_{RZ}^-$  chart showed the sensitivity towards shifts. Which is conversely true for one sided  $Sh_{RZ}^+$  chart when  $\gamma_Y < \gamma_X$ . For example, when n = 1,  $\rho_0 = -0.4$ ,  $\rho_1 = \frac{\rho_0}{2} = -0.2$ , I = 30,  $\gamma_X = 0.01$ ,  $\gamma_Y = 0.2$ ,  $\tau = .99$  & 1.05, the values of TARL are 9.9 and 10. However, for  $\gamma_X = 0.2$  and  $\gamma_Y = 0.01$  TARL are 10 and 9.9 (cf. Table (10-15).

### 6 Real Life Illustration

The following example has been introduced in Celano et al.<sup>5</sup> for the implementation of a two-sided Shewhart control chart for monitoring the ratio of two

Table 10:  $TARL_1$  values of the one-sided Shewhart RZ chart  $(Sh_{RZ}^-)$  and  $Sh_{RZ}^+$ ) for  $z_0 = 1, \gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}, \gamma_X = \gamma_Y, \rho_0 \in \{-0.8, -0.4, 0.0, 0.4, 0.8\}, \rho_1 = \rho_0, n = \{1, 5, 7, 10, 15\}, \tau = \{0.9, 0.95, 0.98, 0.99, 1, 1.01, 1.02, 1.05, 1.1\}$  and  $TARL_0 = 10$ .

		$(\gamma_X$	$(\gamma_Y) = ($	0.01, 0.01)		$(\gamma_X, \gamma_Y) = (0.2, 0.2)$				
τ	n = 1	n = 5	n = 7	n = 10	n = 15	$\overline{n=1}$	n = 5	n = 7	n = 10	n = 15
					$\rho_0 =$	$-0.4, \rho_1 = -0.2$				
0.90	1.0	1.0	1.0	1.0	1.0	9.6	7.9	7.2	6.3	5.0
0.95	1.2	1.0	1.0	1.0	1.0	10.0	9.5	9.2	8.9	8.4
0.98	5.0	1.3	1.1	1.0	1.0	10.2	10.0	10.0	9.9	9.8
0.99	8.4	4.3	3.2	2.3	1.6	10.2	10.2	10.2	10.1	10.1
1.00	10.3	10.3	10.3	10.3	10.3	10.3	10.3	10.3	10.3	10.3
1.01	8.4	4.4	3.3	2.4	1.7	10.2	10.2	10.2	10.1	10.1
1.02	5.1	1.4	1.1	1.0	1.0	10.2	10.1	10.0	9.9	9.8
1.05	1.2	1.0	1.0	1.0	1.0	10.0	9.5	9.3	9.0	8.6
1.10	1.0	1.0	1.0	1.0	1.0	9.7	8.3	7.7	6.8	5.6
					$\rho_0 =$	$-0.4, \rho_1 = -0.8$				
0.90	1.0	1.0	1.0	1.0	1.0	8.5	6.6	5.9	5.1	4.2
0.95	1.2	1.0	1.0	1.0	1.0	9.0	8.1	7.9	7.5	7.0
0.98	4.2	1.4	1.2	1.1	1.0	9.3	8.9	8.8	8.7	8.5
0.99	6.9	3.7	2.9	2.3	1.7	9.4	9.1	9.1	9.0	8.9
1.00	9.3	9.3	9.3	9.3	9.3	9.4	9.3	9.3	9.3	9.3
1.01	7.0	3.7	3.0	2.3	1.7	9.4	9.1	9.1	9.0	9.0
1.02	4.3	1.4	1.2	1.1	1.0	9.3	8.9	8.8	8.7	8.5
1.05	1.3	1.0	1.0	1.0	1.0	9.0	8.2	8.0	7.6	7.1
1.10	1.0	1.0	1.0	1.0	1.0	8.6	6.9	6.3	5.6	4.7
					$\rho_0 =$	$= 0.4, \rho_1 = 0.2$				
0.90	1.0	1.0	1.0	1.0	1.0	7.8	4.8	4.0	3.1	2.3
0.95	1.0	1.0	1.0	1.0	1.0	8.7	7.3	6.8	6.2	5.4
0.98	2.4	1.0	1.0	1.0	1.0	9.1	8.5	8.4	8.2	7.9
0.99	5.3	2.0	1.6	1.3	1.1	9.2	8.9	8.8	8.7	8.6
1.00	9.2	9.2	9.2	9.2	9.2	9.3	9.2	9.2	9.2	9.2
1.01	5.4	2.1	1.6	1.3	1.1	9.2	8.9	8.8	8.7	8.6
1.02	2.4	1.0	1.0	1.0	1.0	9.1	8.6	8.4	8.2	7.9
1.05	1.0	1.0	1.0	1.0	1.0	8.7	7.4	6.9	6.4	5.6
1.10	1.0	1.0	1.0	1.0	1.0	8.0	5.2	4.4	3.6	2.7
					$\rho_0$ =	$= 0.4, \rho_1 = 0.8$				
0.90	1.0	1.0	1.0	1.0	1.0	10.8	9.1	7.5	5.2	2.8
0.95	1.0	1.0	1.0	1.0	1.0	10.9	10.8	10.7	10.4	9.9
0.98	2.8	1.0	1.0	1.0	1.0	10.9	11.0	10.9	10.9	10.9
0.99	9.8	2.0	1.4	1.1	1.0	10.9	11.0	11.0	11.0	11.0
1.00	11.0	11.0	11.0	11.0	11.0	10.9	11.0	11.0	11.0	11.0
1.01	9.9	2.1	1.4	1.1	1.0	10.9	11.0	11.0	11.0	11.0
1.02	3.0	1.0	1.0	1.0	1.0	10.9	11.0	11.0	10.9	10.9
1.05	1.0	1.0	1.0	1.0	1.0	10.9	10.8	10.7	10.5	10.1
1.10	1.0	1.0	1.0	1.0	1.0	10.8	9.6	8.5	6.6	3.9

Table 11:  $TARL_1$  values of the one-sided Shewhart RZ chart  $(Sh_{RZ}^-)$  and  $Sh_{RZ}^+)$  for  $z_0 = 1, \gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}, \gamma_X \neq \gamma_Y, \rho_0 \in \{-0.8, -0.4, 0.0, 0.4, 0.8\}, \rho_1 \neq \rho_0, n = \{1, 5, 7, 10, 15\}, \tau = \{0.9, 0.95, 0.98, 0.99, 1, 1.01, 1.02, 1.05, 1.1\}$  and  $TARL_0 = 10$ .

		$(\gamma_X$	$(\gamma_Y) = ($	(0.01, 0.2)			$(\gamma_X, \gamma_Y) = (0.2, 0.01)$			
au	n = 1	n = 5	n = 7	n = 10	n = 15	n = 1	n = 5	n = 7	n = 10	n = 15
					$\rho_0 = -$	$-0.4, \rho_1 = -0.2$				
0.90	7.5	4.3	3.5	2.7	2.0	9.1	5.8	4.7	3.5	2.3
0.95	9.0	7.7	7.2	6.5	5.5	9.6	8.5	8.0	7.3	6.4
0.98	9.7	9.3	9.2	9.0	8.7	9.9	9.6	9.4	9.3	9.0
0.99	9.9	9.7	9.7	9.6	9.5	10.0	9.8	9.8	9.7	9.6
1.00	10.0	10.0	10.0	10.0	10.0	10.1	10.1	10.1	10.1	10.1
1.01	10.0	9.8	9.8	9.7	9.6	9.9	9.7	9.7	9.6	9.5
1.02	9.9	9.6	9.4	9.3	9.0	9.7	9.3	9.2	9.0	8.8
1.05	9.7	8.6	8.1	7.5	6.6	9.1	7.8	7.3	6.7	5.8
1.10	9.2	6.3	5.3	4.1	2.8	7.8	4.9	4.0	3.1	2.3
					$ \rho_0 = - $	$-0.4, \rho_1 = -0.8$				
0.90	7.2	4.2	3.4	2.6	2.0	9.0	5.7	4.6	3.4	2.3
0.95	8.8	7.4	6.9	6.3	5.4	9.5	8.3	7.8	7.2	6.2
0.98	9.5	9.1	9.0	8.8	8.5	9.8	9.4	9.3	9.1	8.8
0.99	9.7	9.5	9.5	9.4	9.3	9.9	9.7	9.6	9.6	9.4
1.00	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9	9.9
1.01	9.9	9.7	9.6	9.6	9.4	9.7	9.5	9.5	9.4	9.3
1.02	9.8	9.4	9.3	9.1	8.9	9.5	9.1	9.0	8.8	8.5
1.05	9.6	8.4	8.0	7.3	6.4	8.8	7.6	7.1	6.5	5.6
1.10	9.1	6.2	5.1	4.0	2.8	7.5	4.7	3.9	3.1	2.3
					$\rho_0 =$	$0.4, \rho_1 = 0.2$				
0.90	7.1	4.0	3.2	2.5	1.8	9.0	5.5	4.4	3.2	2.2
0.95	8.8	7.4	6.8	6.1	5.2	9.6	8.3	7.8	7.1	6.1
0.98	9.5	9.1	9.0	8.8	8.5	9.8	9.4	9.3	9.1	8.8
0.99	9.7	9.6	9.5	9.4	9.3	9.9	9.7	9.7	9.6	9.5
1.00	10.0	10.0	10.0	10.0	10.0	9.9	9.9	9.9	9.9	9.9
1.01	9.9	9.7	9.7	9.6	9.5	9.7	9.6	9.5	9.4	9.3
1.02	9.8	9.5	9.3	9.1	8.9	9.5	9.2	9.0	8.8	8.5
1.05	9.6	8.4	7.9	7.3	0.3	8.9	7.5	7.0	6.4	5.4
1.10	9.1	6.1	5.0	3.8	2.6	7.4	4.5	3.7	2.9	2.1
0.00		4.1			$\frac{\rho_0}{1.0}$	$0.4, p_1 = 0.8$				
0.90	7.4	4.1	3.3	2.5	1.8	9.1	5.7	4.5	3.3	2.2
0.95	9.1	7.6	7.1	6.3	5.4	9.7	8.5	8.0	7.3	6.2
0.98	9.8	9.4	9.2	9.0	8.7	9.9	9.6	9.5	9.3	9.0
0.99	10.0	9.8	9.7	9.6	9.5	10.0	9.9	9.8	9.7	9.6
1.00	10.1	10.1	10.1	10.1	10.1	10.1	10.1	10.1	10.1	10.1
1.01	10.0	9.9	9.8	9.7	9.6	10.0	9.8	9.7	9.7	9.5
1.02	9.9	9.6	9.5	9.3	9.0	9.8	9.4	9.2	9.1	8.8 5.0
1.05	9.7	8.6	8.1	7.5	0.5 9.6	9.1	7.8	7.3	0.6	5.6
1.10	9.2	6.2	5.1	3.9	2.6	1.7	4.7	3.8	2.9	2.1

Table 12:  $TARL_1$  values of the one-sided Shewhart RZ chart  $(Sh_{RZ}^-)$  and  $Sh_{RZ}^+$ ) for  $z_0 = 1, \gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}, \gamma_X = \gamma_Y, \rho_0 \in \{-0.8, -0.4, 0.0, 0.4, 0.8\}, \rho_1 \neq \rho_0, n = \{1, 5, 7, 10, 15\}, \tau = \{0.9, 0.95, 0.98, 0.99, 1, 1.01, 1.02, 1.05, 1.1\}$  and  $TARL_0 = 30$ .

		$(\gamma_X$	$(\gamma_Y) = ($	0.01, 0.01)			$(\gamma_X, \gamma_Y) = (0.2, 0.2)$				
τ	n = 1	n = 5	n = 7	n = 10	n = 15	n = 1	n = 5	n = 7	n = 10	n = 15	
					$\rho_0 = -$	$-0.4, \rho_1 = -0.2$					
0.90	24.2	13.1	9.8	6.6	4.0	29.1	21.6	17.6	12.3	6.8	
0.95	28.3	25.2	23.8	21.7	18.5	29.6	27.8	26.8	25.3	22.6	
0.98	29.6	29.0	28.7	28.4	27.8	29.9	29.4	29.3	29.0	28.5	
0.99	29.9	29.6	29.5	29.4	29.3	30.0	29.8	29.7	29.6	29.5	
1.00	30.0	30.1	30.1	30.1	30.1	30.1	30.1	30.1	30.1	30.1	
1.01	30.0	29.8	29.7	29.6	29.5	29.9	29.6	29.5	29.4	29.3	
1.02	29.9	29.5	29.3	29.0	28.6	29.6	29.0	28.8	28.4	27.9	
1.05	29.7	28.0	27.1	25.7	23.3	28.4	25.6	24.3	22.5	19.5	
1.10	29.2	23.1	19.7	14.9	9.0	25.2	15.5	12.1	8.5	5.3	
					$\rho_0 = -$	$-0.4, \rho_1 = -0.8$					
0.90	23.0	12.3	9.2	6.3	3.9	28.9	20.9	16.7	11.6	6.6	
0.95	27.5	24.2	22.7	20.7	17.5	29.5	27.3	26.2	24.6	21.8	
0.98	29.0	28.4	28.1	27.7	27.1	29.8	29.2	28.9	28.6	28.1	
0.99	29.4	29.2	29.1	29.0	28.8	29.9	29.6	29.5	29.3	29.2	
1.00	29.9	29.9	29.9	29.9	29.9	29.7	29.8	29.8	29.8	29.8	
1.01	29.9	29.6	29.5	29.3	29.2	29.4	29.2	29.1	29.0	28.8	
1.02	29.8	29.2	29.0	28.6	28.2	29.1	28.4	28.2	27.8	27.2	
1.05	29.5	27.5	26.5	25.0	22.5	27.6	24.7	23.3	21.4	18.5	
1.10	29.0	22.4	18.9	14.1	8.6	24.0	14.5	11.3	8.1	5.1	
					$\rho_0 =$	$= 0.4, \rho_1 = 0.2$					
0.90	22.6	11.5	8.4	5.7	3.5	28.9	20.6	16.2	11.0	6.0	
0.95	27.5	24.0	22.5	20.2	16.9	29.5	27.3	26.2	24.5	21.5	
0.98	29.2	28.5	28.2	27.8	27.2	29.8	29.2	29.0	28.7	28.2	
0.99	29.5	29.3	29.2	29.1	28.9	29.9	29.6	29.5	29.4	29.2	
1.00	30.0	29.9	29.9	29.9	29.9	29.9	29.9	29.9	29.9	29.9	
1.01	29.9	29.6	29.5	29.4	29.2	29.5	29.3	29.2	29.1	28.9	
1.02	29.8	29.2	29.0	28.7	28.2	29.2	28.5	28.2	27.9	27.3	
1.05	29.6	27.5	26.5	24.9	22.3	27.7	24.5	23.1	21.0	17.9	
1.10	29.0	22.2	18.4	13.5	7.9	23.8	13.7	10.5	7.4	4.6	
					$\rho_0 =$	$= 0.4, \rho_1 = 0.8$					
0.90	24.1	12.3	9.0	6.0	3.6	29.1	21.4	17.1	11.6	6.3	
0.95	28.5	25.1	23.6	21.4	18.0	29.7	27.8	26.8	25.3	22.4	
0.98	29.8	29.1	28.8	28.5	27.9	29.9	29.5	29.3	29.1	28.6	
0.99	30.0	29.8	29.7	29.6	29.4	30.0	29.9	29.8	29.7	29.6	
1.00	30.1	30.1	30.1	30.1	30.1	30.3	30.2	30.2	30.2	30.2	
1.01	30.0	29.9	29.8	29.7	29.6	30.0	29.8	29.7	29.6	29.4	
1.02	29.9	29.5	29.4	29.1	28.7	29.8	29.1	28.9	28.5	28.0	
1.05	29.7	28.0	27.1	25.7	23.2	28.6	25.6	24.2	22.2	19.1	
1.10	29.2	23.0	19.4	14.3	8.4	25.1	14.8	11.3	7.8	4.8	

Table 13:  $TARL_1$  values of the one-sided Shewhart RZ chart  $(Sh_{RZ}^-)$  and  $Sh_{RZ}^+)$  for  $z_0 = 1, \gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}, \gamma_X \neq \gamma_Y, \rho_0 \in \{-0.8, -0.4, 0.0, 0.4, 0.8\}, \rho_1 \neq \rho_0, n = \{1, 5, 7, 10, 15\}, \tau = \{0.9, 0.95, 0.98, 0.99, 1, 1.01, 1.02, 1.05, 1.1\}$  and  $TARL_0 = 30$ .

		$(\gamma_X, \gamma_Y) = (0.01, 0.2)$					$(\gamma_X, \gamma_Y) = (0.2, 0.01)$					
au	n = 1	n = 5	n = 7	n = 10	n = 15	n = 1	n = 5	n = 7	n = 10	n = 15		
	$ \rho_0 = -0.4, \rho_1 = -0.2 $											
0.90	24.2	13.1	9.8	6.6	4.0	29.1	21.6	17.6	12.3	6.8		
0.95	28.3	25.2	23.8	21.7	18.5	29.6	27.8	26.8	25.3	22.6		
0.98	29.6	29.0	28.7	28.4	27.8	29.9	29.4	29.3	29.0	28.5		
0.99	29.9	29.6	29.5	29.4	29.3	30.0	29.8	29.7	29.6	29.5		
1.00	30.0	30.1	30.1	30.1	30.1	30.1	30.1	30.1	30.1	30.1		
1.01	30.0	29.8	29.7	29.6	29.5	29.9	29.6	29.5	29.4	29.3		
1.02	29.9	29.5	29.3	29.0	28.6	29.6	29.0	28.8	28.4	27.9		
1.05	29.7	28.0	27.1	25.7	23.3	28.4	25.6	24.3	22.5	19.5		
1.10	29.2	23.1	19.7	14.9	9.0	25.2	15.5	12.1	8.5	5.3		
					$ \rho_0 = -$	$-0.4, \rho_1 = -0.8$						
0.90	23.0	12.3	9.2	6.3	3.9	28.9	20.9	16.7	11.6	6.6		
0.95	27.5	24.2	22.7	20.7	17.5	29.5	27.3	26.2	24.6	21.8		
0.98	29.0	28.4	28.1	27.7	27.1	29.8	29.2	28.9	28.6	28.1		
0.99	29.4	29.2	29.1	29.0	28.8	29.9	29.6	29.5	29.3	29.2		
1.00	29.9	29.9	29.9	29.9	29.9	29.7	29.8	29.8	29.8	29.8		
1.01	29.9	29.6	29.5	29.3	29.2	29.4	29.2	29.1	29.0	28.8		
1.02	29.8	29.2	29.0	28.6	28.2	29.1	28.4	28.2	27.8	27.2		
1.05	29.5	27.5	26.5	25.0	22.5	27.6	24.7	23.3	21.4	18.5		
1.10	29.0	22.4	18.9	14.1	8.6	24.0	14.5	11.3	8.1	5.1		
					$\rho_0 =$	$= 0.4, \rho_1 = 0.2$						
0.90	22.6	11.5	8.4	5.7	3.5	28.9	20.6	16.2	11.0	6.0		
0.95	27.5	24.0	22.5	20.2	16.9	29.5	27.3	26.2	24.5	21.5		
0.98	29.2	28.5	28.2	27.8	27.2	29.8	29.2	29.0	28.7	28.2		
0.99	29.5	29.3	29.2	29.1	28.9	29.9	29.6	29.5	29.4	29.2		
1.00	30.0	29.9	29.9	29.9	29.9	29.9	29.9	29.9	29.9	29.9		
1.01	29.9	29.6	29.5	29.4	29.2	29.5	29.3	29.2	29.1	28.9		
1.02	29.8	29.2	29.0	28.7	28.2	29.2	28.5	28.2	27.9	27.3		
1.05	29.6	27.5	26.5	24.9	22.3	27.7	24.5	23.1	21.0	17.9		
1.10	29.0	22.2	18.4	13.5	7.9	23.8	13.7	10.5	7.4	4.6		
					$\rho_0 =$	$= 0.4, \rho_1 = 0.8$						
0.90	24.1	12.3	9.0	6.0	3.6	29.1	21.4	17.1	11.6	6.3		
0.95	28.5	25.1	23.6	21.4	18.0	29.7	27.8	26.8	25.3	22.4		
0.98	29.8	29.1	28.8	28.5	27.9	29.9	29.5	29.3	29.1	28.6		
0.99	30.0	29.8	29.7	29.6	29.4	30.0	29.9	29.8	29.7	29.6		
1.00	30.1	30.1	30.1	30.1	30.1	30.3	30.2	30.2	30.2	30.2		
1.01	30.0	29.9	29.8	29.7	29.6	30.0	29.8	29.7	29.6	29.4		
1.02	29.9	29.5	29.4	29.1	28.7	29.8	29.1	28.9	28.5	28.0		
1.05	29.7	28.0	27.1	25.7	23.2	28.6	25.6	24.2	22.2	19.1		
1.10	29.2	23.0	19.4	14.3	8.4	25.1	14.8	11.3	7.8	4.8		

Table 14:  $TARL_1$  values of the one-sided Shewhart RZ chart  $(Sh_{RZ}^-)$  and  $Sh_{RZ}^+$ ) for  $z_0 = 1, \gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}, \gamma_X = \gamma_Y, \rho_0 \in \{-0.8, -0.4, 0.0, 0.4, 0.8\}, \rho_1 \neq \rho_0, n = \{1, 5, 7, 10, 15\}, \tau = \{0.9, 0.95, 0.98, 0.99, 1, 1.01, 1.02, 1.05, 1.1\}$  and  $TARL_0 = 50$ .

		$(\gamma_X, \gamma_Y) = (0.01, 0.01)$					$(\gamma_X, \gamma_Y) = (0.2, 0.2)$					
au	n = 1	n = 5	n = 7	n = 10	n = 15	n = 1	n = 5	n = 7	n = 10	n = 15		
	$\rho_0 = -0.4, \rho_1 = -0.2$											
0.90	41.9	22.8	16.5	10.6	6.0	49.1	39.4	32.8	23.3	12.3		
0.95	47.9	43.6	41.5	38.3	33.0	49.7	47.5	46.3	44.3	40.4		
0.98	49.6	48.8	48.5	48.1	47.4	49.9	49.4	49.2	48.9	48.4		
0.99	49.9	49.6	49.5	49.4	49.2	50.0	49.8	49.7	49.6	49.4		
1.00	50.0	50.1	50.1	50.1	50.1	50.2	50.1	50.1	50.1	50.1		
1.01	50.0	49.8	49.7	49.6	49.4	49.9	49.6	49.5	49.4	49.2		
1.02	49.9	49.4	49.2	48.9	48.4	49.6	48.8	48.5	48.1	47.5		
1.05	49.7	47.7	46.6	44.8	41.4	48.1	44.2	42.3	39.5	34.7		
1.10	49.2	41.5	36.3	28.0	16.7	43.4	27.2	21.0	14.2	8.2		
					$ \rho_0 = - $	$-0.4, \rho_1 = -0.8$						
0.90	39.6	20.9	15.2	9.9	5.7	48.9	38.0	31.2	21.8	11.5		
0.95	46.7	41.9	39.6	36.3	30.9	49.5	46.9	45.4	43.1	39.0		
0.98	48.8	48.0	47.6	47.1	46.3	49.8	49.1	48.8	48.4	47.8		
0.99	49.3	49.0	48.9	48.7	48.5	49.9	49.5	49.4	49.2	49.0		
1.00	49.9	49.8	49.8	49.8	49.8	49.6	49.7	49.7	49.7	49.7		
1.01	49.9	49.5	49.4	49.2	49.0	49.3	49.0	48.9	48.8	48.5		
1.02	49.8	49.1	48.8	48.4	47.8	48.8	48.0	47.7	47.2	46.4		
1.05	49.5	47.1	45.8	43.8	40.0	46.9	42.6	40.5	37.5	32.6		
1.10	49.0	40.3	34.7	26.4	15.6	41.2	25.1	19.2	13.2	7.8		
					$\rho_0 =$	$0.4, \rho_1 = 0.2$						
0.90	39.1	19.4	13.7	8.8	5.1	49.0	37.7	30.5	20.6	10.5		
0.95	46.8	41.7	39.2	35.6	29.9	49.6	46.9	45.5	43.1	38.6		
0.98	49.0	48.1	47.8	47.2	46.4	49.8	49.1	48.9	48.5	47.8		
0.99	49.4	49.2	49.0	48.9	48.6	49.9	49.6	49.5	49.3	49.1		
1.00	50.0	49.9	49.9	49.9	49.9	49.8	49.9	49.9	49.9	49.9		
1.01	49.9	49.6	49.5	49.3	49.1	49.4	49.2	49.1	48.9	48.7		
1.02	49.8	49.2	48.9	48.5	47.9	49.0	48.2	47.8	47.3	46.5		
1.05	49.6	47.2	45.8	43.7	39.8	47.0	42.4	40.2	37.0	31.7		
1.10	49.1	40.0	34.2	25.4	14.4	40.9	23.7	17.7	11.8	6.9		
					$\rho_0 =$	$0.4, \rho_1 = 0.8$						
0.90	41.7	21.4	15.0	9.4	5.3	49.2	39.2	32.3	22.2	11.2		
0.95	48.2	43.6	41.4	37.9	32.2	49.7	47.6	46.4	44.3	40.3		
0.98	49.8	49.0	48.7	48.2	47.5	50.0	49.5	49.3	49.0	48.5		
0.99	50.1	49.8	49.7	49.5	49.3	50.0	49.9	49.8	49.7	49.5		
1.00	50.1	50.2	50.2	50.2	50.2	50.3	50.3	50.3	50.2	50.2		
1.01	50.0	49.9	49.8	49.7	49.6	50.1	49.8	49.7	49.5	49.3		
1.02	50.0	49.5	49.3	49.0	48.5	49.8	49.0	48.7	48.3	47.6		
1.05	49.7	47.8	46.7	44.9	41.3	48.3	44.3	42.3	39.2	34.0		
1.10	49.3	41.4	35.9	27.1	15.5	43.3	26.0	19.5	12.9	7.3		

Table 15:  $TARL_1$  values of the one-sided Shewhart RZ chart  $(Sh_{RZ}^-)$  and  $Sh_{RZ}^+$ ) for  $z_0 = 1, \gamma_X \in \{0.01, 0.2\}, \gamma_Y \in \{0.01, 0.2\}, \gamma_X \neq \gamma_Y, \rho_0 \in \{-0.8, -0.4, 0.0, 0.4, 0.8\}, \rho_1 \neq \rho_0, n = \{1, 5, 7, 10, 15\}, \tau = \{0.9, 0.95, 0.98, 0.99, 1, 1.01, 1.02, 1.05, 1.1\}$  and  $TARL_0 = 50$ .

		$(\gamma_X, \gamma_Y) = (0.01, 0.2)$					$(\gamma_X, \gamma_Y) = (0.2, 0.01)$					
τ	n = 1	n = 5	n = 7	n = 10	n = 15	n = 1	n = 5	n = 7	n = 10	n = 15		
					$\rho_0 = -$	$-0.4, \rho_1 = -0.2$						
0.90	41.9	22.8	16.5	10.6	6.0	49.1	39.4	32.8	23.3	12.3		
0.95	47.9	43.6	41.5	38.3	33.0	49.7	47.5	46.3	44.3	40.4		
0.98	49.6	48.8	48.5	48.1	47.4	49.9	49.4	49.2	48.9	48.4		
0.99	49.9	49.6	49.5	49.4	49.2	50.0	49.8	49.7	49.6	49.4		
1.00	50.0	50.1	50.1	50.1	50.1	50.2	50.1	50.1	50.1	50.1		
1.01	50.0	49.8	49.7	49.6	49.4	49.9	49.6	49.5	49.4	49.2		
1.02	49.9	49.4	49.2	48.9	48.4	49.6	48.8	48.5	48.1	47.5		
1.05	49.7	47.7	46.6	44.8	41.4	48.1	44.2	42.3	39.5	34.7		
1.10	49.2	41.5	36.3	28.0	16.7	43.4	27.2	21.0	14.2	8.2		
					$ \rho_0 = -$	$-0.4, \rho_1 = -0.8$						
0.90	39.6	20.9	15.2	9.9	5.7	48.9	38.0	31.2	21.8	11.5		
0.95	46.7	41.9	39.6	36.3	30.9	49.5	46.9	45.4	43.1	39.0		
0.98	48.8	48.0	47.6	47.1	46.3	49.8	49.1	48.8	48.4	47.8		
0.99	49.3	49.0	48.9	48.7	48.5	49.9	49.5	49.4	49.2	49.0		
1.00	49.9	49.8	49.8	49.8	49.8	49.6	49.7	49.7	49.7	49.7		
1.01	49.9	49.5	49.4	49.2	49.0	49.3	49.0	48.9	48.8	48.5		
1.02	49.8	49.1	48.8	48.4	47.8	48.8	48.0	47.7	47.2	46.4		
1.05	49.5	47.1	45.8	43.8	40.0	46.9	42.6	40.5	37.5	32.6		
1.10	49.0	40.3	34.7	26.4	15.6	41.2	25.1	19.2	13.2	7.8		
					$\rho_0 =$	$0.4, \rho_1 = 0.2$						
0.90	39.1	19.4	13.7	8.8	5.1	49.0	37.7	30.5	20.6	10.5		
0.95	46.8	41.7	39.2	35.6	29.9	49.6	46.9	45.5	43.1	38.6		
0.98	49.0	48.1	47.8	47.2	46.4	49.8	49.1	48.9	48.5	47.8		
0.99	49.4	49.2	49.0	48.9	48.6	49.9	49.6	49.5	49.3	49.1		
1.00	50.0	49.9	49.9	49.9	49.9	49.8	49.9	49.9	49.9	49.9		
1.01	49.9	49.6	49.5	49.3	49.1	49.4	49.2	49.1	48.9	48.7		
1.02	49.8	49.2	48.9	48.5	47.9	49.0	48.2	47.8	47.3	46.5		
1.05	49.6	47.2	45.8	43.7	39.8	47.0	42.4	40.2	37.0	31.7		
1.10	49.1	40.0	34.2	25.4	14.4	40.9	23.7	17.7	11.8	6.9		
					$\rho_0 =$	$= 0.4, \rho_1 = 0.8$						
0.90	41.7	21.4	15.0	9.4	5.3	49.2	39.2	32.3	22.2	11.2		
0.95	48.2	43.6	41.4	37.9	32.2	49.7	47.6	46.4	44.3	40.3		
0.98	49.8	49.0	48.7	48.2	47.5	50.0	49.5	49.3	49.0	48.5		
0.99	50.1	49.8	49.7	49.5	49.3	50.0	49.9	49.8	49.7	49.5		
1.00	50.1	50.2	50.2	50.2	50.2	50.3	50.3	50.3	50.2	50.2		
1.01	50.0	49.9	49.8	49.7	49.6	50.1	49.8	49.7	49.5	49.3		
1.02	50.0	49.5	49.3	49.0	48.5	49.8	49.0	48.7	48.3	47.6		
1.05	49.7	47.8	46.7	44.9	41.3	48.3	44.3	42.3	39.2	34.0		
1.10	49.3	41.4	35.9	27.1	15.5	43.3	26.0	19.5	12.9	7.3		

normal variables in a long production run context and will be adapted, in this paper, to a short production run context. This example considers a real quality control problem from the food industry but with the simulation data. A muesli brand recipe is produced by using a mixture of several ingredients including sunflower oil, wildflower honey, seeds (pumpkin, flaxseeds, sesame, poppy), coconut milk powder and rolled oats. To meet the food's nutrient composition requirements declared in the brand packaging label and to preserve the mixture taste, the recipe calls for equal weights of "pumpkin seeds" and "flaxseeds". Furthermore, their nominal proportions to the total weight of box content are both fixed at  $p_p = p_f = 0.1$ . To satisfy the needs of customers, the brand boxes are manufactured in different sizes. According to Celano et al.<sup>5</sup>, whichever is the package dimension, the quality practitioner wants to perform on-line SPC monitoring at regular intervals i = 1, 2, ... to check deviations from the in-control ratio  $z_0 = \frac{\mu_{p,i}}{\mu_{f,i}} = \frac{0.1}{0.1} = 1$  due to problems occurring at the dosing machine. Here,  $\mu_{p,i}$  and  $\mu_{f,i}$  are the mean weights for "pumpkin seeds" and "flaxseeds", respectively. The quality practitioner collects a sample of n = 5 boxes every 60 minutes. Because the box size is allowed to change from one sample to another, it is possible to have  $\mu_{p,i} \neq \mu_{p,k}$  and  $\mu_{f,i} \neq \mu_{f,k}$ ,  $\forall i \neq k$ . In the quality control laboratory, a mechanical procedure separates the "pumpkin seeds" and "flaxseeds" from the muesli mixture filling each box and the sample average weights  $\bar{W}_{p,i} = \frac{1}{n} \sum_{j=1}^{n} W_{p,i,j}$  and  $\bar{W}_{f,i} = \frac{1}{n} \sum_{j=1}^{n} W_{f,i,j}$  are recorded. Finally, the ratio  $\hat{Z}_i = \frac{\bar{W}_{p,i}}{W_{f,i}}$  is computed. For this example, like in Celano et al.<sup>5</sup>, for  $i = 1, 2, \ldots$ , and  $j = 1, 2, \ldots, n$  both  $W_{p,i,j}$  and  $W_{f,i,j}$  can be well approximated as normal variables with constant coefficients of variation  $\gamma_p = 0.02$  and  $\gamma_f = 0.01$ , i.e.  $W_{p,i,j} \sim N(\mu_{p,i}, 0.02 \times \mu_{p,i})$  and  $W_{f,i,j} \sim N(\mu_{f,i}, 0.01 \times \mu_{f,i})$ . Moreover, the in-control correlation coefficient between these two variables is  $\rho_0 = 0.8$ . The process engineer has decided to implement the  $\mathcal{S}h_{RZ}^+$  chart in order to monitor the ratio for a short run production of H = 16 hours calling for I = 15 inspections, i.e. an inspection every hour.

For n = 5 and  $\rho_0 = 0.8$ , the control limit of the  $Sh_{RZ}^+$  control chart to potentially detect unexpected increase in the ratio for a short run production is UCL = 1.01421. Table -16 shows the set of simulated sample data collected from the process (based on Celano et al.<sup>5</sup>), the corresponding box sizes 250–500 gr, and the  $\hat{Z}_i$  statistic. The process is assumed to run in-control up to sample #10. Then, between samples #10 and #11, Celano et al.<sup>5</sup> have simulated the occurrence of an assignable cause shifting  $z_0 = 1$  to  $z_1 = 1.01 \times z_0$ , i.e. a ratio percentage increase equal to 1%. Figure 2 shows the  $Sh_{RZ}^+$  control chart, which signals the occurrence of the out-of-control condition by plotting point #11 above the control limit  $UCL^+ = 1.01421$  (see also bold values in Table -16). The process is allowed to continue, while corrective actions are started by the repair crew who find and eliminate the assignable cause after sample #14 and restore the process back to the in-control condition.

Sample	Box Size			Wfii [gr	1		$\bar{W}_{f,i}$ [gr]	$\hat{Z}_i = \frac{\bar{W}_i}{\bar{W}_i}$
1	250 gr	25 479	25 355	24 027	25 792	24.960	25 122	1 003
1	200 gi	25.415	25.300 25.171	24.021	25.152	24.500 25.107	25.122	1.005
2	250 gr	25.359	25.172	24.508	25.292	24.449	24.956	1.003
	8-	25.211	25.115	24.679	24.933	24.831	24.954	
3	250  gr	24.574	24.864	25.865	25.107	24.811	25.044	1.005
		24.784	24.868	25.377	24.879	24.734	24.929	
4	250  gr	25.313	24.483	24.088	25.184	25.681	24.950	0.999
		25.338	24.859	24.305	25.115	25.251	24.974	
5	$250 \ \mathrm{gr}$	25.557	24.959	25.023	24.482	25.531	25.111	0.998
		25.277	25.402	25.012	24.937	25.148	25.163	
6	250  gr	24.882	24.473	24.814	25.418	24.732	24.864	0.997
		24.962	24.644	24.817	25.419	24.818	24.932	
7	500  gr	49.848	48.685	49.994	49.910	49.374	49.562	0.999
		49.993	49.128	49.830	49.566	49.422	49.588	
8	500  gr	49.668	50.338	49.149	47.807	49.064	49.205	0.990
		49.695	50.681	49.640	48.969	49.612	49.720	
9	500  gr	51.273	48.303	48.510	50.594	48.591	49.454	0.993
		50.366	49.210	49.844	49.890	49.595	49.781	
10	500  gr	48.720	51.566	49.677	50.651	50.344	50.192	1.002
		49.721	50.215	50.178	50.324	50.071	50.102	
11	500  gr	51.372	51.700	51.000	50.886	49.641	50.920	1.017
		50.164	50.272	49.884	50.061	49.845	50.045	
12	500  gr	52.020	53.182	51.374	51.342	48.771	51.138	1.023
		50.749	50.369	49.697	49.575	49.440	49.966	
13	500  gr	52.360	49.412	50.704	50.370	50.901	50.949	1.016
		50.047	49.981	50.297	50.408	50.026	50.152	
14	500  gr	52.498	50.447	48.713	48.574	50.275	50.101	1.008
		50.064	50.124	49.162	48.865	50.344	49.712	
15	250  gr	25.123	24.658	24.468	25.030	25.071	24.870	0.996
	-	25.041	24.790	24.835	25.211	25.008	24.977	

Table 16: The food industry example data



Figure 1: The  $\mathcal{S}h^+_{RZ}$  control chart for the food industry example

#### 7 Conclusion and Recommendations

In this article we examined the statistical performance of two one-sided Shewhart charts  $(Sh_{RZ}^-$  and  $Sh_{RZ}^+$ ) in monitoring the ratio of two normal variables using truncated average run length as a performance measure in short production runs. For practical consideration of quality experts, we have presented the probability limits and TARL values of both charts by varying the number of inspections. The sample size(n) and the number of inspections(M) affect the width of the control limits. Quality practitioners maybe adjust control limits according to the requirement of the production process. We observed the TARL performance of the both designs at fixed values  $n, \rho_0, \rho_1, \gamma_X, \gamma_Y, \tau, Z_0$  at prespecified  $TARL_0 = 10, 30 \& 50$ . The main conclusions maybe drive from results. The performance of chart one-sided Shewhart charts  $(Sh_{RZ}^-$  and  $Sh_{RZ}^+)$  is depend on the values  $n, \gamma_X, \gamma_Y$  and  $\rho_0$ . When shift size increase or decrease the values of TRL increase or decrease accordingly. There are several extensions for future research like one-sided EWMA type and CUSUM type ratio chart for short production runs.

#### References

- Amdouni, A., Castagliola, P., Taleb, H. and Celano, G. 2015, 'Monitoring the coefficient of variation using a variable sample size control chart in short production runs', *The International Journal of Advanced Manufacturing Technology* 81(1-4), 1–14.
- [2] Castagliola, P., Amdouni, A., Taleb, H. and Celano, G. 2015, 'One-sided shewhart-type charts for monitoring the coefficient of variation in short production runs', *Quality Technology & Quantitative Management* 12(1), 53– 67.
- [3] Castagliola, P., Celano, G., Fichera, S. and Nenes, G. 2013, 'The variable sample size t control chart for monitoring short production runs', *The International Journal of Advanced Manufacturing Technology* 66(9-12), 1353–1366.
- [4] Celano, G. and Castagliola, P. 2016, 'Design of a phase ii control chart for monitoring the ratio of two normal variables', *Quality and Reliability Engineering International* 32(1), 291–308.
- [5] Celano, G., Castagliola, P., Faraz, A. and Fichera, S. 2014, 'Statistical Performance of a Control Chart for Individual Observations Monitoring the Ratio of two Normal Variables', *Quality and Reliability Engineering International* **30**(8), 1361–1377.
- [6] Celano, G., Castagliola, P. and Trovato, E. 2012, 'The economic performance of a cusum t control chart for monitoring short production runs', *Quality Technology & Quantitative Management* 9(4), 329–354.

- [7] Del Castillo, E. and Montgomery, D. 1993, 'Optimal design of control charts for monitoring short production runs', *Economic Quality Control* 8(4), 225– 240.
- [8] Del Castillo, E. and Montgomery, D. C. 1996, 'A general model for the optimal economic design of x<sup>-</sup> charts used to control short or long run processes', *IIE Transactions (Institute of Industrial Engineers)* 28(3), 193– 201.
- [9] Khatun, M., Khoo, M. B., Lee, M. H. and Castagliola, P. 2019, 'One-sided control charts for monitoring the multivariate coefficient of variation in short production runs', *Transactions of the Institute of Measurement and Control* 41(6), 1712–1728.
- [10] Khoo, M. B., Saha, S., Teh, S. Y., Haq, A. and Lee, H. C. 2020, 'The median control chart for process monitoring in short production runs', *Communi*cations in Statistics-Simulation and Computation pp. 1–16.
- [11] Ladany, S. P. 1973, 'Optimal use of control charts for controlling current production', *Management Science* 19(7), 763–772.
- [12] Ladany, S. P. and Bedi, D. N. 1976, 'Selection of the optimal setup policy', Naval Research Logistics Quarterly 23(2), 219–233.
- [13] Naseri, H., Najafi, S. E. and Saghaei, A. 2020, 'Statistical process control (spc) for short production run with cauchy distribution, a case study with corrected numbers approach', *Communications in Statistics-Theory and Methods* 49(4), 879–893.
- [14] Nenes, G. and Tagaras, G. 2006, 'The economically designed cusum chart for monitoring short production runs', *International Journal of Production Research* 44(8), 1569–1587.
- [15] Nenes, G. and Tagaras, G. 2010, 'Evaluation of cusum charts for finitehorizon processes', Communications in Statistics—Simulation and Computation (R) 39(3), 578–597.
- [16] Nguyen, H. D., Tran, K. P. and Heuchenne, C. 2019, 'Monitoring the ratio of two normal variables using variable sampling interval exponentially weighted moving average control charts', *Quality and Reliability Engineer*ing International **35**(1), 439–460.
- [17] Nguyen, H. D., Tran, K. P. and Heuchenne, H. L. 2020, 'Cusum control charts with variable sampling interval for monitoring the ratio of two normal variables', *Quality and Reliability Engineering International* 36(2), 474–497.
- [18] Nguyen, H. and Tran, K. 2020, 'Effect of the measurement errors on two one-sided shewhart control charts for monitoring the ratio of two normal variables', *Quality and Reliability Engineering International*.

- [19] Nguyen, H., Tran, K. and Goh, T. 2020, 'Variable sampling interval control charts for monitoring the ratio of two normal variables', *Journal of Testing* and Evaluation 48(3).
- [20] Shewhart, W. 1931, Economic Control of Quality of Manufactured Product, Van Nostrand, New York.
- [21] Tagaras, G. 1996, 'Dynamic control charts for finite production runs', European Journal of Operational Research 91(1), 38–55.
- [22] Tran, K. P., Castagliola, P. and Celano, G. 2016a, 'Monitoring the ratio of two normal variables using run rules type control charts', *International Journal of Production Research* 54(6), 1670–1688.
- [23] Tran, K. P., Castagliola, P. and Celano, G. 2016b, 'The performance of the shewhart-rz control chart in the presence of measurement error', *Interna*tional Journal of Production Research 54(24), 7504–7522.
- [24] Tran, K. P., Castagliola, P. and Celano, G. 2018, 'Monitoring the ratio of population means of a bivariate normal distribution using cusum type control charts', *Statistical Papers* **59**(1), 387–413.
- [25] Tran, K. P. and Knoth, S. 2018, 'Steady-state arl analysis of arl-unbiased ewma-rz control chart monitoring the ratio of two normal variables', *Qual*ity and Reliability Engineering International 34(3), 377–390.