

The Unconditional Performance of Control Charts for Zero-Inflated Processes with Estimated Parameters

¹Athanasios C. RAKITZIS *, ²Eftychia MAMZERIDOU, ³Petros E. MARAVELAKIS

¹Department of Statistics and Insurance Science, University of Piraeus, Piraeus 18534, Greece.

²Department of Statistics and Actuarial-Financial Mathematics, University of the Aegean, Karlovasi 83200, Samos, Greece.

³Department of Business Administration, University of Piraeus, Piraeus 18534, Greece.

Abstract

Control charts for zero-inflated processes have attracted the interest of the researchers in the recent years. In this work we investigate the performance of Shewhart-type charts for zero-inflated Poisson and zero-inflated Binomial processes, in the case of estimated parameters. This is a case that usually occurs in practice, especially prior to starting the process monitoring. Using Monte Carlo simulation we evaluate charts' performance under an unconditional perspective and provide guidelines for their use in practice. We examine both the in-control and the out-of-control performance.

Keywords: Moment estimators, Maximum likelihood estimators, Unconditional run length distribution, zero-inflated binomial distribution, zero-inflated Poisson distribution.

1 Introduction

Control charts are the main tool of Statistical Process Control (SPC) and can be used for monitoring a process in order to detect changes in it. Walter A. Shewhart (Shewhart (1926)) was the first who proposed the use of control charts, back in the 1920's. The most common and often used are the Shewhart-type charts because of their ease in design and interpretation. Two main categories of control charts are the variables charts and the attributes charts. Control charts for variables are used when the quality characteristic X (random variable, r.v.) follows a continuous distribution while if X follows a discrete distribution then the respective chart is a control chart for attributes. Control charts for attributes are used for process monitoring when the data collected by the process are counts. For example, attributes control charts are used for monitoring the number of non-conforming items in a sample, the number of non-conformities in

*Corresponding author. E-mail address: arakitz@unipi.gr.

This is an original manuscript of an article that will be published by Taylor & Francis in *Statistical Methods and Applications in Systems Assurance & Quality* of the Book Series *Advanced Research in Reliability and System Assurance*

each inspected unit, the number of new daily infections in a specific region or the daily number of logins in the computers of a workstation.

The np - and c -chart are two common Shewhart-type attributes charts. The first is used when X is a binomial random variable (such as the number of non-conforming items in the sample) while the second is used when X is a Poisson random variable (such as the number of emergency calls in a hospital during the night shift). See Montgomery (2009) for the basic properties of the np - and c -chart.

However, there are several processes where the np - and c -chart cannot be used for their monitoring because the distributional assumption of the binomial and the Poisson distribution is violated. For example, when there is overdispersion in the data or if there is an excessive number of zero values (or, sometimes, both). Therefore, practitioners have to select first the model that fits better their data and then develop a control chart based on this model.

Zero-inflated models (see Johnson et al. (2005), pp. 351-356) have been recommended as alternative models that take into account the excessive number of zeros as well as the overdispersion that is caused by them. This excess in zeros is attributed to the technological progress and automation of manufacturing technology which led to high-quality (or high-yield) processes; processes with a very low probability of non-conforming items or with a very low rate in the occurrence of non-conforming items. A zero value occurs when there are no non-conforming items in a sample or no non-conformities in the inspected unit.

In recent years, there has been an increased interest in control charts for monitoring zero-inflated processes. See the recent overview by Mahmood and Xie (2019). However, the majority of these works is about control charts for Phase II monitoring, where the basic assumption is the values of the process parameters are known. This is a strong assumption which rarely (if ever) is met in practice. According to Montgomery (2009) (see also Jensen et al. (2006)) there is significant difference between the theoretical and the actual performance of a control chart, which is attributed to the presence of estimation error. With the term theoretical we refer to the case where process parameters are known (or Case K) while the term actual performance refers to the case where the process parameters are unknown and must be estimated (Case U). Albers et al. (2004) discriminated the estimation error into two distinct sources, namely *model error* and *stochastic error*. The first is caused by incorrect model assumptions (e.g. the true distributional model is much different than the selected one) while the latter is due to estimation uncertainty and is related to the selected Phase I sample. In this work the focus is solely on the stochastic (estimation) error. He et al. (2003) where the first who studied the estimation effect on the performance of a Shewhart-type control chart for monitoring a zero-inflated Poisson process. Rakitzis and Castagliola (2016) extended the work of He et al. (2003) and studied also the performance of a Shewhart-type chart for monitoring a zero-inflated binomial process. Both works assume that only one of the two parameters of these zero-inflated processes

is unknown. Recently, Mamzeridou and Rakitzis (2023) investigated the performance of an upper one-sided Shewhart chart for monitoring a zero-inflated Poisson process, in the case where both process parameters are unknown.

In this work we consider two popular zero-inflated models (namely, the zero-inflated Poisson and the zero-inflated binomial distribution) and study the statistical design and performance of the corresponding Shewhart-type charts in Case U. It should be mentioned that control charts for monitoring a zero-inflated binomial process in Case U have not been considered so far. In addition, we consider two estimation methods, maximum likelihood estimation (MLE) and method of moments (MoM), while the proposed chart is two-sided with Shewhart-type limits, instead of probability limits. The main difference with the work of Mamzeridou and Rakitzis (2023) is that in this work we evaluate the performance of the charts in Case U from a different perspective. Thus, different performance measures are used. This will be explained later.

The structure of this paper is: In Section 2 we provide, in brief, the basic properties of the Shewhart charts for monitoring a zero-inflated Poisson (Section 2.1) and a zero-inflated binomial (Section 2.2) process, in the case of known parameters (Case K), along with the appropriate measures for their performance (Section 2.3). In Section 3, we describe the implementation of the charts in Case U, for each of the considered processes, providing also the estimators under each case. Using these estimates we derive the basic properties of the considered Shewhart charts in the case of estimated parameters. Also, we present the steps for designing the charts as well as the appropriate performance measures, under an unconditional perspective. In Section 4 we present the findings of a simulation study regarding the in-control (IC) and the out-of-control (OOC) performance of the considered charts in Case U. The results in the case of monitoring a ZIP process are given in Section 4.1 while in Section 4.2 we provide the results in the case of a ZIB process. A brief discussion on the OOC performance of the charts is given in Section 5 while conclusions are summarized in Section 6.

2 Shewhart Charts for Monitoring ZIP and ZIB Processes

2.1 The Shewhart Chart for ZIP Processes (Case K)

The zero-inflated Poisson (ZIP) distribution is a generalization of the Poisson distribution that can be used to model count data containing an excessive number of zeros. By definition, if X is a ZIP random variable, it is defined on $\{0, 1, \dots\}$ (as for the standard Poisson distribution) and its probability mass function (p.m.f.) is given by

$$f_{ZIP}(x|\phi, \lambda) = \begin{cases} \phi + (1 - \phi) f_P(0|\lambda), & x = 0 \\ (1 - \phi) f_P(x|\lambda), & x = 1, 2, \dots \end{cases}, \quad (1)$$

where $f_P(x|\lambda)$ is the p.m.f. of the standard Poisson distribution with parameter $\lambda > 0$ and $\phi \in [0, 1]$ is the zero-inflation parameter. If $\phi = 0$, then the ZIP distribution coincides with the standard Poisson distribution. If $\phi = 1$, then the ZIP distribution reduces to the Dirac distribution on $x = 0$. Moreover, it is not difficult to verify that the cumulative distribution function (c.d.f.) of X is given by:

$$F_{ZIP}(x|\phi, \lambda) = \phi + (1 - \phi)F_P(x|\lambda), \quad (2)$$

where $F_P(x|\lambda)$ is the c.d.f. of the Poisson distribution with parameter λ . The mean and the variance of the ZIP distribution with parameters (ϕ, λ) are, respectively, given by

$$E(X) = \lambda(1 - \phi), \quad V(X) = \lambda(1 + \lambda\phi)(1 - \phi). \quad (3)$$

Let us now assume that we want to set-up a Shewhart control chart for monitoring a ZIP process. In the case of known parameters (Case K), the upper and the lower control limits (denoted as UCL_{ZIP} , LCL_{ZIP} , respectively) are given by (see, for example, Rakitzis and Castagliola (2016), page 4196):

$$UCL_{ZIP} = \left\lfloor \lambda_0(1 - \phi_0) + L\sqrt{\lambda_0(1 + \lambda_0\phi_0)(1 - \phi_0)} \right\rfloor, \quad (4)$$

$$LCL_{ZIP} = \max\left(0, \left\lceil \lambda_0(1 - \phi_0) - L\sqrt{\lambda_0(1 + \lambda_0\phi_0)(1 - \phi_0)} \right\rceil\right), \quad (5)$$

where $\lfloor \dots \rfloor$ and $\lceil \dots \rceil$ denote the rounded down and rounded up integer, ϕ_0, λ_0 are the in-control values of the process parameters ϕ and λ , while $L > 0$ is a constant that plays the role of chart's design parameter. These limits are also known as *Shewhart-type* or $L\sigma$ limits. It should be noted that in Mamzeridou and Rakitzis (2023) the authors used only one probability limit and not Shewhart-type limits. Also, given ϕ_0 and λ_0 , the value of L determines the limits of the interval $[LCL_{ZIP}, UCL_{ZIP}]$. Thus, it is directly related to the false alarm rate (FAR) of the chart. Recall that the FAR is the probability for the chart to give an OOC signal when the process is actually IC. The largest the L the smallest the FAR.

Let Y_1, Y_2, \dots be independent random variables such that $Y_i \sim ZIP(\phi_1, \lambda_1)$, i.e. a ZIP distribution with parameters (ϕ_1, λ_1) , where, in general, $\phi_1 \neq \phi_0$, $\lambda_1 \neq \lambda_0$ and $\phi_1 \in [0, 1]$, $\lambda_1 > 0$. If $\phi_1 = \phi_0$ and $\lambda_1 = \lambda_0$, then the process is IC, otherwise it is OOC. Then, the probability β which is the probability that the number Y_i of non-conformities is within the interval $[LCL_{ZIP}, UCL_{ZIP}]$ equals

$$\begin{aligned} \beta &= P(LCL_{ZIP} \leq Y_i \leq UCL_{ZIP}) \\ &= F_{ZIP}(UCL_{ZIP}|\phi_1, \lambda_1) - F_{ZIP}(LCL_{ZIP} - 1|\phi_1, \lambda_1) \end{aligned} \quad (6)$$

2.2 The Shewhart Chart for ZIB Processes (Case K)

The zero-inflated binomial (ZIB) distribution is a generalization of the binomial distribution that takes into account the excessive number of zeros, compared to the usual binomial distribution. By definition, if X is a ZIB random variable, it is defined on $\{0, 1, \dots, n\}$ (same as the binomial distribution) and its p.m.f. is given by

$$f_{ZIB}(x | \phi, n, p) = \begin{cases} \phi + (1 - \phi) f_B(0 | n, p), & x = 0 \\ (1 - \phi) f_B(x | n, p), & x = 1, 2, \dots, n \end{cases}, \quad (7)$$

where $f_B(x | n, p)$ is the p.m.f. of the binomial distribution $B(n, p)$ with parameters $n \in \{1, 2, \dots\}$ and $p \in (0, 1)$. Parameter p is the success probability (i.e. the probability of an item being non-conforming) while ϕ is the zero-inflation parameter. If $\phi = 0$, the ZIB distribution coincides with the binomial distribution with parameters n and p while, for $\phi = 1$, the ZIB distribution reduces to the Dirac distribution on $x = 0$. The c.d.f. of X is given by

$$F_{ZIB}(x | \phi, n, p) = \phi + (1 - \phi) F_B(x | n, p), \quad (8)$$

where $F_B(x | n, p)$ is the c.d.f. of $B(n, p)$. The mean and the variance of the ZIB distribution with parameters (ϕ, n, p) are, respectively, given by the following two expressions

$$E(X) = np(1 - \phi), \quad V(X) = np(1 - p + np\phi)(1 - \phi). \quad (9)$$

In a similar manner, the control limits of a the Shewhart chart for monitoring a ZIB process with known parameters are given by (see, for example, Rakitzis and Castagliola (2016), page 4196):

$$UCL_{ZIB} = \left\lceil np_0(1 - \phi_0) + L\sqrt{np_0(1 - p_0 + np_0\phi_0)(1 - \phi_0)} \right\rceil, \quad (10)$$

$$LCL_{ZIB} = \max \left(0, \left\lceil np_0(1 - \phi_0) - L\sqrt{np_0(1 - p_0 + np_0\phi_0)(1 - \phi_0)} \right\rceil \right), \quad (11)$$

where ϕ_0, p_0 are the in-control values of process parameters ϕ and p , while constant $L > 0$ is the chart's design parameter. Let Y_1, Y_2, \dots be independent random variables with $Y_i \sim ZIB(\phi_1, n, p_1)$, i.e., the number of non-conforming units in a sample of size n is a ZIB random variable with parameters (ϕ_1, n, p_1) . Again, in general, $\phi_1 \neq \phi_0$ and $p_1 \neq p_0$ with $\phi_1 \in [0, 1]$ and $p_1 \in (0, 1)$. If $\phi_1 = \phi_0$ and $p_1 = p_0$ the process is IC, otherwise it is OOC. Then, the probability β which is the probability that the number Y_i of non-conforming

items is within the interval $[LCL_{ZIB}, UCL_{ZIB}]$ equals

$$\begin{aligned}\beta &= P(LCL_{ZIB} \leq Y_i \leq UCL_{ZIB}) \\ &= F_{ZIB}(UCL_{ZIP} | \phi_1, n, p_1) - F_{ZIP}(LCL_{ZIP} - 1 | \phi_1, n, p_1)\end{aligned}\quad (12)$$

2.3 Run length properties (Case K)

The run length of the Shewhart charts for ZIP and ZIB processes with known parameters is a geometric random variable N with parameter $1 - \beta$, i.e., the p.m.f. $f_N(\nu)$ and the c.d.f. $F_N(\nu)$ of N are defined for $\nu = 1, 2, \dots$ and they are, respectively, given by:

$$f_N(\nu) = (1 - \beta)\beta^{\nu-1}, \quad F_N(\nu) = 1 - \beta^\nu, \quad (13)$$

where β is the probability defined in equations (6) and (12). Therefore, the Average Run Length (ARL) and the Standard Deviation Run Length ($SDRL$) of the Shewhart charts for ZIP and ZIB processes with known parameters equal

$$E(N) = ARL = \frac{1}{1 - \beta}, \quad \sqrt{V(N)} = SDRL = \frac{\sqrt{\beta}}{1 - \beta}. \quad (14)$$

Note also that the moment about the origin of order two of the run length distribution equals

$$\mu'_2 = E(N^2) = V(N) + E^2(N) = \frac{\beta}{(1 - \beta)^2} + \frac{1}{(1 - \beta)^2} = \frac{1 + \beta}{(1 - \beta)^2}, \quad (15)$$

where $\mu'_k = E(N^k)$, $k = 1, 2, \dots$. It should be mentioned that since β is given by equations (6) or (12) the run length distribution as well as the ARL and $SDRL$ refer all to the OOC case. For $\phi_1 = \phi_0$ and $\lambda_1 = \lambda_0$ we get the respective IC measures.

3 Shewhart Charts for Monitoring ZIP and ZIB Processes With Unknown Parameters

In this section we discuss the properties of the two Shewhart charts, for ZIP and ZIB processes, in Case U. The two processes are treated individually. As already stated, for estimating the process parameters, we consider both the MLE method and the MoM.

3.1 The Shewhart Chart for ZIP Processes (Case U)

Suppose that we are interested in monitoring a ZIP process but the IC values of the process parameters are unknown. Thus, ϕ_0 and λ_0 must be estimated from a Phase I sample. Let X_1, X_2, \dots, X_m be a random sample from $ZIP(\phi_0, \lambda_0)$, i.e., $X_i \sim ZIP(\phi_0, \lambda_0)$, $i = 1, 2, \dots, m$. This is the Phase I sample which is used for estimating ϕ_0 and λ_0 .

Using the MoM, the respective moment estimators (ME) for λ_0 and ϕ_0 are given by:

$$\tilde{\lambda} = \frac{\overline{X^2}}{\bar{X}} - 1, \quad \tilde{\phi} = 1 - \bar{X}/\tilde{\lambda}, \quad (16)$$

where

$$\bar{X} = \frac{1}{m} \sum_{i=1}^m X_i, \quad \overline{X^2} = \frac{1}{m} \sum_{i=1}^m X_i^2, \quad (17)$$

Also, using the MLE method, the respective estimators are not given in closed form but they are obtained numerically by solving the following non-linear system of equations:

$$\begin{cases} \hat{\lambda} = \bar{X}^+(1 - e^{-\hat{\lambda}}) \\ \hat{\phi} = 1 - \bar{X}/\hat{\lambda} \end{cases} \quad (18)$$

where \bar{X}^+ is the average of strictly positive X 's.

When ϕ_0, λ_0 are estimated by $\hat{\phi}, \hat{\lambda}$, the control limits of the Shewhart chart are denoted as \widehat{LCL}_{ZIP} , \widehat{UCL}_{ZIP} and they are simply obtained by substituting ϕ_0, λ_0 with $\hat{\phi}$ and $\hat{\lambda}$ in equations (5) and (4). In a similar manner, if ϕ_0 and λ_0 are estimated by $\tilde{\phi}, \tilde{\lambda}$, the respective limits are denoted as \widetilde{LCL}_{ZIP} , \widetilde{UCL}_{ZIP} . It is not difficult to see that in Case U the control limits are based on the estimates of process parameters obtained from the available Phase I sample and thus, they are random variables. Given the estimates of ϕ_0 and λ_0 it is possible to calculate the limits and proceed to Phase II process monitoring.

It is not difficult to realize that different practitioners will end up with different estimates for the process parameters, because of the different Phase I samples. Thus, it is possible to use different control limits. In order to reflect the estimation error that it is attributed to the different estimates among all the practitioners, we will use the probability $\hat{\beta} = P(Y_i \in [\widehat{LCL}_{ZIP}, \widehat{UCL}_{ZIP}] | \phi_1, \lambda_1)$ (or $\tilde{\beta} = P(Y_i \in [\widetilde{LCL}_{ZIP}, \widetilde{UCL}_{ZIP}] | \phi_1, \lambda_1)$, in case of MoM estimators) to investigate the performance of the ZIP-Shewhart chart in Case U. Note also that this probability cannot be calculated in practice because ϕ_1, λ_1 is unknown.

The assessment of the control chart's performance in Case U is made under two perspectives, the 'unconditional' or the 'conditional'. In Case U, the run length distribution of the ZIP-Shewhart chart is no longer a geometric one because the control limits are r.v. However, given the estimates $\hat{\phi}, \hat{\lambda}$ (or $\tilde{\phi}, \tilde{\lambda}$), the run length

of the chart becomes *conditional* on them and thus, it is known *conditional run length*. Its distribution is now a geometric one. Using the conditional run length distribution it is possible to evaluate the performance of the chart under the ‘conditional’ perspective. This approach was followed by Mamzeridou and Rakitzis (2023). See also Zhao and Driscoll (2016); Vakilian et al. (2018) regarding the use of the conditional run length distribution to study the c -chart in Case U.

On the other hand, by averaging the conditional run length distribution over the (joint) distribution of $(\hat{\phi}, \hat{\lambda})$ (or $(\tilde{\phi}, \tilde{\lambda})$) we get the *unconditional* run length distribution. Using the unconditional run length distribution, the performance of the chart is evaluated under the unconditional perspective. This approach was followed by He et al. (2003) and Rakitzis and Castagliola (2016). The majority of the literature on the performance of attributes control charts in Case U is based on the use of the ‘unconditional’ run length distribution (see, for example, Braun (1999); Testik et al. (2006); Castagliola and Wu (2012); Castagliola et al. (2014); Wu et al. (2016); Johannssen et al. (2022) and references therein). An advantage of this perspective is that it can be applied before collecting the Phase I sample. Thus, it is possible to have practical guidelines regarding the size of the Phase I samples that gives the desired IC performance. For further details on the use of the unconditional run length distribution in studying the performance of control charts in Case U, see Jensen et al. (2006). Motivated by the previously mentioned works, we will use the unconditional (or marginal) run length distribution.

In Algorithm 1 we provide the steps for the calculation of the appropriate performance measures of the ZIP-Shewhart chart in Case U. To the best of our knowledge, the joint distribution of $(\hat{\phi}, \hat{\lambda})$ (or $(\tilde{\phi}, \tilde{\lambda})$) is not known. For this reason, we use Monte Carlo simulation. The steps are given in the case of MLE method while in the case of the MoM, the steps are similar. In order to avoid additional complexities in notation we will use the notations ARL , μ'_2 and $SDRL$ in either Case K and Case U. However, in the latter case, these are the *unconditional* measures.

Algorithm 1 Calculation of the unconditional performance measures - ZIP process

- 1: Choose a Phase I sample of size m from a $ZIP(\phi_0, \lambda_0)$ process.
 - 2: Use the Phase I sample and estimate ϕ_0, λ_0 by using the MLE method (and get the $\hat{\phi}, \hat{\lambda}$ estimates).
 - 3: Given the values $L, \hat{\phi}$ and $\hat{\lambda}$, determine $\widehat{UCL}_{ZIP}, \widehat{LCL}_{ZIP}$ from equations (4) and (5), respectively.
 - 4: Calculate the IC ARL and the IC μ'_2 as $1/(1 - \hat{\beta})$ and $(1 + \hat{\beta})/(1 - \hat{\beta})^2$, respectively.
 - 5: Repeat Steps 1-4 T times and calculate (i) the *unconditional* IC ARL as the average of the T values $1/(1 - \hat{\beta})$, (ii) the *unconditional* IC μ'_2 as the average of the T values $(1 + \hat{\beta})/(1 - \hat{\beta})^2$, (iii) the *unconditional* IC $SDRL$ as $\sqrt{\mu'_2 - ARL^2}$, where ARL and μ'_2 are those obtained in (i) and (ii).
-

3.2 The Shewhart Chart for ZIB Processes (Case U)

Let X_1, X_2, \dots, X_m be a random sample from the zero-inflated binomial (ZIB) distribution with in-control parameters n, p_0 and ϕ_0 , i.e., $X_i \sim ZIB(\phi_0, n, p_0)$, $i = 1, 2, \dots, m$. Using the MoM, the respective estimates of the IC process parameters are given by:

$$\tilde{p} = \frac{\bar{X}^2 - \bar{X}}{(n-1)\bar{X}}, \quad \tilde{\phi} = 1 - \frac{(n-1)\bar{X}^2}{n(\bar{X}^2 - \bar{X})}, \quad (19)$$

where

$$\bar{X} = \frac{1}{m} \sum_{i=1}^m X_i, \quad \bar{X}^2 = \frac{1}{m} \sum_{i=1}^m X_i^2, \quad (20)$$

Also, similar to the case of ZIP process, the MLEs are not given in closed form but they are obtained numerically by solving the following non-linear system of equations:

$$\begin{cases} \hat{p} = \bar{X}^+(1 - (1 - \hat{p})^n) \\ \hat{\phi} = 1 - \bar{X}/(n\hat{p}) \end{cases} \quad (21)$$

where \bar{X}^+ is the average of strictly positive X 's. When ϕ_0, p_0 are estimated by $\hat{\phi}, \hat{p}$, the control limits of the Shewhart chart are denoted as $\widehat{LCL}_{ZIB}, \widehat{UCL}_{ZIB}$. Similarly, if the process parameters are estimated by $\tilde{\phi}, \tilde{p}$, the respective limits are denoted as $\widetilde{LCL}_{ZIB}, \widetilde{UCL}_{ZIB}$. Therefore, the control limits of the ZIB-Shewhart chart in Case U are calculated by simply replacing the (unknown) values ϕ_0 and p_0 with their respective estimates. Then, practitioners can proceed to the Phase II process monitoring.

The performance of the ZIB-Shewhart chart in Case U is evaluated in terms of the *unconditional ARL* and *SDRL*. The steps for their calculation are identical to those provided in Section 3.1 for the ZIP-Shewhart chart, after some straightforward but necessary modifications. Due to space economy, the details are left to the readers.

4 Numerical Results

In this section, we present the results of an extensive simulation study, using 50000 simulation runs (i.e. $T = 50000$), regarding the IC performance of the ZIP- and ZIB-Shewhart charts in Case U.

4.1 The Unconditional Performance of the ZIP-Shewhart Chart

In Tables 1 and 2 we present the IC *ARL* and *SDRL* values for the ZIP-Shewhart chart in Case U, for $m \in \{100, 200, 500, 1000, 2000, 5000\}$, $\lambda_0 \in \{1, 2, 4, 5, 6, 8\}$ and $\phi \in \{0.9, 0.8, 0.7\}$. The MLE method has

been used to get the results in Table 1 while the MoM has been used for the results in Table 2. The first line in each cell gives the ARL while the second line gives the $SDRL$. In the column ‘Case K’ we provide the ARL and $SDRL$ values in Case K while constant L , given in the respective column, has been determined in Case K (in two decimals accuracy) so as the IC ARL is *as close as possible* to the nominal value $ARL_0 = 370.4$, a value that appears very frequently in several SPC textbooks. It is well known (see, for example, Rakitzis and Castagliola (2016)) that due to the discrete nature of the ZIP distribution it is almost impossible to achieve *exactly* the desired ARL_0 value. From the results in column ‘Case K’ in Table 1 (and Table 2) we deduce that there are cases where the IC ARL in Case K is above 370.4 while for the remaining ones it is below.

It is not difficult to see that for the particular combinations (ϕ_0, λ_0) , the IC ARL values can be very different between the Case K and Case U. For example, from the results in Table 1, when $(\phi_0, \lambda_0) = (0.8, 4)$ the IC ARL ($SDRL$) in Case K is $ARL = 234.04$ ($SDRL = 233.54$) while when $m = 200$ we have $ARL = 566.39$ ($SDRL = 1116.81$). Note also that for a relatively small Phase I sample (i.e. for $m = 100$ or 200), the ARL and $SDRL$ are very large, especially the latter. Actually, for large ϕ_0 values (such as 0.9 or 0.8) and for Phase I samples of size $m = 100$, the $SDRL$ values are extremely large. This is an indication of increased uncertainty regarding the actual IC performance of the chart. As m increases, the IC ARL values tend to decrease, but not in a monotonic way. This is common for attributes control charts with estimated parameters (see, for example, Castagliola and Wu (2012), Rakitzis and Castagliola (2016), Mamzeridou and Rakitzis (2023) and references, therein). Note also that as m increases, it is not necessary that the IC ARL and $SDRL$ obtained in Case U will converge to the respective IC ARL and $SDRL$ values in Case K. Even for very large Phase I samples (such as for $m = 2000$ or 5000), the ARL and $SDRL$ can be significantly different than the respective values in Case K. See, for example, the case $(\phi_0, \lambda_0) = (0.8, 1)$ or $(\phi_0, \lambda_0) = (0.7, 2)$. This fact is also attributed to the discrete nature of the ZIP distribution.

The results so far show that if we want to apply the ZIP-Shewhart chart in the practice, then we must collect a very large Phase I sample, even larger than 5000 preliminary observations, in order to have similar performance between the Case K and Case U. Since this is not always possible in practice, we provide in Tables 3 (MLE method) and 4 (MoM) the ‘adjusted’ L^* values (see column ‘ L^* ’ in the tables) which have been obtained so as the IC ARL in Case U is *as close as possible* to IC ARL in Case K, for a given size m for the Phase I sample. Note also that any other value (instead of the IC ARL in Case K) can be used instead, according to practitioners needs. Once the L^* values has been obtained, we calculate the respective IC ARL and $SDRL$ values when the constant L^* is used, instead of L .

The L^* have been determined with a two decimals accuracy, using 50000 simulation runs. The steps of the algorithmic procedure are given at Algorithm 2.

Table 1: IC *ARL* and *SDRL* values for the ZIP-Shewhart Chart in Case U when L is from Case K - MLE method

ϕ_0	λ_0	L	100	200	500	1000	2000	5000	Case K
0.9	1	6.66	735.21	426.62	330.69	323.88	325.72	326.11	526.64
			3164.42	1039.20	502.21	434.35	431.99	432.28	526.14
	2	6.41	1268.37	617.42	435.46	395.69	392.04	393.24	189.92
			11282.42	1739.44	694.71	518.63	489.55	489.74	189.42
	4	5.61	1173.64	568.04	390.56	348.66	335.52	335.86	468.09
			14863.58	1527.86	614.13	447.65	392.86	386.74	467.59
	5	5.72	2775.20	1043.62	643.09	555.63	522.05	511.23	314.19
			32197.04	3564.15	1118.23	752.59	624.91	589.38	313.69
	6	5.31	1685.94	714.62	457.20	396.67	374.75	366.50	497.71
			14686.21	2545.71	764.17	522.35	439.39	410.96	497.21
	8	5.15	3201.76	991.22	575.55	486.03	450.12	432.52	292.56
			45373.05	4210.97	1025.86	665.61	538.16	480.22	292.06
0.8	1	6.33	1605.20	1033.08	811.91	797.17	801.98	799.38	263.32
			8203.23	2641.74	1245.20	1115.59	1118.12	1116.19	262.82
	2	5.49	1561.49	943.59	726.60	700.33	696.85	692.86	301.87
			7511.36	2157.01	1075.06	911.12	897.56	894.40	301.37
	4	4.47	850.31	566.39	449.27	424.31	420.75	417.34	234.04
			3305.00	1116.81	620.58	518.11	499.33	496.14	233.54
	5	4.47	1536.53	927.90	707.73	650.36	633.37	634.67	365.09
			6766.62	2016.17	1033.60	808.04	746.39	744.54	364.59
	6	4.09	875.03	568.34	446.35	411.82	403.97	400.85	248.86
			3104.88	1129.01	622.37	498.47	463.78	458.92	248.36
	8	3.89	1092.12	667.40	502.29	459.47	444.99	440.59	289.74
			4205.83	1436.17	717.51	562.35	505.80	494.03	289.24
0.7	1	5.18	785.25	587.16	535.49	538.28	537.27	539.31	175.55
			2352.71	1179.19	757.51	474.96	747.22	748.72	175.05
	2	4.5	693.97	532.31	465.54	462.64	468.50	467.07	201.24
			1799.96	941.45	615.07	597.17	601.32	600.20	200.74
	4	3.66	412.11	328.80	291.87	287.96	290.63	294.41	409.89
			896.25	516.96	362.38	339.81	341.00	344.01	409.39
	5	3.65	658.47	506.09	434.03	420.35	416.23	411.57	243.39
			1584.07	832.45	552.26	497.58	490.16	485.96	242.89
	6	3.34	408.37	327.86	285.55	276.14	276.70	280.81	377.61
			863.19	514.41	353.55	316.93	314.09	317.52	377.11
	8	3.17	475.63	370.34	318.53	304.70	303.99	306.20	404.97
			1114.49	594.23	398.22	347.88	338.69	340.27	404.47

For example, in the case $(\phi_0, \lambda_0) = (0.8, 4)$, the IC *ARL* (*SDRL*) in Case K is equal to $ARL = 234.04$ ($SDRL = 233.54$) with $L = 4.47$. Here $ARL_0 = 234.04$. When the size of the Phase I sample is $m = 200$, then the ‘adjusted’ value for the chart parameter is $L^* = 4.02$ (when the process parameters are estimated via the maximum likelihood estimation method), which gives IC $ARL = 234.34$ and $SDRL = 390.11$. Recall that for $m = 200$ and $L = 4.47$ the $ARL = 566.39$ and $SDRL = 1116.81$. Therefore, the use of the ‘adjusted’ L^* value results in an IC *ARL* value is much closer to the nominal ARL_0 value while there is also a significant reduction in the *SDRL* value.

Table 2: IC *ARL* and *SDRL* values for the ZIP-Shewhart Chart in Case U when L is from Case K - MoM

ϕ_0	λ_0	L	100	200	500	1000	2000	5000	Case K
0.9	1	6.66	883.14	427.10	328.68	318.96	322.32	326.28	526.64
			12359.71	1145.97	518.36	432.19	429.41	432.41	526.14
	2	6.41	1281.62	624.01	435.30	398.50	390.07	389.88	189.92
			13991.43	1953.22	708.40	527.32	488.35	486.97	189.42
	4	5.61	1462.50	577.83	391.60	348.63	335.95	335.42	468.09
			58219.25	1993.99	628.37	452.55	394.96	386.37	467.59
	5	5.72	2839.46	1068.15	653.69	558.32	521.99	511.90	314.19
			31349.76	3975.49	1163.99	762.75	628.38	590.31	313.69
	6	5.31	1759.65	721.64	458.78	398.31	373.00	367.80	497.71
			15155.06	2718.01	775.81	533.86	439.46	412.17	497.21
	8	5.15	3049.76	1022.58	578.72	488.46	448.43	433.13	292.56
			36613.36	4224.83	1056.43	674.30	536.22	481.14	292.06
0.8	1	6.33	1920.78	1074.68	814.54	794.96	796.77	802.86	263.32
			13635.01	3116.44	1285.25	1116.00	1114.25	1118.77	262.82
	2	5.49	1647.73	984.21	727.80	696.39	694.18	696.20	301.87
			9176.57	2471.15	1113.19	915.94	895.45	897.04	301.37
	4	4.47	913.25	580.55	453.29	422.83	419.63	417.46	234.04
			3924.83	1208.57	638.30	518.07	498.36	496.24	233.54
	5	4.47	1670.69	948.22	713.63	652.88	637.28	636.91	365.09
			9529.34	2154.13	1047.45	822.13	750.63	746.48	364.59
	6	4.09	941.12	583.22	448.94	412.70	402.90	400.97	248.86
			3628.02	1268.77	632.52	501.68	463.91	459.03	248.36
	8	3.89	1157.29	684.89	509.14	464.15	445.14	441.07	289.74
			4884.43	1528.66	730.69	571.11	506.42	494.43	289.24
0.7	1	5.18	848.42	601.17	532.47	536.05	533.64	539.36	175.55
			3613.84	1268.09	753.96	746.32	744.54	748.75	175.05
	2	4.5	744.48	541.96	468.19	464.60	466.30	465.76	201.24
			2272.43	1000.84	631.23	598.28	599.60	599.18	200.74
	4	3.66	428.65	337.05	291.65	287.69	289.70	293.15	409.89
			1036.65	549.53	367.38	339.81	340.25	343.01	409.39
	5	3.65	698.85	514.16	437.42	419.80	416.28	410.79	243.39
			1788.67	863.89	563.35	497.57	490.20	485.24	242.89
	6	3.34	432.39	333.83	286.85	278.06	278.10	280.96	377.61
			1015.94	532.35	357.67	320.08	315.37	317.64	377.11
	8	3.17	509.23	377.29	322.06	306.22	303.69	305.87	404.97
			1291.78	613.58	407.06	351.84	338.65	339.99	404.47

Before closing this section it is worth mentioning that Tables 1-4 offer a head-to-head comparison between the MLEs and the MEs. Recall that for the MEs there are closed-form expressions while MLEs require the use of a non-linear equation solver and can only be obtained numerically. The results show that for Phase I samples of size $m \geq 500$, the two methods provide (almost) identical results. When $m = 100$ or 200 , the respective *ARL* and *SDRL* values can be very different. According to Beckett et al. (2014); Wagh and Kamalja (2018), the MLEs are superior than the estimates obtained by the MoM, in terms of mean square error and bias, especially for small sample sizes. Therefore, we would suggest the use of MLEs when very

Algorithm 2 Determination of the adjusted constant L^* - ZIP process

- 1: Choose the nominal IC ARL value, say ARL_0 .
 - 2: Collect a Phase I sample of size m from a $ZIP(\phi_0, \lambda_0)$ process.
 - 3: Use the Phase I sample and estimate ϕ_0, λ_0 by using the MLE method (and get the $\hat{\phi}, \hat{\lambda}$ estimates).
 - 4: Set the initial value $L \leftarrow 0.01$
 - 5: Given the values $L, \hat{\phi}$ and $\hat{\lambda}$, determine $\widehat{UCL}_{ZIP}, \widehat{LCL}_{ZIP}$ from equations (4) and (5) and calculate the IC ARL .
 - 6: Repeat Steps 2-5 T times and calculate the *unconditional* IC ARL as the average of the T values $1/(1 - \hat{\beta})$.
 - 7: Compare the ARL obtained in step 6 with the ARL_0 . If $|ARL - ARL_0|/ARL_0 > 0.05$ then increase L by 0.01 and go back to Step 1. Otherwise, select L as the 'adjusted' L^* value.
-

large Phase I samples are not available. However, for larger Phase I samples (e.g. when $m > 1000$) the MoM estimators of ϕ_0, λ_0 might be more appealing to practitioners due to their simplicity in calculation.

4.2 The Unconditional Performance of the ZIB-Shewhart Chart

Tables 5-6 and Tables 7-8 are counterparts to Tables 1-2 and Tables 3-4 but for the ZIB-Shewhart chart. In Tables 5 and 6 we present the IC ARL and $SDRL$ values for the ZIB-Shewhart chart, for $n \in \{100, 250\}$, $p_0 \in \{0.01, 0.02, 0.030\}$, $m \in \{100, 200, 500, 1000, 2000, 5000\}$ and $\phi \in \{0.9, 0.8, 0.7\}$. The value of L has been determined in order to achieve an IC ARL value in Case K that it is *as close as possible* to the nominal $ARL_0 = 370.4$. Note also that the results in Table 5 have been obtained via the MLE method while for those in Table 6 we used the MoM. Again, the values of the achieved ARL_0 can be very different than the nominal 370.4 value. As for the case of ZIP-Shewhart chart, this is attributed to the discrete nature of the ZIB distribution and the large value of the zero-inflation parameter ϕ_0 .

For example, for $\phi_0 = 0.8$, $p_0 = 0.01$, $n = 100$ and $L = 6.35$, the control limits are obtained from equations (10) and (11) and they equal $UCL_{ZIB} = 3$, $LCL_{ZIB} = 0$. Therefore, using equation (12), the FAR equals $1 - \beta = 1 - F_{ZIB}(3 | 0.8, 100, 0.01) + F_{ZIB}(0 - 1 | 0.8, 100, 0.01) \approx 0.0036748 + 0 = 0.0036748$ and the $ARL_0 = 1/0.0036748 \approx 272.12$.

Conclusions from Tables 5 and 6 are similar to those from Tables 1 and 2. Specifically, the IC ARL values can be very different between Case K and Case U. For example, if $(\phi_0, n, p_0) = (0.9, 250, 0.01)$ then the IC ARL and $SDRL$ are 242.82 and 242.32, respectively. But, in Case U and for $m = 200$, the IC ARL and $SDRL$ are 828.37 and 2962.55, respectively. Clearly, these values are much larger than the respective ones in Case K, especially the IC $SDRL$. Therefore, very large Phase I samples are needed (e.g. $m \geq 1000$) while there are cases where even $m = 5000$ preliminary observations might not be enough in order to have similar performance between Case K and Case U. See, for example, the cases $(\phi_0, n, p_0) = (0.8, 100, 0.01)$ or $(\phi_0, n, p_0) = (0.9, 100, 0.02)$. However, as the size m increases, the IC $SDRL$ reduces while the IC ARL

Table 3: ‘Adjusted’ L^* Values for the ZIP-Shewhart Chart - MLE method

λ_0	m	$\phi_0 = 0.9$			$\phi_0 = 0.8$			$\phi_0 = 0.7$		
		L^*	ARL	$SDRL$	L^*	ARL	$SDRL$	L^*	ARL	$SDRL$
1	100	6.54	526.64	1914.88	4.86	263.22	650.62	4.10	179.75	374.91
	200	6.90	528.91	1390.08	5.12	262.39	494.63	4.26	175.45	276.87
	500	7.33	527.17	947.08	5.30	263.03	358.17	4.36	174.57	202.59
	1000	7.51	529.11	739.50	5.38	263.06	288.63	4.41	175.39	177.76
	2000	7.64	527.05	581.89	5.43	263.30	264.45	4.44	175.54	175.05
	5000	7.67	526.33	526.29	5.64	263.34	262.94	4.44	175.55	175.05
2	100	4.98	189.51	526.49	4.53	300.65	806.72	3.80	199.34	400.56
	200	5.30	189.66	360.71	4.73	304.39	543.58	3.92	202.41	309.87
	500	5.52	190.31	265.89	4.86	300.18	406.96	4.00	201.09	243.50
	1000	5.61	190.35	227.59	4.92	301.04	344.89	4.04	201.66	212.20
	2000	5.67	189.86	200.66	4.96	302.01	309.55	4.05	201.21	201.62
	5000	5.74	189.98	189.86	4.98	301.87	301.42	4.05	201.24	200.74
4	100	5.14	473.58	3861.22	3.88	235.33	579.53	3.66	409.93	924.35
	200	5.49	463.95	1431.24	4.02	234.34	390.11	3.75	405.19	654.51
	500	5.74	464.46	753.44	4.12	232.37	302.78	3.82	406.40	520.92
	1000	5.84	466.90	618.94	4.15	234.95	273.28	3.85	408.91	460.79
	2000	5.89	465.12	547.49	4.17	233.91	246.11	3.86	407.91	418.67
	5000	5.94	468.77	487.91	4.19	234.04	234.12	3.88	409.90	409.54
5	100	4.73	323.72	1673.04	3.92	365.10	993.44	3.28	242.37	487.02
	200	5.04	314.12	726.86	4.06	364.24	663.87	3.36	242.89	364.17
	500	5.24	313.38	480.98	4.16	366.44	499.38	3.41	241.53	297.82
	1000	5.32	313.61	400.84	4.20	367.29	442.19	3.44	245.08	272.32
	2000	5.36	311.84	359.94	4.22	365.72	398.56	3.45	243.57	249.88
	5000	5.40	314.64	327.18	4.24	365.54	368.39	3.46	243.46	243.16
6	100	4.81	499.73	2733.80	3.62	250.20	689.91	3.31	381.12	826.60
	200	4.79	492.48	3018.95	3.75	250.10	443.31	3.39	372.96	594.64
	500	5.12	495.15	1425.54	3.83	249.11	326.73	3.45	380.46	482.38
	1000	5.45	493.99	663.90	3.86	248.56	292.40	3.47	378.22	431.74
	2000	5.50	499.64	597.13	3.88	248.15	267.48	3.48	376.75	394.47
	5000	5.53	496.66	530.07	3.89	248.49	250.36	3.49	377.58	377.91
8	100	4.33	299.65	1500.19	3.47	289.30	796.77	3.12	404.77	886.12
	200	4.60	293.34	777.60	3.60	293.82	548.37	3.20	409.21	670.61
	500	4.80	292.26	463.56	3.68	289.34	390.57	3.25	407.76	519.92
	1000	4.87	292.58	378.29	3.71	289.76	344.97	3.27	409.30	473.06
	2000	4.91	293.21	340.75	3.73	292.57	323.01	3.28	406.63	433.95
	5000	4.94	294.13	313.23	3.74	289.99	295.78	3.29	405.99	408.78

converges (not monotonically) to a specific value, which is not necessarily the same with the IC ARL under Case K.

In Tables 7 and 8 we provide the ‘adjusted’ values L^* of the chart’s design parameter L , so as for a pre-specified size m of the Phase I sample, the IC ARL under Case K is the closest possible to the IC ARL under Case K. The L^* has been determined with a two decimals accuracy, using Monte Carlo simulation. The steps of the related algorithmic procedure are similar to those presented in Section 3.1, for the case of

Table 4: ‘Adjusted’ L^* Values for the ZIP-Shewhart Chart - MoM

λ_0	m	$\phi_0 = 0.9$			$\phi_0 = 0.8$			$\phi_0 = 0.7$		
		L^*	ARL	$SDRL$	L^*	ARL	$SDRL$	L^*	ARL	$SDRL$
1	100	6.25	531.07	3095.24	4.86	267.77	857.32	4.09	175.79	391.94
	200	6.90	543.54	1649.93	5.11	263.45	508.96	4.24	176.52	287.04
	500	7.33	529.79	951.57	5.30	264.72	369.75	4.36	175.91	209.19
	1000	7.51	532.30	756.62	5.38	264.53	296.31	4.42	175.79	180.14
	2000	7.63	527.60	592.97	5.44	263.61	265.94	4.44	175.55	175.19
	5000	7.68	526.70	528.12	5.32	263.32	262.82	4.25	175.55	175.05
2	100	4.98	193.14	792.41	4.52	306.59	855.64	3.80	201.34	419.99
	200	5.30	190.68	384.17	4.72	306.55	578.28	3.92	204.84	325.62
	500	5.53	192.77	273.03	4.86	303.33	422.58	4.00	202.36	250.62
	1000	5.61	190.45	231.20	4.92	304.04	357.06	4.04	201.89	215.39
	2000	5.67	190.04	202.49	4.96	302.50	312.96	4.06	201.38	202.14
	5000	5.71	189.98	189.95	4.97	301.87	301.48	4.04	201.24	400.74
4	100	5.12	468.23	2383.37	3.86	235.30	634.38	3.65	424.18	1115.79
	200	5.48	470.19	3398.92	4.02	237.56	416.71	3.75	412.83	687.30
	500	5.75	471.20	782.49	4.11	234.15	309.95	3.82	412.84	539.78
	1000	5.84	468.29	631.06	4.15	234.46	274.23	3.85	411.61	470.61
	2000	5.90	471.43	561.97	4.18	235.88	250.54	3.87	411.04	425.87
	5000	5.94	468.75	489.51	4.19	234.09	234.39	3.88	409.90	409.62
5	100	4.71	320.47	1739.25	3.90	371.43	1109.44	3.26	237.90	480.98
	200	5.02	314.95	770.66	4.06	373.64	710.68	3.36	248.60	381.95
	500	5.25	320.30	500.50	4.16	366.83	504.38	3.42	248.55	309.66
	1000	5.33	318.47	411.56	4.20	369.94	450.50	3.44	247.02	278.25
	2000	5.37	316.00	367.03	4.22	366.28	401.06	3.45	244.04	251.96
	5000	5.40	314.45	327.80	4.24	365.33	368.72	3.46	243.46	243.30
6	100	4.79	510.34	4858.52	3.61	253.05	691.00	3.30	386.09	883.67
	200	5.13	519.81	1693.26	3.74	249.54	441.93	3.39	382.38	621.35
	500	5.37	509.23	886.18	3.83	251.35	333.00	3.45	384.21	492.48
	1000	5.45	500.16	679.99	3.86	249.25	294.17	3.47	380.40	438.07
	2000	5.50	500.60	601.97	3.88	250.16	272.42	3.49	383.03	405.29
	5000	5.54	502.74	539.86	3.90	249.53	252.24	3.50	378.26	379.39
8	100	4.29	299.06	5744.17	3.46	293.92	923.36	3.10	397.00	952.52
	200	4.60	296.97	784.66	3.60	297.99	576.82	3.18	392.39	645.46
	500	4.80	294.37	468.89	3.68	293.14	400.61	3.24	400.23	513.15
	1000	4.87	293.66	381.99	3.71	291.57	349.50	3.26	400.55	463.44
	2000	4.91	295.21	344.15	3.73	292.42	323.03	3.28	407.42	436.28
	5000	4.94	295.41	315.50	3.74	290.44	296.90	3.29	405.94	408.91

the ZIP-Shewhart chart. Some direct but necessary modifications are needed. The results in both Tables 7 and 8 show that the use of the ‘adjusted’ L^* results in IC ARL values much closer to the respective value in Case K while the IC $SDRL$ is much lower, compared to the case where the unadjusted L value is used.

Table 5: IC *ARL* and *SDRL* values for the ZIB-Shewhart Chart in Case U when L is from Case K - MLE method

ϕ_0	p_0	n	L	100	200	500	1000	2000	5000	Case K
0.9	0.01	100	6.68	905.96	450.09	340.95	332.53	334.73	337.79	544.25
				5067.77	1205.60	518.39	446.73	446.30	448.57	543.75
		250	6.38	1804.08	828.37	551.49	490.08	478.06	475.08	242.82
				16092.61	2962.55	916.65	654.97	590.73	586.15	242.32
0.8	0.01	100	6.35	1959.66	1106.40	870.21	854.52	851.31	858.41	272.12
				11762.09	2957.93	1349.42	1197.39	1193.81	1199.00	271.62
		250	5.31	1845.05	1117.18	836.70	793.15	788.18	783.97	364.92
				9380.28	2617.58	1248.05	1028.49	1002.35	998.90	364.42
0.7	0.01	100	5.19	844.34	617.27	562.32	565.09	561.93	558.17	181.42
				2883.62	1213.13	799.13	793.95	791.61	788.79	180.91
		250	4.35	815.67	604.66	528.87	520.38	513.14	508.91	243.28
				2210.39	1068.48	700.18	664.77	657.86	654.25	242.78
0.9	0.02	100	6.43	1390.59	658.03	463.27	419.49	413.94	413.81	196.73
				9792.72	1864.65	748.52	552.77	522.49	521.12	196.23
		250	5.73	3301.38	1126.98	695.83	596.43	555.99	542.99	329.22
				76501.60	3833.54	1231.11	825.55	668.75	630.13	328.72
0.8	0.02	100	5.51	1752.68	1059.84	800.56	773.11	768.20	766.16	322.92
				8044.89	2697.97	1211.15	1018.73	1000.71	999.11	322.42
		250	4.04	546.84	367.64	300.80	284.05	281.48	284.06	390.77
				2701.38	675.68	402.04	338.08	323.91	325.42	390.27
0.7	0.02	100	4.51	771.87	581.34	509.49	501.80	499.72	489.92	215.28
				2145.68	1034.41	686.15	659.35	657.09	648.97	214.78
		250	3.66	730.52	556.84	475.17	458.28	456.62	451.26	260.51
				1834.69	948.22	613.03	544.71	540.56	535.75	260.01
0.9	0.03	100	6.38	3195.35	1230.92	756.34	657.13	624.07	620.12	320.23
				55772.52	4905.18	1345.95	909.57	774.01	759.32	319.73
		250	5.09	2297.93	808.28	484.48	414.70	388.05	375.15	248.86
				34034.94	2666.92	834.65	557.19	460.84	417.27	248.36
0.8	0.03	100	4.51	570.29	398.58	330.08	319.25	322.23	326.26	470.64
				1891.84	746.76	445.74	390.33	389.40	392.55	470.14
		250	3.86	935.83	576.64	439.76	405.54	391.48	387.97	252.12
				3658.73	1244.32	619.49	494.25	446.75	439.04	251.61
0.7	0.03	100	4.27	1083.34	802.81	680.58	667.35	668.83	668.83	313.76
				3109.93	1467.40	910.28	842.23	841.27	840.69	313.26
		250	3.4	1035.11	760.02	621.56	589.34	578.33	567.52	363.24
				2753.87	1373.60	816.73	697.60	667.16	656.36	362.74

5 Out-of-Control Performance of the Charts in Case U

In this section, we investigate the OOC performance of the ZIP- and ZIB-Shewhart charts. It is expected that when the ‘adjusted’ constant L^* is used, there will be differences in the detection ability of the chart. These differences also depend on the size m of the Phase I sample as well as on the magnitude of shift(s) in process parameters. Again, we use Monte Carlo simulation and the *ARL*, *SDRL* values are provided for several shifts in process parameters. Due to space economy, only the results in the case of MLE method are

Table 6: IC *ARL* and *SDRL* values for the ZIB-Shewhart Chart in Case U when L is from Case K - MoM

ϕ_0	p_0	n	L	100	200	500	1000	2000	5000	Case K
0.9	0.01	100	6.68	819.19	442.89	337.97	329.77	330.31	335.92	544.25
				5757.19	1528.21	537.91	449.36	442.94	447.19	543.75
		250	6.38	1964.63	813.32	553.84	490.51	476.76	475.55	242.82
				38479.06	2549.29	952.35	663.62	590.62	586.55	242.32
0.8	0.01	100	6.35	2066.18	1128.33	856.90	844.78	849.41	853.56	272.12
				14747.90	3252.57	1376.88	1196.22	1192.42	1195.46	271.62
		250	6	1907.18	1126.10	839.75	789.24	783.95	779.37	364.92
				11480.70	2864.85	1286.38	1029.17	998.91	995.10	364.42
0.7	0.01	100	5.19	859.75	620.89	557.01	555.93	557.25	553.53	181.42
				3177.49	1270.84	798.42	787.10	788.10	785.27	180.91
		250	4.35	814.89	609.44	525.10	517.14	512.98	503.76	243.28
				2371.18	1135.87	710.05	662.48	657.73	649.79	242.78
0.9	0.02	100	6.43	1411.89	664.56	460.10	417.44	411.19	410.55	196.73
				19130.12	2215.13	772.55	558.28	520.09	518.42	196.23
		250	5.73	3139.49	1149.55	691.13	594.82	554.54	542.81	329.22
				36337.64	4337.88	1249.93	826.06	673.75	629.65	328.72
0.8	0.02	100	5.51	1805.57	1050.28	804.90	763.27	764.15	770.48	322.92
				8924.58	2581.10	1249.33	1010.73	997.52	1002.50	322.42
		250	4.04	524.27	364.56	301.95	283.03	281.73	284.55	390.77
				1687.15	693.27	412.39	337.16	324.26	325.83	390.27
0.7	0.02	100	4.51	781.04	586.60	505.38	500.09	498.89	490.52	215.28
				2441.09	1146.70	684.72	657.40	656.41	649.48	214.78
		250	3.66	728.28	556.02	473.93	457.86	455.61	451.69	260.51
				1916.02	959.71	618.42	546.08	539.76	536.13	260.01
0.9	0.03	100	6.38	3265.02	1217.89	749.80	653.31	624.05	618.16	320.23
				47087.82	4698.07	1359.02	923.07	776.75	757.65	319.73
		250	5.09	2174.34	796.58	483.49	416.57	386.64	373.77	248.86
				22699.92	3104.88	854.60	570.90	460.04	416.15	248.36
0.8	0.03	100	4.51	571.83	398.43	329.15	318.58	319.97	324.40	470.64
				2249.32	805.98	454.06	392.87	387.60	391.10	470.14
		250	3.86	904.74	574.09	441.43	404.73	391.78	387.30	252.12
				3503.86	1234.12	632.01	495.61	446.67	483.42	251.61
0.7	0.03	100	4.27	1111.46	805.86	680.79	668.27	666.85	668.61	313.76
				3585.85	1501.58	922.51	845.54	839.90	841.10	313.26
		250	3.4	1029.06	754.55	622.78	586.09	578.36	567.83	363.24
				2848.15	1366.98	825.29	695.60	667.58	656.65	362.74

presented.

5.1 Out-of-Control Performance of the ZIP-Charts in Case U

In Table 9, we give the *ARL* and *SDRL* values for two ZIP processes: $ZIP(0.8, 2)$ and $ZIP(0.7, 1)$. The shifts in process parameters are $\phi_1 = \tau\phi_0$ with $\tau \in \{0.8, 0.6\}$ and $\lambda_1 = \delta\lambda_0$ with $\delta \in \{1.2, 1.5\}$. For the first process, we assume that the size of the Phase I sample is $m = 200$ while in the second $m = 500$.

The OOC *ARL* values are compared for both ZIP-Shewhart charts with either ‘adjusted’ or unadjusted

Table 7: ‘Adjusted’ L^* Values for the ZIB-Shewhart Chart - MLE method

p_0	n	m	$\phi_0 = 0.9$			$\phi_0 = 0.8$			$\phi_0 = 0.7$		
			L^*	ARL	$SDRL$	L^*	ARL	$SDRL$	L^*	ARL	$SDRL$
0.01	100	100	6.22	547.62	2898.06	4.83	275.82	734.92	4.10	187.96	416.23
		200	6.86	553.26	1464.83	5.13	277.34	536.52	4.27	182.05	293.11
		500	7.36	554.95	984.83	5.30	272.52	379.78	4.37	181.63	215.06
		1000	7.53	550.44	783.88	5.40	272.71	300.60	4.43	181.48	184.54
		2000	7.66	544.80	603.72	5.46	272.36	274.22	4.44	181.43	181.08
		5000	7.73	544.28	544.97	5.34	272.12	271.62	4.21	181.42	180.91
0.02	100	100	4.99	196.97	718.36	4.55	326.95	914.88	3.83	218.21	455.28
		200	5.30	197.17	380.91	4.74	324.82	606.08	3.94	216.92	338.19
		500	5.54	197.61	277.31	4.88	324.36	450.06	4.03	217.99	267.40
		1000	5.63	196.87	237.15	4.94	322.97	373.78	4.06	216.04	228.13
		2000	5.70	197.22	208.97	4.98	323.02	331.20	4.08	215.36	215.65
		5000	5.74	196.78	196.75	5.00	322.93	322.55	4.01	215.28	214.78
0.03	100	100	5.09	323.34	1293.61	4.42	477.90	1513.62	3.73	317.90	673.94
		200	5.44	323.53	747.21	4.60	473.39	965.78	3.83	315.70	503.62
		500	5.68	320.37	483.84	4.73	472.69	677.53	3.90	314.05	400.09
		1000	5.77	320.28	415.16	4.78	471.26	576.32	3.94	316.69	349.47
		2000	5.83	320.38	362.67	4.82	472.82	504.36	3.95	313.84	317.76
		5000	5.88	320.43	324.91	4.85	470.93	471.65	3.96	313.76	313.26
0.01	250	100	5.05	248.87	943.69	4.47	375.30	1005.00	3.76	246.02	511.11
		200	5.38	245.81	525.73	4.65	368.71	689.54	3.86	244.62	379.11
		500	5.62	245.20	356.34	4.79	370.87	515.43	3.94	244.92	304.14
		1000	5.70	243.80	304.10	4.83	365.06	432.10	3.97	243.45	260.65
		2000	5.76	243.18	265.94	4.87	365.57	381.55	3.99	243.39	244.93
		5000	5.81	243.10	244.36	4.90	364.99	364.83	3.99	243.28	242.78
0.02	250	100	4.74	337.48	1522.58	3.92	396.38	1240.43	3.29	262.28	539.24
		200	5.04	332.37	875.33	4.07	393.34	748.01	3.37	262.76	397.89
		500	5.25	331.23	511.43	4.17	393.15	537.20	3.43	266.14	331.43
		1000	5.33	330.02	426.54	4.21	395.09	480.39	3.45	263.90	295.47
		2000	5.38	331.36	385.70	4.23	392.28	427.76	3.46	261.44	268.93
		5000	5.41	329.94	343.60	4.25	390.37	394.67	3.48	260.72	260.59
0.03	250	100	4.28	252.68	1350.49	3.44	252.94	674.34	3.10	359.07	821.73
		200	4.54	250.29	646.02	3.57	260.90	480.26	3.17	351.75	562.90
		500	4.73	250.57	390.05	3.65	256.79	344.24	3.23	362.81	461.89
		1000	4.80	251.69	321.47	3.68	257.94	307.20	3.24	354.55	406.47
		2000	4.84	251.71	290.24	3.69	252.70	276.63	3.26	362.99	384.36
		5000	4.87	252.18	267.24	3.71	253.99	258.71	3.26	362.34	363.33

L . Also, we provide the OOC ARL values in Case K. The results show that the use of the ‘adjusted’ L^* value results in ARL values that are very close to the theoretical values (i.e. those under Case K) while there is a reduction in the $SDRL$ values. Note also, that even for large shifts in process parameters (e.g. for $\delta = 1.5$ and $\tau = 0.6$) the respective IC ARL and $SDRL$ in Case U when the unadjusted L is used can be much different than the corresponding values under Case K.

Table 8: ‘Adjusted’ L^* Values for the ZIB-Shewhart Chart - MoM

p_0	n	m	$\phi_0 = 0.9$			$\phi_0 = 0.8$			$\phi_0 = 0.7$		
			L^*	ARL	$SDRL$	L^*	ARL	$SDRL$	L^*	ARL	$SDRL$
0.01	100	100	6.22	549.55	8769.46	4.88	272.38	892.13	4.12	182.62	413.66
		200	6.92	544.46	1711.07	5.12	272.35	542.85	4.26	182.66	307.14
		500	7.35	544.48	970.99	5.31	273.55	386.41	4.38	182.00	218.65
		1000	7.53	549.34	794.59	5.40	273.23	305.94	4.43	181.43	185.40
		2000	7.66	545.77	613.90	5.46	272.41	274.95	4.45	181.46	181.25
		5000	7.73	544.25	545.20	5.37	272.12	271.62	4.26	181.42	180.91
0.02	100	100	5.01	198.13	728.96	4.54	325.00	979.55	3.83	215.85	476.67
		200	5.33	196.99	395.82	4.75	325.78	619.55	3.94	216.50	345.00
		500	5.55	199.01	284.76	4.88	325.51	461.30	4.02	215.86	268.80
		1000	5.63	197.01	240.24	4.94	324.76	382.56	4.06	216.52	231.72
		2000	5.70	197.76	211.85	4.97	323.00	333.42	4.08	215.41	216.14
		5000	5.73	196.74	196.76	5.00	322.95	322.62	4.01	215.28	214.78
0.03	100	100	5.10	323.72	1962.17	4.42	477.24	1577.82	3.73	320.25	747.63
		200	5.45	323.21	829.87	4.60	472.48	1011.32	3.83	315.39	514.54
		500	5.69	320.64	497.95	4.73	474.02	692.41	3.90	314.86	408.38
		1000	5.77	320.75	420.67	4.78	471.66	584.45	3.94	317.75	356.21
		2000	5.83	320.69	366.18	4.82	473.45	510.22	3.96	314.94	321.24
		5000	5.87	320.24	325.46	4.83	470.68	471.69	3.96	313.78	313.31
0.01	250	100	5.07	244.13	891.46	4.46	364.97	1082.59	3.76	244.34	555.38
		200	5.40	248.42	543.63	4.66	368.34	699.62	3.87	248.16	398.63
		500	5.62	244.77	360.81	4.78	366.04	516.36	3.94	244.81	308.94
		1000	5.70	243.84	307.25	4.84	367.57	442.50	3.97	243.55	264.50
		2000	5.76	243.47	268.96	4.87	366.00	385.89	3.99	243.30	245.08
		5000	5.81	243.20	244.94	4.90	365.03	365.05	3.96	243.28	242.78
0.02	250	100	4.75	344.06	1986.21	3.93	402.80	1373.22	3.29	262.04	565.00
		200	5.04	332.03	840.28	4.07	392.60	756.94	3.37	262.55	410.71
		500	5.26	332.81	522.39	4.17	393.90	550.32	3.43	265.68	333.49
		1000	5.34	332.74	432.10	4.21	395.62	482.49	3.45	264.35	298.61
		2000	5.38	330.73	386.37	4.23	392.27	430.20	3.46	261.68	270.50
		5000	5.41	330.15	345.08	4.25	391.27	394.91	3.47	260.55	260.38
0.03	250	100	4.30	259.09	1453.56	3.45	258.11	842.59	3.10	358.13	868.61
		200	4.55	250.38	628.92	3.57	258.28	484.50	3.18	362.44	592.21
		500	4.73	249.27	389.73	3.65	256.53	345.74	3.22	351.99	449.17
		1000	4.80	251.08	321.89	3.68	257.24	307.31	3.24	354.47	407.83
		2000	4.84	251.44	290.47	3.69	253.20	278.18	3.25	356.52	377.35
		5000	4.87	252.08	267.51	3.71	254.03	259.04	3.26	362.22	363.50

5.2 Out-of-Control Performance of the ZIB-Charts in Case U

In Table 10, we provide the ARL and $SDRL$ values for two ZIB processes: $ZIB(0.9, 0.03, 250)$ and $ZIB(0.8, 0.01, 100)$.

Similar to the case of a ZIP process, the shifts in process parameters are $\phi_1 = \tau\phi_0$ with $\tau \in \{0.8, 0.6\}$ and $p_1 = \delta p_0$ with $\delta \in \{1.2, 1.5\}$. For the first process, we assume that the size of the Phase I sample is $m = 500$ while in the second $m = 1000$.

The results in Table 10 are similar to those in Table 9. Specifically, they show that the use of the

Table 9: OOC Performance of the ZIP-Shewhart Chart - MLE

		Case K, $L = 5.49$		Case U, $L = 5.49, m = 200$		Case U, $L^* = 4.73, m = 200$	
ϕ_1	λ_1	<i>ARL</i>	<i>SDRL</i>	<i>ARL</i>	<i>SDRL</i>	<i>ARL</i>	<i>SDRL</i>
0.80	2.0	301.87	301.37	936.24	2109.12	303.87	549.85
0.80	2.4	140.16	139.66	353.55	681.22	135.87	213.47
0.80	3.0	59.58	59.08	121.06	196.63	55.77	75.56
0.64	2.0	167.70	167.20	525.50	1226.86	168.79	301.97
0.64	2.4	77.87	77.37	197.93	382.76	75.39	119.99
0.64	3.0	33.10	32.60	67.44	107.50	31.17	42.15
0.48	2.0	116.10	115.60	362.21	820.71	116.05	207.98
0.48	2.4	53.91	53.41	138.30	283.77	52.26	81.71
0.48	3.0	22.92	22.41	45.54	74.05	21.58	29.25
		Case K, $L = 5.18$		Case U, $L = 5.18, m = 500$		Case U, $L^* = 4.36, m = 500$	
ϕ_1	λ_1	<i>ARL</i>	<i>SDRL</i>	<i>ARL</i>	<i>SDRL</i>	<i>ARL</i>	<i>SDRL</i>
0.70	1.0	175.55	175.05	537.67	757.06	174.84	202.52
0.70	1.2	98.71	98.21	260.15	351.78	97.92	109.00
0.70	1.5	50.78	50.27	113.41	145.43	50.17	53.25
0.56	1.0	119.69	119.19	366.41	516.63	119.55	138.96
0.56	1.2	67.30	66.80	177.81	241.10	66.81	73.99
0.56	1.5	34.62	34.12	77.84	99.37	34.22	36.19
0.42	1.0	90.80	90.30	277.36	391.92	90.46	104.06
0.42	1.2	51.06	50.55	134.04	180.94	50.72	56.12
0.42	1.5	26.27	25.76	59.01	75.39	25.93	27.24

‘adjusted’ L^* gives *ARL* values that are very close to the theoretical ones (i.e. those under Case K), while the *SDRL* are much lower than the respective ones in the case of ‘unadjusted’ L . Like the case of ZIP processes, the OOC *ARL* and *SDRL* can be much larger, compared to the respective values in Case K, even for large shifts in process parameters (such as $\delta = 1.5$ and $\tau = 0.6$) if the ‘unadjusted’ L is used.

6 Conclusions

In this work we studied the design and performance of Shewhart-type charts for zero-inflated processes, when the process parameters are unknown and must be estimated. Using Monte Carlo simulation and two estimation methods (maximum likelihood and method of moments) we evaluated the performance of the considered charts for several Phase I sample sizes, in terms of the unconditional *ARL* and *SDRL* performance measures. The numerical results showed that in the case of zero-inflated processes, very large Phase I samples are needed in order to obtain a reliable design of the chart, whose performance in the case of the estimated parameters is similar to its theoretical performance. In almost all of the examined cases, the suggested size m of the Phase I sample is larger than 1000 preliminary observations while there are cases where even more than 5000 preliminary observations do not guarantee that the actual performance will be

Table 10: OOC Performance of the ZIB-Shewhart Chart - MLE

			Case K, $L = 5.09$		Case U, $L = 5.09, m = 500$		Case U, $L^* = 4.73, m = 500$	
ϕ_1	p_1	n	ARL	$SDRL$	ARL	$SDRL$	ARL	$SDRL$
0.90	0.030	250	248.86	248.36	483.73	833.67	250.84	382.82
0.90	0.036	250	83.19	82.69	132.07	187.96	80.43	104.01
0.90	0.045	250	24.68	29.17	38.55	44.62	28.41	31.08
0.72	0.030	250	88.88	88.38	173.84	306.16	89.08	135.42
0.72	0.036	250	29.71	29.21	47.17	67.06	28.62	36.72
0.72	0.045	250	10.60	10.09	13.78	15.67	10.12	10.76
0.54	0.030	250	54.10	53.60	105.20	180.56	54.52	83.48
0.54	0.036	250	18.08	17.58	28.51	39.97	17.46	22.24
0.54	0.045	250	6.45	5.93	8.36	9.35	6.17	6.38
			Case K, $L = 6.35$		Case U, $L = 6.35, m = 1000$		Case U, $L^* = 5.40, m = 1000$	
ϕ_1	p_1	n	ARL	$SDRL$	ARL	$SDRL$	ARL	$SDRL$
0.80	0.010	100	272.12	271.62	848.45	1195.33	272.55	299.14
0.80	0.012	100	152.31	151.81	410.53	556.14	153.99	161.53
0.80	0.015	100	77.86	77.36	178.83	229.69	77.64	80.66
0.64	0.010	100	151.18	150.68	472.46	662.73	151.42	165.80
0.64	0.012	100	84.62	84.12	229.06	309.98	89.65	90.28
0.64	0.015	100	43.26	42.75	98.62	127.01	43.08	44.46
0.48	0.010	100	104.66	104.16	325.56	458.49	105.11	115.89
0.48	0.012	100	58.58	58.08	158.08	213.82	58.63	62.54
0.48	0.015	100	29.95	29.44	68.74	88.10	29.86	30.80

close to the theoretical one.

For relatively small preliminary samples (e.g. for $m = 100$ or 200), the IC ARL and $SDRL$ values can be very large. Therefore, we do not advise practitioners to set-up their chart when the process parameters are estimated from a Phase I sample of this size. Note also that in case of large ϕ_0 values, a small Phase I sample might end up to a sample with only zero values, making the estimate of process parameters impossible. As a general guideline, we suggest that Phase I samples with at least 1000 observations are necessary to obtain reliable estimates of process parameters. As m increases, the IC ARL and $SDRL$ reduce, but not necessarily in a monotonic way (the former).

In an attempt to assist practitioners in ending up with reliable designs for their charts, we provided ‘adjusted’ values for the design parameter L in order to obtain an IC ARL very close to IC ARL in Case K, for a given size m of the Phase I sample. Note also that the proposed methodology works for any other nominal ARL_0 (instead of the IC ARL value in Case K) that meets practitioners’ needs.

Finally, We used R (see R Core Team (2023)) for all the necessary computations in this work. The related programs are available from the authors upon request.

References

- W. Albers, W. C. M. Kallenberg, and S. Nurdianti. Parametric control charts. *Journal of Statistical Planning and Inference*, 124(1):159–184, 2004.
- S. Beckett, J. Jee, T. Ncube, S. Pompilus, Q. Washington, A. Singh, and N. Pal. Zero-inflated Poisson (ZIP) distribution: Parameter estimation and applications to model data from natural calamities. *Involve, a Journal of Mathematics*, 7(6):751–767, 2014.
- W.J. Braun. Run length distributions for estimated attributes charts. *Metrika*, 50:121–129, 1999.
- P. Castagliola and S. Wu. Design of the c and np charts when the parameters are estimated. *International Journal of Reliability, Quality and Safety Engineering*, 19(02):1250010, 2012.
- P. Castagliola, S. Wu, M.B.C. Khoo, and S. Chakraborti. Synthetic Phase II Shewhart-type attributes control charts when process parameters are estimated. *Quality and Reliability Engineering International*, 30(3):315–335, 2014.
- B. He, M. Xie, T.N. Goh, and P. Ranjan. On the estimation error in zero-inflated Poisson model for process control. *International Journal of Reliability, Quality and Safety Engineering*, 10(2):159–169, 2003.
- W. A. Jensen, L. A. Jones-Farmer, C. W. Champ, and W. H. Woodall. Effects of parameter estimation on control chart properties: a literature review. *Journal of Quality Technology*, 38(4):349–364, 2006.
- A. Johannssen, N. Chukhrova, and P. Castagliola. The performance of the hypergeometric np chart with estimated parameter. *European Journal of Operational Research*, 296(3):873–899, 2022.
- NL Johnson, AW Kemp, and S Kotz. *Univariate Discrete Distributions*. John Wiley & Sons, Inc. New York, NY, USA, 2005.
- T. Mahmood and M. Xie. Models and monitoring of zero-inflated processes: the past and current trends. *Quality and Reliability Engineering International*, 35(8):2540–2557, 2019.
- E. Mamzeridou and A. Rakitzis. On the design and performance of upper one-sided Shewhart charts for zero-inflated Poisson processes with estimated parameters. *Quality Technology & Quantitative Management*, 0(0):1–22, 2023. doi: 10.1080/16843703.2023.2232640. URL <https://doi.org/10.1080/16843703.2023.2232640>.
- D.C. Montgomery. *Introduction to Statistical Quality Control*. John Wiley & Sons, Inc., New York, USA, 6th edition, 2009.

- R Core Team. *R: A Language and Environment for Statistical Computing*. R Foundation for Statistical Computing, Vienna, Austria, 2023. URL <https://www.R-project.org/>.
- A.C. Rakitzis and P. Castagliola. The effect of parameter estimation on the performance of one-sided Shewhart control charts for zero-inflated processes. *Communications in Statistics-Theory and Methods*, 45(14):4194–4214, 2016.
- W. A. Shewhart. Quality control charts. *The Bell System Technical Journal*, 5(4):593–603, 1926.
- M.C. Testik, B.D. McCullough, and C.M. Borrór. The effect of estimated parameters on Poisson EWMA control charts. *Quality Technology & Quantitative Management*, 3(4):513–527, 2006.
- F. Vakilian, A. Amiri, and A. Faraz. The guaranteed adaptive c-charts with estimated parameter. *Quality and Reliability Engineering International*, 34(8):1575–1589, 2018.
- Y.S. Wagh and K.K. Kamalja. Zero-inflated models and estimation in zero-inflated poisson distribution. *Communications in Statistics-Simulation and Computation*, 47(8):2248–2265, 2018.
- S. Wu, P. Castagliola, and M.B.C. Khoo. Run rules based phase II c and np charts when process parameters are unknown. *Communications in Statistics-Theory and Methods*, 45(4):1182–1197, 2016.
- M.J. Zhao and A.R. Driscoll. The c-chart with bootstrap adjusted control limits to improve conditional performance. *Quality and Reliability Engineering International*, 32(8):2871–2881, 2016.