

GPT-4V as Traffic Assistant: An In-depth Look at Vision Language Model on Complex Traffic Events

Xingcheng Zhou[✉], Alois C. Knoll^{ID}, *Fellow, IEEE*

CONTENTS

I	Introduction	1
II	Success Cases	2
II-A	Dooring	2
II-B	Run the Red Light at Night	5
II-C	Motorcycle Car Collision	7
II-D	Rollover	9
II-E	Fires and Explosion	11
III	Failure Cases	14
III-A	Vehicle Collision	14
III-B	Jaywalking	17
III-C	Vehicle Smoke	19
III-D	Multiple Vehicle Collision	20
IV	Discussion	23

LIST OF FIGURES

1	Dooring Part 1	3
2	Dooring Part 2	4
3	Run the Red Light at Night Part 1	5
4	Run the Red Light at Night Part 2	6
5	Motorcycle Car Collision Part 1	7
6	Motorcycle Car Collision Part 2	8
7	Rollover Part 1	9
8	Rollover Part 2	10
9	Fires and Explosion Part 1	12
10	Fires and Explosion Part 2	13
11	Vehicle Collision Part 1	14
12	Vehicle Collision (Highlighted) Part 1	15
13	Vehicle Collision (Highlighted) Part 2	16
14	Jaywalking Part 1	17
15	Jaywalking Part 2	18
16	Vehicle Smoke Part 1	19
17	Vehicle Smoke (Highlighted) Part 1	20
18	Multiple Vehicle Collision Part 1	21
19	Multiple Vehicle Collision Part 2	22

LIST OF TABLES

I	Evaluation Summary of all Traffic Events.	23
----------	--	-----------

GPT-4V as Traffic Assistant: An In-depth Look at Vision Language Model on Complex Traffic Events

Abstract

The recognition and understanding of traffic incidents, particularly traffic accidents, is a topic of paramount importance in the realm of intelligent transportation systems and intelligent vehicles. This area has continually captured the extensive focus of both the academic and industrial sectors. Identifying and comprehending complex traffic events is highly challenging, primarily due to the intricate nature of traffic environments, diverse observational perspectives, and the multifaceted causes of accidents. These factors have persistently impeded the development of effective solutions. The advent of large vision-language models (VLMs) such as GPT-4V, has introduced innovative approaches to addressing this issue. In this paper, we explore the ability of GPT-4V with a set of representative traffic incident videos and delve into the model's capacity of understanding these complex traffic situations. We observe that GPT-4V demonstrates remarkable cognitive, reasoning, and decision-making ability in certain classic traffic events. Concurrently, we also identify certain limitations of GPT-4V, which constrain its understanding in more intricate scenarios. These limitations merit further exploration and resolution.

I. INTRODUCTION

The existing traffic event recognition approaches [14, 1] do not work well in practice due to the lack of common sense, high-level reasoning ability, and poor zero-shot recognition ability. Large Vision Language Models (VLMs) [3, 18, 8], represented by GPT-4V [6], integrate the vision modality with large language models (LLMs). They inherit the emergent abilities of LLMs [5, 10, 9], including strong reasoning and understanding abilities, the capability to leverage common sense, and zero-shot recognition abilities. It provides the possibility of accomplishing complex multimodal tasks as well as tackling the challenges in traffic event recognition. GPT-4V, recognized as one of the most powerful multi-modal models to date, has garnered widespread attention since its release. Several papers have shown exploratory applications of GPT-4V in different domains [13, 17, 16]. Therefore we are curious whether it can address these issues and bring new solution to this field.



Fig. Image Generated with DALLE-3 by prompting our paper title:
"GPT-4V as Traffic Assistant: An In-depth Look at Vision Language Model on Complex Traffic Events"

In our study, we qualitatively evaluate how much GPT-4V understands various traffic events. To ensure the diversity and representativeness of the evaluation, we carefully selected the key frames from a variety of videos showing classic traffic events. The selections are made with the objective of providing a complete and detailed overview of each incident. It means that chosen frames contain the essential information required for logical analysis and reasoning of the events depicted. The evaluated videos come from a wide range of sources, including the **Providetia++** infrastructure [2, 7], open-source datasets [15, 14], and various Internet resources. For clarity, the dashed boxes on the images are marked to help the reader comprehend the traffic events more quickly, and are not given as additional hints to GPT-4V. We set the temperature as 0 during evaluation to achieve the most confident and precise results from the model.

II. SUCCESS CASES

In this section, we present several exemplary success cases during the evaluations. We classify those traffic incidents that GPT-4V successfully recognizes both the presence of traffic events and the traffic type as success cases, although some of these instances may encompass certain misconceptions in event understanding.

A. *Dooring*

Dooring is a common type of traffic accident, usually occurring in areas with dense traffic, such as urban settings. It typically happens when a vehicle is parked roadside, and a passenger or driver inside the vehicle opens the door without noticing an approaching cyclist or motorcyclist. The sudden opening of the door often leaves the approaching individuals without sufficient time to avoid the collision, which can lead to an accident. It is usually very risky for vulnerable road users. The six images in Figure 1 are extracted from a video resourced from [11]. It illustrates a traffic accident where an electric scooter rider was pushed and fell to the side by a car door suddenly opening. We first evaluate whether GPT-4V can recognize the traffic accident occurring from the keyframes, and then test its performance in generating traffic accident reports, which is a critical task in traffic applications. We also evaluate model’s abilities of causal reasoning, attribution, and decision-making in such a complex traffic event.

As shown in figure 1 and 2, we observe that GPT-4V can correctly recognize the car accident depicted in the images and accurately identify it as ‘dooring’. This indicates that GPT-4V aligns the text semantic feature of ‘dooring’ accidents with semantic context captured in multiple images. It can also provide an overall accurate description of the accident, only except for the misidentifying of another red vehicle as the car opens the door. This demonstrates the feasibility of generating accident reports based on keyframes, and provides a good example of vision-based traffic report generation.

Based on the precise understanding and description of accidents, we delved into the model’s high-level reasoning and inductive capabilities. By querying the causes of accidents, we assessed its casual inference ability within the given scenario. The answer shows it can include specific accident contexts, such as ‘wet road surface,’ to provide possible reasons applicable to the ‘dooring’ accident type. Additionally, GPT-4V attributes the primary responsibility of the accident to the act of opening the car door which is consistent with common traffic regulations. Through the prompt regarding required necessary emergency measures, we aimed to evaluate the model’s decision-making ability. It turns out that the generated decisions are relatively general and applicable to almost all types of accident scenarios. This generality may be attributed to the limited information available from the provided images, causing the model to lean towards offering a correct yet non-specific answer. When analyzing the severity of accidents, the model provides a broad range of assessments, which aligns with what humans can infer based on the given images.

In summary, GPT-4V demonstrates a high level of accuracy in recognizing and comprehending this case. It exhibits the capability to make reasonable analyses, conclusions, and decisions based on the provided image information. Its analytical skills in this particular case are comparable to those of humans.




Fig. 1: Dooring Part 1

Q: Generate a **detailed description** of the accident based on the given images.

GPT4V: Based on the sequence of images provided, the accident unfolds as follows:

1. ****Initial Scene****: The first image sets the scene with a person riding a motorbike down a **street that appears to be wet**, possibly from recent rain. The street is lined with parked cars on the right side, and traffic is visible in the opposite lane. The **rider is positioned close to the parked cars**, which suggests a risk of collision if a car door were to open.
2. ****Car Door Opens****: In the second image, **the car door of a red vehicle** begins to open just as the motorbike is passing by. The timing and proximity indicate a high risk of collision. The **rider seems unaware of the opening door**, and there is no indication of evasive action at this point.
3. ****Imminent Collision****: The third image shows the car door further open, and the motorbike is now very close to the car. **The rider's position and trajectory suggest that a collision is imminent**. The **rider may now be aware of the door but does not have sufficient time or space to avoid it**.
4. ****Impact****: The fourth image captures the moment of impact. **The rider appears to collide with the edge of the open car door....**
5. ****Rider and Motorbike Down****: The fifth image shows the immediate aftermath of the collision. The rider and the motorbike have been knocked to the ground, indicating **a loss of balance and control as a result of the impact**. The **rider's body is positioned awkwardly**, suggesting a sudden and forceful fall.
6. ****Post-Accident Scene****: The final image depicts **the rider lying on the ground**, motionless, **a short distance from the motorbike**. The motorbike is on its side, and the rider is separated from it, indicating they have been thrown from the bike. The open car door remains in the same position, and **it's clear that the accident was caused by the sudden opening of the door into the path of the motorbike**.

The accident described is **a classic example of "dooring,"** a situation where a cyclist or motorcyclist is struck by an opening vehicle door. This type of accident can result in serious injury, **as riders are often unable to react quickly enough to avoid the suddenly opened door....**

Q: Based on the given images, what could be the **reason for this accident**?

GPT4V: Here are some contributing factors that can be inferred from the images:

1. ****Lack of Awareness****: The person opening the **car door may not have checked for oncoming traffic, including motorbikes, before opening the door**.
2. ****Proximity to Parked Cars****: The **motorbike is traveling close to the line of parked cars**, which increases the risk of collision if a door is opened unexpectedly.
3. ****Wet Road Conditions****: The road appears to be wet, which could potentially **reduce the motorbike's ability to brake quickly and maneuver safely** to avoid the suddenly opened door.
4. ****Reaction Time****: The motorbike rider may **not have had enough time to react** to the opening door, especially if it was opened abruptly.
5. ****Visibility****: Depending on the speed of the motorbike and the timing of the door opening, **the rider's ability to see and anticipate the opening door could have been limited**.

Q: Who should be **primary responsible** for this traffic accident.

GPT4V: Based on general traffic safety principles:

1. The person opening the car door should check for oncoming traffic, including motorcyclists and cyclists, before opening the door. **Opening a door into traffic without being aware of approaching vehicles can create a hazard and may be considered negligent**.
2. The **motorcyclist should maintain a safe distance from parked vehicles** and be vigilant for the possibility of doors opening, especially if there is an indication of occupied vehicles (people sitting inside, lights on, etc.).

In many places, the responsibility would likely lie primarily with the person who opened the car door, as it is typically their duty to ensure that it is safe to do so without putting others at risk. That said, the specific circumstances, such as visibility, road conditions, and local laws, must be considered when making an official determination of fault....

Q: Determine the **severity of this accident** and analyze what **emergency measures** need to be taken.

GPT4V: The severity of traffic accidents can be difficult to determine from images alone.... Here are some general emergency measures that should be considered in such a situation:

1. ****Assess the Situation****.... 2. ****Check for Injuries****3. ****Call Emergency Services**** 4. ****Avoid Moving the Injured Person**** 5. ****Secure the Area**** 6. ****Gather Information**** 7. ****Document the Scene**** 8. ****Provide Comfort and Reassurance**** 9. ****Check for Traffic Hazards****

However, based on the images, it is reasonable to assume that **injuries could range from minor bruises and abrasions to more serious trauma**, especially given the vulnerability of motorcyclists in traffic accidents....

Fig. 2: Dooring Part 2

B. Run the Red Light at Night

Running red lights is one of the most common traffic violations. The recognition of this traffic event solely from video is challenging. The model needs to first recognize the status of the traffic light and the layout of the traffic scene. Based on the common sense that vehicles should stop and wait at red lights, the model identifies whether there is a vehicle traveling in the corresponding lane at the red light and then reaches a conclusion. The frames shown in figure 3 and 4 are extracted from the video in dataset [15]. There is a blue truck dragging a full load of dirt on the lower left side of the image, which continues to move forward at a red light and hits another large red semi-trailer truck that is moving normally. This ultimately caused the dust from the blue truck to spill into the air and caused the red semi-trailer truck to veer off course.




Fig. 3: Run the Red Light at Night Part 1

Q: Generate a **detailed description** of the accident based on the given images.

GPT4V: Based on the sequence of images provided, here is a detailed description of the traffic accident:
 The initial images depict a nighttime scene at an intersection with traffic lights. Vehicles are stopped at the intersection, waiting for the traffic signal to change. The traffic light is red, and the vehicles are correctly positioned within their designated lanes.

As the sequence progresses, a large vehicle, which appears to be a bus, enters the frame from the left side of the image. The bus is moving towards the intersection, and it becomes apparent that it is not slowing down despite the red traffic light. The bus continues to approach the intersection at speed, indicating a failure to adhere to the traffic signal. Other vehicles remain stationary, obeying the red light.

The bus encroaches into the intersection, crossing the traffic lanes perpendicular to its path. At this point, it is clear that the bus is not going to stop, creating a dangerous situation. Suddenly, a collision occurs. The bus impacts a smaller vehicle that was crossing the intersection from the opposite direction. The smaller vehicle had the right of way, as it was moving on a green light.... The final image shows the immediate aftermath of the collision. A cloud of smoke or dust envelops the area where the two vehicles have collided, indicating a significant impact....

Q: Specify the **number of recognized traffic participants** in the provided images. Describe their **appearances** and **trajectories** in detail.

GPT4V: In the provided images, there are several traffic participants that can be recognized. Here is a detailed description of their appearances and trajectories:

- Red Car:** There is a red car visible in all images, positioned in the bottom right corner of the frame, waiting at the intersection. It does not appear to move throughout the sequence, indicating that it is obeying the traffic signal.
- Blue Car:** A blue car is also present in all images, located to the left of the red car, and similarly waiting at the intersection without moving.
- Bus:** A large vehicle, which appears to be a bus, enters the frame from the left side in the third image. It continues to move towards the intersection in the fourth image, despite the traffic light being red. In the fifth image, the bus is seen colliding with another vehicle within the intersection, and in the sixth image, the bus is at a standstill post-collision, with smoke or dust around it.
- Smaller Vehicle (Collision Victim):** This vehicle is not clearly visible until the moment of the collision in the fifth image. It seems to be coming from the opposite direction of the bus, moving perpendicularly to it....
- Other Vehicles:** There are other vehicles with their headlights on in the background, but their details and movements are not clear from the images provided. They do not appear to be directly involved in the event....

Q: Who should be the **primary responsible** for this traffic accident?

GPT4V: Based on the sequence of images provided, it appears the large vehicle, presumably a bus, may be the primary party responsible for the traffic accident. This conclusion is drawn from the observation that it continues to move into the intersection against what appears to be a red traffic light, while other vehicles are stopped and a smaller vehicle is already crossing the intersection....

Q: Determine the **severity** of this accident and analyze what **emergency measures** need to be taken.

GPT4V: Certain indicators suggest it was a significant impact:

- Vehicle Damage:** The collision between the bus and the smaller vehicle is likely to result in substantial damage to both vehicles, given the size difference and the context of the collision.
- Smoke or Dust Cloud:** The presence of a large smoke or dust cloud indicates a high force of impact, which can lead to severe vehicle damage and potential injuries to occupants.
- Potential Injuries:** High-impact collisions like this one can cause a range of injuries to vehicle occupants, from minor bruises and whiplash to more serious conditions like broken bones, internal injuries, or head trauma.

Emergency measures following such an accident typically include:

- Secure the Area....
- Call Emergency Services....
- Assess and Aid Injuries....
- Investigation....
- Medical Attention....
- Clear Debris....
- Support and Follow-Up....

Fig. 4: Run the Red Light at Night Part 2

From the results in Figure 3 and 4, we can observe that GPT-4V can recognize the occurrence of the crash in the figure and is able to describe the crash relatively accurately. Yet the description of the involved accident vehicles is not precise, for example, the blue truck is misrecognized as a bus, while the red semi-trailer truck is misrecognized as a smaller vehicle. In order to investigate the recognition ability of traffic participants in this scenario, we prompt the model to describe the appearance and trajectory of all the recognized traffic participants. The answer shows that GPT-4V has relatively limited ability in spatial

reasoning, and has difficulties in recognizing the class and attributions of small objects, especially for such a nighttime scene. However, despite the imprecise description of the vehicle type and appearance, the model can still include common sense for causal inference and determine that the primary responsibility for this crash is from the vehicle running the red light. While analyzing the severity of the crash, the model infers that it brings significant impact based on indicators such as "substantial damage" and "smoke or dust," which is reasonable. The emergency measures taken for the crash are still relatively general as in section II-A.

C. Motorcycle Car Collision

Collisions between cars and two-wheel vehicles are also common traffic accidents. These collisions can cause varying degrees of injury to both parties depending on their driving speed at the time of the incident, the traffic environment, and whether the two-wheel driver wears a helmet. As shown in figure 5, resourced from the video in dataset [15], a motorcyclist is traveling straight on the road and is hit by a black sedan. Since both of them are traveling at high speeds, the motorcyclist is knocked down, flies into the air, and then falls to the ground. Due to the camera's restricted observation perspective, the images do not fully reveal the situation of the traffic signal and surrounding details, but the accident was in fact caused by the motorcyclist using his cell phone while driving and running a red light.




Fig. 5: Motorcycle Car Collision Part 1

Q: Generate a **detailed description of the accident** based on the given images.

GPT4V: Based on the given images, a detailed description of the traffic accident can be provided as follows:

- **Initial Conditions**:** The intersection is shown with **clear weather conditions and good visibility**. A motorcycle is seen in the middle of the intersection, followed by a blue car. **A yellow bus is seen on the side road, but it does not appear to be involved in the incident.**
- **Approach**:** Both the motorcycle and the car are proceeding through the intersection. **The motorcycle is ahead of the blue car and both vehicles are moving in the same direction.**
- **Collision Initiation**:** As the vehicles continue, the distance between the car and the motorcycle reduces, indicating that the car may be traveling at a higher speed than the motorcycle or did not maintain a safe following distance.
- **Impact**:** The car comes into contact with the rear of the motorcycle. The exact moment of collision is indicated by the sudden change of angle of the motorcycle and signs of instability from the rider.
- **Immediate Aftermath**:** **The rider appears to be thrown from the motorcycle due to the impact.** The motorcycle is knocked over, starting to slide across the road surface, while the rider is not visible in the frame, which may suggest that they have been tossed a distance away from the initial point of contact.
- **Resulting Chaos**:** **Debris is scattered across the intersection as a result of the accident, confirming a violent crash between the two vehicles.** The motorcycle continues to slide and rotate across the road surface, leaving a trail of debris.
- **Final Scene**:** The motorcycle comes to rest on its side, some distance away from the point of impact, indicating the momentum it had after being struck. The cloud of smoke or dust settles slightly

Throughout this event, the rest of the traffic scene remains static, **with no other vehicles involved or any noticeable reactions** from other road users captured in these images....

Q: Specify the number of recognized traffic participants in the provided images. Describe their appearances and trajectories in detail.

GPT4V: In the provided images, there are three traffic participants recognized:

- 1. A motorcycle with a rider:** The motorcycle appears to be a standard design, with the rider sitting upright. In the first image, the motorcycle **is in the middle of the intersection**, moving **from the bottom of the image towards the top**. The **rider is wearing a helmet** and is **the only person on the motorcycle**. The trajectory of the motorcycle is **initially straight**, but as the sequence progresses, the motorcycle gets hit by the car, causing the rider to be **thrown off** and the motorcycle to **tip over and slide across the intersection**.
- 2. A car:** The car is a **dark-colored sedan**. It is following the motorcycle through the intersection, moving in the same direction **from the bottom of the image towards the top**. The car is initially at a distance behind the motorcycle but gets closer with each subsequent image. After the collision, the car **continues to move forward, passing by the fallen motorcycle**.
- 3. A bus:** The bus is a **large, yellow vehicle visible in the top left of the images**. It is stationary throughout the sequence, positioned on the road **perpendicular to the motorcycle and car's path**. The bus does not appear to be involved in the accident and remains in the same location during the entire sequence....

Q: Determine the **severity** of this accident and analyze what **emergency measures** need to be taken.

GPT4V: The severity of this accident, as shown in the images, can be **considered significant** based on the following observations:

1. The collision resulted in the **motorcycle rider being thrown from the bike**, which **suggests a high impact and potential for serious injury**.
2. The motorcycle is significantly damaged, with debris scattered across the road.
3. There is **a visible cloud of smoke or dust**, which **indicates a forceful impact**.

Given this information, emergency measures that should be taken include:

- **Immediate Medical Attention:** Call emergency medical services to **ensure that the motorcycle rider receives prompt medical attention**. The rider may have sustained injuries from being thrown off the motorcycle or from the collision itself.
- **Traffic Control:** **Law enforcement or traffic control personnel should be notified** to manage the flow of traffic around the accident site to prevent further accidents and to create a safe environment for responders and the injured parties.
- **Securing the Scene:** The accident area should be secured to **preserve evidence for an investigation** into the crash
- **Debris Clearance:** Once it is appropriate to do so, and after an investigation, the debris should be cleared from the roadway to restore traffic flow and **prevent any subsequent accidents or damage to other vehicles**....

Fig. 6: Motorcycle Car Collision Part 2

According to the answer in figure 5 and 6, model can recognize the accident type as "car struck the motorcycle" based on the provided keyframes. The generated accident reports also accurately describe the initial scene of the accident, the process of the collision, the aftermath, as well as the final consequences. However, there are still some mistakes when it comes to the ability of spatial reasoning, such as when determining the relative spatial positions between the motorcycle and the car, and when determining their movement directions.

By prompting the model to specify the recognized traffic participant's appearance and trajectory, we discover that although the model can identify the major vehicles, there are still some deviations in the details, such as the motorcyclist actually not wearing a helmet. Regarding the description of vehicle trajectory, GPT-4V interprets it more from the image's perspective, even though it is still not completely accurate for their location descriptions. In the analysis of the severity of the accident, the model recognizes it as "significant" via some scene contexts, such as the rider being thrown from the bike, and the visible cloud of smoke or dust, etc. These indicators have also been taken into account when deciding the required emergency measures.

D. Rollover

Vehicle rollover usually refers to a situation where its gravity center leans to one side and loses its balance during driving. Eventually, the whole side or even the top of the vehicle touches the ground, resulting in a crash that prevents the vehicle from continuing its journey. There are many different causes for vehicle rollover, such as taking a sharp turn, encountering side winds, or driving too fast resulting in an unstable center of gravity.

The images in Figure 7 are selected and extracted in a video from **Providentia++** project [7]. As shown in the images, there is a blue van towing a trailer box highlighted with the red dashed line. This vehicle was moving at high speed when the trailer box attached to it tipped over and landed on the side. Since the blue van was connected to the trailer box, its own trajectory was also affected and thus rolled over and fell to the ground, ultimately causing the accident.




Fig. 7: Rollover Part 1

Q: Generate a **detailed description of the accident** based on the given images.

GPT4V: Based on the sequence of images provided, here is a detailed description of the traffic accident observed:

1. **Location:** The accident has occurred on a multi-lane highway. There is a grassy median separating the opposite directions of traffic. Road signs are visible in the distance, indicating an exit or interchange nearby.
2. **Vehicles Involved:** The primary vehicle involved in the accident is a light-colored, possibly commercial van or a similar type of vehicle. No other vehicles are seen to be directly involved in the accident within the images provided.
3. **Position of the Vehicle:** The vehicle in question has tipped over onto its side and is resting in the median area. Its position suggests that it was traveling in the leftmost lane of the highway before the accident occurred.
4. **Direction of Travel:** The orientation of the vehicle, with its wheels facing the sky and its undercarriage exposed towards the camera, indicates that it was likely traveling in the same direction as the camera's point of view before it flipped.
5. **Damage:** The exact extent of the damage cannot be determined from the images, but the vehicle's position suggests a significant impact.
6. **Traffic Flow:** Traffic continues to flow in both directions, with some vehicles in the lanes closest to the accident slowing down, likely due to drivers reacting to the sight of the overturned vehicle. There is no indication of a traffic jam or significant slowdown, but drivers appear to be exercising caution as they pass by the scene.
7. **Emergency Response:** There are no visible emergency vehicles or personnel in the images. This could mean that the accident has just occurred and responders have not yet arrived, or they may be out of the frame of the images.
8. **Weather and Road Conditions:** The sky is overcast, suggesting cloudy weather conditions, but the road surface appears dry. There are no visible signs of adverse weather conditions that might have contributed to the accident.
9. **Other Observations:** There are no visible signs of debris from the vehicle or skid marks on the road, which might provide additional clues about the cause of the accident....

Q: Determine the **severity** of this accident and analyze what **emergency measures** need to be taken.

GPT4V: The severity of a traffic accident can be assessed based on several factors In this case, we have an overturned vehicle, which suggests a significant impact or loss of control leading to the vehicle rolling over. This type of accident is often considered severe due to the high potential for serious injury to the occupants of the vehicle.

Emergency measures that typically need to be taken in such a situation include:

1. ****Securing the Scene**:** The first priority is to secure the accident scene to prevent further accidents
2. ****Emergency Services**:** Dispatching police, fire services, and emergency medical services (EMS) to the scene is crucial
3. ****Medical Attention**:** Assessing and providing medical care to any injured individuals is a priority. In the case of a rollover, there is a risk of significant injuries, and individuals may need to be carefully extricated from the vehicle to prevent further harm.
4. ****Traffic Management**:** ... This helps to prevent secondary accidents and allows emergency workers to do their jobs safely.
5. ****Investigation**:** ... An investigation into the cause of the accident will be necessary to understand what happened and to prevent similar incidents in the future.
6. ****Clearing the Scene**:** After the injured have been attended to and an initial investigation has been conducted, the vehicle will need to be righted and removed from the scene to restore normal traffic flow. This may require specialized towing and recovery services.

Q: Based on the given images, what could be the **reason** for this accident?.

GPT4V:I can speculate on several common factors that might contribute to such an incident:

1. ****Driver Error:**** 2. ****Speeding:**** 3. ****Vehicle Load:**** 4. ****Road Conditions:**** 5. ****Mechanical Failure:****
6. ****Other Drivers:**** 7. ****Weather Conditions:****

Without additional information, such as eyewitness accounts, vehicle telemetry data, or a more detailed investigation by authorities, it is not possible to pinpoint the exact cause of the accident.

Fig. 8: Rollover Part 2

From the analysis in figure 7 and figure 8, we show that GPT-4V can recognize image-level traffic accidents and correctly determine the accident type. Among the given 6 keyframes, the model can distinguish that the vehicle is tipped over on its side from the third frame onwards. The generated accident report provides an accurate description of the location and surrounding environment, e.g., on a multi-lane highway with an exit or interchange nearby. Based on the recognized environmental cues in the images such as the overcast sky and dry road surface, the model deduces that they're not the main factors contributing to this accident as there are no visible signs of adverse weather conditions. In the summary of traffic flow in the accident description, the model can identify the slowing down of vehicles close to the accident and attribute the reason to the reaction to the overturned vehicle, which

demonstrates the powerful reasoning and causal inference abilities of GPT-4V. By combining a series of contextual information including environment, weather, vehicles involved, traffic conditions, etc., the model characterizes the level of the accident as severe. It provides emergency measures to be taken including dispatching police, fire service, and emergency medical services. Most of these measures do appear in the subsequent rescue after the accident, which can prove that the model has the ability to make similar decisions when reacting to emergent traffic situations as a human being.

However, GPT-4V again fails to make accurate statements when it comes to spatial reasoning. For example, the accident was not in the median area between the opposing lane of traffic, but on the side of the highway. And the vehicle was not traveling in the same direction as the camera’s point of view, but on the opposite side of the camera before it flipped over. The vehicle was also not light-colored but a dark-colored van with a trailer box. From these descriptions, we can tell that the model, while being able to recognize the rollover of the vehicle and reasoning in the context of the recognized environmental information, did not succeed in recognizing the type and driving condition of the vehicle itself. This leads to the inability to make correct and specific determinations when carrying out a cause analysis.

E. Fires and Explosion

Vehicle explosions are a relatively uncommon but extremely dangerous type of traffic accident. It is usually caused by some issues such as severe collisions, fuel leaks, or overheating of electric vehicle batteries. These accidents are usually accompanied by loud noises and flames, resulting in significant injuries and property damage. The video shown in figure 9 and 10 is resourced from [12]. The captured keyframe shows a red truck traveling on the highway, which overturned due to a lane change while in motion at high speed. And due to its fast traveling velocity, the cargo it carries rubs violently against the road surface, resulting in an explosion accompanied by bright flames. Since it is difficult to distinguish between an explosion as well as a sole fire without providing acoustic information, we regard this as a successful case as the model is able to recognize the flame from the vehicle as a notable traffic event.




Fig. 9: Fires and Explosion Part 1

Q: Based on the images extracted from the video, is there a red vehicle overturned and down on the ground?
GPT4V: Based on the images provided, there is no clear evidence of a red vehicle being overturned or down on the ground. The sequence of images shows a red vehicle experiencing a fire, as indicated by flames and smoke coming from the rear of the vehicle.... The visible flames and smoke in the fifth and sixth images appear while the vehicle is upright on its wheels and no image shows the vehicle in an overturned position.
Q: What can be the direct cause of the accident?
GPT4V: Based on the images provided, the direct cause of the vehicle fire cannot be definitively determined. Vehicle fires can result from numerous potential causes, such as mechanical issues, electrical faults, collisions, fuel system leaks, overheating, arson, or other factors....
Q: Determine the severity of this traffic incident and analyze what emergency measures need to be taken.
GPT4V: The traffic incident depicted appears to be severe, as it involves a vehicle that has caught fire while on the highway. A vehicle fire can be dangerous and potentially life-threatening, with risks including the fire spreading, explosions, as well as smoke inhalation and burns to the occupants of the vehicle or to other road users. In addition, the fire could lead to secondary incidents if other drivers are distracted or if they need to take evasive action to avoid the burning vehicle. Emergency measures that need to be taken include: 1. **Alerting emergency services**: It is crucial to notify the fire department and emergency medical services immediately.... 2. **Evacuating the vehicle**: If safe to do so, the occupants of the burning vehicle should exit the vehicle quickly and move to a safe location away from the traffic and the burning car. 3. **Securing the area**: The area around the burning vehicle should be secured.... 4. **Traffic management**: Law enforcement or highway patrol should be informed to manage traffic flow.... 5. **Use of fire extinguishers**: If there are people with fire extinguishers nearby who are trained to use them and can do so safely, they may attempt to extinguish the fire before the fire department arrives.... 6. **Providing first aid**: ... Offer medical assistance to the vehicle's occupants or any injured persons until emergency medical services arrive. 7. **Documenting the incident**: Witnesses may take notes or photos/videos at a safe distance....

Fig. 10: Fires and Explosion Part 2

As shown in Figures 9 and 10, GPT-4V is able to identify the abnormalities in the fifth and sixth images through image-level analysis, i.e., there is a visible flame which later on becomes larger. According to the first question prompted in figure 10, it is obvious that the model has not been able to successfully recognize the driving lane changes of the vehicles displayed in the 2nd, 3rd, and 4th images, which result in the inability to provide the corresponding attribution analysis and causal link. Therefore, in the analysis of the causes of the accident, some correct but more general answers are presented. In terms of the emergency measures taken for this accident, the model proposes to try putting out the fire safely with fire extinguishers if possible before the fire department arrives. It shows that the model is able to provide rational decisions according to the types of accidents.

III. FAILURE CASES

In this section, we demonstrate some failure cases when exploring GPT-4V to recognize traffic events. As for some cases, we try out prompting methods by providing additional visual or text cues, and show the results for comparison. We summarize and analyze the potential failing reason for each case.

A. Vehicle Collision

Figure 11 shows a vehicle collision accident, resourced from **Providentia++** Project. The images depict a yellow car traveling on a multi-lane highway when a white van in front of it suddenly stops on the highway lane. In order to avoid the vehicle in front of it that slows down, the yellow car makes a sharp turn, which yet still hits the guardrail in the middle of the highway due to its excessive speed, and later hits the stopped white van. Although there are similar accident scenarios with two vehicles colliding in this video as in section II-B, the number of vehicles present in this video is far larger and the causes are more complex, with multiple vehicles interconnected with each other. And due to the limitation of view angle, the obvious collision between the yellow car and the white van cannot be directly observed either, which can probably only be confirmed through comprehending context information.




Fig. 11: Vehicle Collision Part 1

As shown in figure 11 GPT-4V fails to recognize either the accident or notable traffic events within the provided keyframes. Although it is obvious for human beings to identify the abnormality in the images, the model still describes it as having "no evidence of an accident or unusual event". Based on the previous evidence that, the model can recognize vehicle collisions, as well as recognize the debris, we hypothesize the failure of recognition happens due to the excessive number of vehicles displayed in the picture. The excessive number of vehicles leads to the inability of the model to focus attention on the behavioral recognition of all the vehicles, which results in the missing of the obvious accidental vehicles. Based

on this assumption, we manually highlight the accident vehicles in the images and conduct the analysis again.








Q: The images are extracted from a video and sent in a chronological order. Please determine if there are **any traffic accidents or notable traffic events** happen in the video. If yes, please give detailed descriptions, if no, give the reason.

GPT4V: Based on the sequence of images provided, it appears that **a traffic event involving a single vehicle** occurs. Here is a chronological description of the event:

1. In the first image, traffic seems to be flowing normally. **A yellow vehicle is highlighted within a red box**, which suggests that it may be the focus of the subsequent events.
2. In the second image, the **yellow vehicle appears to have moved slightly to the right**, closer to the edge of the roadway, but there is no clear indication of an accident yet.
3. The third image shows **the yellow vehicle at a sharper angle to the road**, indicating that it has **made a significant movement to the right and is now facing the guardrail**, suggesting a loss of control or an evasive maneuver.
4. In the fourth image, the yellow vehicle is now **perpendicular to the road** and has **come into contact with the guardrail**. This confirms that the **vehicle has been involved in a traffic incident**.
5. The fifth image shows the yellow vehicle after the collision, with its **rear end facing the road and the front end against the guardrail**. It appears to have spun around after the impact.
6. The final image shows **the aftermath of the incident**, with the **yellow vehicle no longer visible**, likely because it has come to a stop off the road or behind the guardrail....

From this sequence, it can be concluded that the **yellow vehicle experienced a single-vehicle accident**, likely **due to a loss of control, resulting in a collision with the guardrail**. There are **no indications of other vehicles being involved in this incident**.

Fig. 12: Vehicle Collision (Highlighted) Part 1

Q: Generate a **detailed description of the accident** based on the given images.

GPT4V: Based on the sequence of images provided, here is a detailed description of the traffic accident involving the yellow vehicle:

1. ****Initial Position**:** The yellow vehicle **is initially spotted traveling in the rightmost lane** of a multi-lane highway. The traffic around the vehicle appears to be flowing smoothly, with no immediate signs of distress or erratic driving.
2. ****Deviation from Lane**:** As the sequence progresses, **the yellow vehicle begins to deviate from its lane, veering towards the right side of the highway**. This suggests that the driver may have lost control, been distracted, or attempted to avoid an obstacle.
3. ****Approaching the Guardrail**:** The vehicle's angle becomes more acute in relation to the road, **indicating a sharper turn or loss of control as it approaches the guardrail....**
4. ****Collision with Guardrail**:** The vehicle **makes contact with the guardrail**, and the impact is evident as the vehicle's orientation changes drastically....
5. ****Post-Impact Position**:** ...The vehicle has likely spun around due to the impact, coming to rest in a position that suggests **a complete 180-degree turn** from its original direction of travel.
6. ****Aftermath**:** In the final image, the yellow vehicle is no longer in the frame, which could mean **it has come to a stop out of the camera's view**, possibly behind the guardrail or on the shoulder of the highway....

From this analysis, it can be concluded that the yellow vehicle experienced a **single-vehicle accident resulting from a loss of control that led to a collision with the highway guardrail....**

Q: Does the yellow vehicle **hit any other** traffic participants?

GPT4V: Based on the images provided, **there is no evidence that the yellow vehicle hits any other traffic participants**. ... Throughout the sequence, the other vehicles on the road maintain their lanes and **there is no interaction seen between the yellow vehicle and any other vehicle....**

Q: Please make a reasonable inference that who should be **primary responsible** for this traffic accident.

GPT4V: Based on the sequence of images alone, we can make some general observations:

- The yellow vehicle appears to be **the only one directly involved in the incident**.
- The vehicle's trajectory suggests it **veered to the right and collided with the guardrail** without any visible interaction with other vehicles.
- There are **no clear indications of external factors**, such as another vehicle forcing the yellow car off the road.

Given these observations, it is possible that the driver of the **yellow vehicle may have lost control due to a variety of reasons such as distraction, a medical issue, mechanical failure, or adverse road conditions** (e.g., ice or debris). However, without additional context or evidence, it is not possible to definitively determine the cause of the incident or assign responsibility....

Q: Determine the **severity** of this accident and analyze what **emergency measures** need to be taken.

GPT4V: The severity of a traffic accident can be assessed based on several factors:

1. **Vehicle Damage:** The exact extent of the damage cannot be determined from the images, but the vehicle's orientation and contact with the guardrail suggest **at least moderate damage to the front end of the vehicle**.
2. **Occupant Safety:** There is no direct evidence in the images of the condition of the vehicle's occupants. However, given that the vehicle has collided with the guardrail, there is **a possibility of injury...**
3. **Traffic Flow:** The presence of the accident could **pose a risk to passing traffic** and may require traffic control measures to ensure safety.

Emergency Measures: 1. ****Emergency Services**:** 2. ****Securing the Scene**:**

3. ****Vehicle Recovery**:** Once the occupants have been cared for and the scene is safe, **a tow truck or recovery vehicle would be needed** to remove the damaged vehicle from the guardrail and clear the area.
4. ****Investigation**:** 5. ****Traffic Management**:**

It is important to note that the actual severity of the accident and the required emergency measures can only be accurately determined by on-site emergency responders who can assess the situation in person.

Fig. 13: Vehicle Collision (Highlighted) Part 2

Figure 12 reveals the results as expected, GPT-4V can successfully recognize the accident after prompting highlighted visual cues on the involved yellow car in the images. It can also describe the accident process relatively accurately this time. We observe that the model can recognize the driving state's change of the highlighted yellow car in the accident report, including deviation from the current lane, approaching and hitting the guardrail, and driving out of the observable area of the camera. In addition, the model

is able to identify the front end of the vehicle as having at least moderate damage when it comes to the severity evaluation of the accident based on the cue that the front end hit the guardrail. These are additional performance enhancements obtained through visual cue prompting, which illustrate that the model can be adapted to such tasks with properly designed prompting techniques.

However, the model still fails to completely analyze the cause of the accident and fails to identify the collision with the stopped white van. In addition to the previously discussed failing reasons including restricted camera view, lack of spatial reasoning, and lack of temporal and acoustic information, another possible reason might be that, the model assigns less attention to the remaining vehicles after highlighting the target vehicle. This then leads to the failure to capture the causal link between the stopped white vehicle and the result of the accident.

B. Jaywalking

Jaywalking is a typical and common example of traffic rule violation, usually referring to the act of pedestrians crossing roads where there are no crosswalks or traffic signals. This behavior poses a traffic safety hazard, especially when jaywalking across roads with high traffic volumes and high speeds, as pedestrians are vulnerable traffic participants and can easily lead to traffic accidents. The video in figure 14, resourced from dataset [15] displays a scene with two pedestrians jaywalking across a multi-lane street. To protect the privacy of the pedestrian, their faces are been anonymized.




Fig. 14: Jaywalking Part 1

Q: Based on the given images from a video, how many pedestrians cross the street?
GPT4V: Based on the given images from the video, there is one pedestrian crossing the street. This individual is first seen in the second image crossing the road and then reaching the median strip in the third image.
Q: Generate a detailed description of the pedestrian crossing the street.
GPT4V: In the images provided, the pedestrian crossing the street appears to be an adult wearing dark-colored clothing. The pedestrian is initially seen in the second image, where they are in the process of crossing the street, moving from the right side of the road towards the median strip. They are carrying a wheeled bag, which is commonly used for travel or transporting heavy items. As the pedestrian reaches the median strip in the third image, they seem to have safely navigated across the first half of the street, avoiding the oncoming traffic. However, the wheeled bag is left behind in the lane closest to the median strip, creating a potential traffic hazard. The pedestrian does not appear to be in any immediate danger themselves, as they have reached a safe position on the median strip. Overall, the pedestrian's actions inadvertently created a traffic hazard by leaving the bag in the road, but there is no indication of a traffic accident involving the pedestrian themselves.
Q: Do the pedestrian cross the street according to traffic rules?
GPT4V: In the second image, the pedestrian is seen crossing the street while vehicles are in motion, which suggests that they may not be crossing in accordance with traffic rules. Typically, pedestrians are expected to cross at designated crosswalks and only when traffic signals permit (if signals are present) or when it is safe to do so (if signals are not present). Since the pedestrian is crossing while cars are actively moving through the lane, it appears they are not following standard traffic rules for pedestrian crossing. This action could be considered jaywalking, which is crossing the street outside of a crosswalk or against the pedestrian traffic signal, and is generally against traffic regulations.

Fig. 15: Jaywalking Part 2

The evaluation result in figure 14 and figure 15 shows that GPT-4V fails to recognize two pedestrians crossing the road, but only recognized one of them and viewed the other pedestrian as a wheeled bag. And due to the illusory effect of the Large Language Model, the whole story was refined into a scenario in which a pedestrian lost his wheeled bag on the road while crossing the road and avoided a traffic accident due to the timely stopping of the driver. Nevertheless, GPT-4V can still reason that this traffic violation behavior is jaywalking based on the traffic environment in the images and based on the context that one recognized pedestrian crossing the road there.

C. Vehicle Smoke

Vehicle smoke is usually a serious sign of damage to the vehicle, which indicates that the vehicle is defective. For safety reasons, people should immediately move the vehicle to a safe place if it begins to smoke so that the situation does not escalate further, such as to a fire or even a vehicle explosion. The images in figure 16 and figure 17 are from the video recorded by **Porivdentia++** Project. On the upper right side of the image is a white vehicle parked in the emergency lane with visible white smoke streaming from it. The rest of the vehicles were traveling normally on the road and were not affected.






Q: The images are extracted from a video and sent in a chronological order. Please determine if there are **any traffic accidents or notable traffic events** happen in the video. If yes, please give detailed descriptions, if no, give the reason.

GPT4V: Based on the images provided, there **does not appear to be any traffic accidents or notable traffic events** occurring. The vehicles seem to be moving smoothly in their respective lanes, and there are no visible signs of distress or collision. The traffic flow is consistent across all images, and there are **no obstructions or unusual activities** on the road that would indicate an accident or a traffic event.

Q: Are there any vehicles with **smoke and or signs of fire**?

GPT4V: In the images provided, there are **no visible signs of smoke, fire, or any other indications that a vehicle is experiencing such issues**. All vehicles appear to be functioning normally without any distress signals like smoke or fire.

Fig. 16: Vehicle Smoke Part 1




Fig. 17: Vehicle Smoke (Highlighted) Part 1

Figure 16 demonstrates that GPT-4V cannot recognize the abnormality of the image, nor can it recognize the car that is emitting white smoke, which means that the model fails to capture the corresponding visual semantic features despite the explicit prompts of "whether there's smoke or a sign of fire in the images". In figure 17, we apply the same highlight operations to the images as we do in figure 12, and we input the same question with even more explicit prompts. However, the model still could not identify any signs of smoke and fire. One possible reason could be that the distance of the white vehicle is too far from the camera, and the image resolution is not clear enough so that the visual features can not be well extracted and utilized. Another possible explanation is that GPT-4V still does not achieve a well-performed semantic alignment of vehicle smoking visual features and text features, especially for this distant, dense and noisy scenario.

D. Multiple Vehicle Collision

Multi-vehicle collisions or chain vehicle collisions, commonly happen in areas with dense traffic where extreme weather, driver distraction, or too little distance between vehicles leads to a succession of vehicle collisions in a short period of time. Due to the multiple number of involved vehicles, the causes of these accidents are usually very complicated, and the assignment of responsibility can be difficult.

The images in figure 18, resourced from [4], shows a case of four vehicle collisions. It demonstrates a scene of a traffic jam on a multi-lane road where a small black SUV, highlighted with the dotted line,

slows down after approaching the vehicle in front of it. As can be observed in images 2, 3, and 4, the black SUV was followed closely by a white car. Due to its excessive velocity and the insufficient distance, the white car was unable to stop within a safe braking distance, and thus crashed into the black SUV in front of it. Image 4 and 5 show the collision of these two vehicles. In image 5, a new white car appears behind the white sedan, which also fails to brake in time for the same reason, and crashes head-on into the vehicle in front of it. The collision between these two white cars can be observed in image 6. As a result of these two consecutive collisions, the position of the black SUV was shifted forward and also then rear-ended the vehicle in front of it. This leads to the eventual collision of the four vehicles shown in image 6. In summary, this accident involved 4 vehicles, associated with 3 consecutive collisions.




Fig. 18: Multiple Vehicle Collision Part 1

Q: Specify the **number of recognized traffic participants** in the provided images. Describe their **appearances and trajectories** in detail.

GPT4V: In the sequence of images provided, there are several traffic participants visible....

1. **White Sedan (Car 1):** This vehicle is initially in the leftmost lane in the first image. It **begins to change lanes to the right** in the second image and continues this maneuver in the third image. By the fourth image, the white sedan has moved into the center lane. In the fifth image, it appears to be moving back towards the left lane, and in the sixth image, it collides with the black SUV.
2. **Black SUV (Car 2):** This vehicle is **first seen in the leftmost lane in the fourth image**, traveling behind the white sedan. As the white sedan **moves back towards the left lane in the fifth image**, the black SUV gets closer to it. **In the sixth image, the black SUV is hit by the white sedan and is pushed towards the left, ending up facing oncoming traffic in the leftmost lane.**
3. **White Box Truck (Vehicle 3):** This truck is **seen in the rightmost lane in the second image and continues on a straight trajectory** throughout the sequence, passing by the incident **without any apparent change in course or speed.**
4. **Red Truck (Vehicle 4):** In the **first image, a red truck is visible in the rightmost lane**, ahead of the white box truck. It maintains its lane and trajectory, moving ahead along the highway.
5. **White Compact Car (Car 3):** This car is **seen in the second lane from the right in the first image** and continues to travel straight ahead in its lane throughout the sequence.
6. **Dark-colored Compact Car (Car 4):** This car is **visible in the second lane from the right in the first image**, behind the white compact car. It maintains its lane and trajectory, following the white compact car.

In summary, there are **six** traffic participants identified in the images...

Q: How many vehicles are involved in this traffic accident?

GPT4V: Based on the sequence of images provided, it appears that **two vehicles are directly involved in the traffic accident:**

1. **White Car:** This vehicle is **initially seen in the leftmost lane**. It begins to **change lanes to the right**, then after some time, it attempts to **move back to the left lane**. During this second lane change, it comes into close contact with the black car, which is traveling in the left lane. The **white car's driving behavior suggests an indecisive or erratic lane-changing pattern**, which leads to the collision with the black car.
2. **Black Car:** The black car is **traveling in the leftmost lane** and appears to be **maintaining its lane and speed**. As the white car re-enters the left lane, the black car is impacted on its right side, which forces it to veer sharply to the left, resulting in it facing oncoming traffic after the collision.

No other vehicles are shown to be directly involved in the collision, although **the presence of other vehicles**, such as **the white box truck and a red vehicle in the rightmost lane**, indicates that the accident occurred in a moderately busy traffic environment. **These other vehicles are not implicated in the accident** based on the images provided.

Fig. 19: Multiple Vehicle Collision Part 2

As illustrated in figure 18 and figure 19, GPT-4V can detect the collision between the black SUV and white sedans in image 4. However, the whole description of the accident is completely biased from the facts. For example, the model suggests that the black SUV in image 2 was veering and then collided with the white sedan in the center lane after switching lanes to the right in the 5th and 6th images, which is completely inconsistent with what is shown in the images. To better understand how precisely the model recognizes the traffic participants appearing in the extracted images, we prompted the model to specify the number of identified vehicles, including their appearances and trajectories. We can tell from the answers that the model can identify a total of 6 vehicles, yet 3 of them, the red truck (Vehicle 4), the white compact car (Car 3), and the dark-colored compact car (Car 4), are false positive samples and do not appear in the images provided. For the four vehicles involved in this accident, the model can recognize two of them, but the description of their trajectories is completely different from the fact.

Based on these observations, we can deduce that the possible reasons for this failure can be as follows. First, in order to make the generated textual description of the traffic event logically self-consistent, the model somewhat neglects the semantic associations with visual features, thus creating an illusory effect. Secondly, the image-level vehicle recognition is not accurate enough, and there are many false positive and false negative detections. For the third, model fails to associate the corresponding vehicles across images when performing multi-object tracking, which may be because the appearances between the vehicles are similar, e.g. the colors, and performing multiple vehicle associations solely utilizing visual features while ignoring spatial features can be difficult. Lastly, the image-level vehicle collision detection is still not accurate enough, since it is clear that there are multiple vehicles involved in the collision in image 6, which are not mentioned in the answers.

IV. DISCUSSION

In this section, we analyze and discuss in depth the reasons for the successes and failures demonstrated by the aforementioned traffic incidents. In particular, we focused on comparing how well the model performs on different types of questions in these cases, and discussing its capabilities and limitations. Table I displays the results of all the cases evaluated in this paper across several major capabilities of interest, including accident or event recognition, event type identification, severity analysis, emergent decision-making, involved number of participants, cause reasoning, and responsibility reasoning.

Main Capabilities of GPT-4V on complex traffic events can be summarized qualitatively as follows. First based on the table, we observe that in almost 2/3 of all the cases, the presence of accidents or notable traffic events can be successfully recognized and identified without any specific prompting strategies or fine-tuning methods. This demonstrates the powerful zero-shot abilities of GPT-4V, and the feasibility of further adaptation to traffic event recognition and understanding. In addition, we discover that as long as GPT-4V can successfully identify the type of accident, it will also be able to draw reasonable emergency measures, and make severity analysis combining the characteristics of the accident and the relevant context information extracted from the images. It shows that GPT-4V can apply the powerful multi-modal reasoning ability in decision-making and severity assessment in this emergent traffic situation. Thirdly, we are surprised to find that GPT-4V can comprehend dooring and red-light running cases in a zero-shot manner, and make a reasonable analysis of the causes and responsibility of these accidents. Cause reasoning and responsibility reasoning take the successful identification of the accident type as the prerequisite, and require the accurate recognition of the details, as well as cross-modal high-level reasoning capabilities. This suggests that GPT-4V has been able to acquire the cross-modal semantic associations of these cases, showing technical possibilities for other more complex traffic events.

Traffic Event	Accident / Event Recognition	Event Type Identification	Severity Analysis	Emergent Decision Making	Involved Num. Participants	Cause Attribution	Responsibility Reasoning
Dooring II-A	✓	✓	✓	✓	✓	✓	✓
Run the Red Light at Night II-B	✓	✓	✓	✓	✓	✓	✓
Motorcycle Car Collision II-C	✓	✓	✓	✓	✓	-	-
Rollover II-D	✓	✓	✓	✓	✓	✗	-
Fires and Explosion II-E	✓	✓	✓	✓	✗	✗	-
Vehicle Collision III-A	✗	-	-	-	-	-	-
Vehicle Collision (Highlighted) III-A	✓	✓	✓	✓	✗	✗	✗
Jaywalking III-B	✗	✓	-	-	✗	-	-
Vehicle Smoke III-C	✗	✗	-	-	-	-	-
Vehicle Smoke (Highlighted) III-C	✗	✗	-	-	-	-	-
Multiple Vehicle Collision III-D	✓	✗	-	-	-	-	-

TABLE I: Evaluation Summary of all Traffic Events.

We summarize and analyze the failed cases and answers, and divide the failure reasons into two main types, i.e. performance limitations and inherent restrictions. Performance limitations can be alleviated with either the scaling up of the dataset or the improvement of training and deployment techniques. Whereas, the inherent restrictions cannot be resolved with the current GPT-4V model, and require the support of extra modalities.

Performance Limitation consists of the following aspects. Firstly, the spatial reasoning ability of GPT-4V is weak. As mentioned in II-B, II-D, II-C, the poor spatial reasoning leads to mistakes when it comes to describing the location of the vehicle, the vehicle’s orientation, and the relative positions to other traffic participants. This greatly affects the accuracy of the generated accident reports that involve spatial descriptions. Secondly, GPT-4V is still not accurate enough in recognizing the details of objects of interest, including the color of the vehicles, whether the vehicle tows a trailer, and whether the motorcyclist wears a helmet. These details play an important role in the reasoning of the accident causes, in generating

precise descriptions of vehicles involved in the traffic events, and in the analysis of accident severity. Thirdly, GPT-4V suffers from poor cross-image associations of multiple objects, especially when there is dense traffic in the images, or when cars with similar appearance come close to each other. This leads to the failure to provide a precise description of the trajectories and behaviors of target vehicles.

Inherent Restrictions refers that only utilizing the input modalities supported by GPT-4V, i.e. texts and images, can not provide the minimum required information for successful recognition and reasoning. For example, it is difficult to identify the explosion without acoustic information, and it is also challenging to recognize a direct collision between vehicles only through images, especially when the vehicle's direction is parallel to the camera's viewpoint. All of this points to the fact that the model could tackle these problems only with the support of additional modalities and additional information, including acoustic, videos, and 3D spatial information.

REFERENCES

- [1] Guangyi Chen et al. *Tem-adapter: Adapting Image-Text Pretraining for Video Question Answer*. 2023. arXiv: 2308.08414 [cs.CV].
- [2] Christian Creß et al. *A9-Dataset: Multi-Sensor Infrastructure-Based Dataset for Mobility Research*. 2022. arXiv: 2204.06527 [cs.CV].
- [3] Haotian Liu et al. *Visual Instruction Tuning*. 2023. arXiv: 2304.08485 [cs.CV].
- [4] *Missed the intersection and caused a rear-end collision*. https://www.bilibili.com/video/BV12U4y157gs/?spm_id_from=333.337.search-card.all.click&vd_source=25b99882205bf99d791a8ceaea5664b9. June 2021.
- [5] OpenAI. *GPT-4 Technical Report*. 2023. URL: <https://cdn.openai.com/papers/gpt-4.pdf>.
- [6] OpenAI. *GPT-4V(ision) System Card*. 2023. URL: https://cdn.openai.com/papers/GPTV_System_Card.pdf?ref=getdgtl.com.
- [7] *Providentia++ Project*. <https://innovation-mobility.com/en/project-providentia/>.
- [8] Gemini Team et al. *Gemini: A Family of Highly Capable Multimodal Models*. 2023. arXiv: 2312.11805 [cs.CL].
- [9] Hugo Touvron et al. *Llama 2: Open Foundation and Fine-Tuned Chat Models*. 2023. arXiv: 2307.09288 [cs.CL].
- [10] Hugo Touvron et al. *LLaMA: Open and Efficient Foundation Language Models*. 2023. arXiv: 2302.13971 [cs.CL].
- [11] *Traffic accidents (warning function)*. https://www.bilibili.com/video/BV1EM411Y7ZE/?spm_id_from=333.337.search-card.all.click&vd_source=25b99882205bf99d791a8ceaea5664b9. Feb. 2023.
- [12] *Vehicle Suddenly Explodes on Highway (Surveillance View)*. https://www.bilibili.com/video/BV1Rg411o7p8/?spm_id_from=333.337.search-card.all.click&vd_source=25b99882205bf99d791a8ceaea5664b9. July 2022.
- [13] Licheng Wen et al. *On the Road with GPT-4V(ision): Early Explorations of Visual-Language Model on Autonomous Driving*. 2023. arXiv: 2311.05332 [cs.CV].
- [14] Li Xu, He Huang, and Jun Liu. *SUTD-TrafficQA: A Question Answering Benchmark and an Efficient Network for Video Reasoning over Traffic Events*. 2021. arXiv: 2103.15538 [cs.CV].
- [15] Yajun Xu et al. *TAD: A Large-Scale Benchmark for Traffic Accidents Detection from Video Surveillance*. 2022. arXiv: 2209.12386 [cs.CV].
- [16] Zhengyuan Yang et al. *The Dawn of LMMs: Preliminary Explorations with GPT-4V(ision)*. 2023. arXiv: 2309.17421 [cs.CV].
- [17] Xingcheng Zhou et al. *Vision Language Models in Autonomous Driving and Intelligent Transportation Systems*. 2023. arXiv: 2310.14414 [cs.CV].
- [18] Deyao Zhu et al. *MiniGPT-4: Enhancing Vision-Language Understanding with Advanced Large Language Models*. 2023. arXiv: 2304.10592 [cs.CV].